| Form 9-331 (May 1963) | DEPART | UNITED S=ATES MENT OF HE II GEOLOGICAL SURV | NTERIOR | SUBMIT IN TRIFFICATE (Other instructions on reverse side) | LC LC | - 030174 | u No. 42-R1424. | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|--------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|------------------------------------------------|-----------------|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) | | | | | | GREEMENT NA | | |
| 1. OIL GAS WELL WELL 2. NAME OF OPERATOR | OTHER | Water Injection | Well | <u> </u> | | OR LEASE NAM | | |
| TEXACO | | | | 1407 1011 | O WELL | | Fed. NCT- | |
| P. O. Box 728, Hobbs, New Mexico 88240. S. CEOLOGICAL SURVES 4. Location of Well (Report location clearly and in accordance with any State requirements.) At surface At surface | | | | | 10. FIELD | 19 10. FIELD AND FOOL, OR WILDCAT Rhodes Yates | | |
| At Surface | | FNL & 1980' FEL , R-37-E, Unit xico | | | 11. sec., sue | T., R., M., OR B. EVEY OR AREA 26, T-26- | -S, R-37-E | |
| 14. PERMIT NO. Regular | | 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 2995 (GR) | | | Lea | TY OR PARISH | New Mexico | |
| 16. | Check A | | licate Natur | e of Notice, Report, or | Other Date | | | |
| TEST WATER SHUTTER TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) | | PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS | | WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report result Completion or Recommils, and give pertinent date and greatered and true verifies.) | s of multiple pletion Repor | e completion of tand Log for | on Well | |

starting any d zones pertinent to this work.) *

Spud 12 1/4" Hole 3:00 A.M., 6-17-77 Total Depth ..669

- Ran 659' 8 5/8" OD 24# K-55 Csg. and set @ 669'
- Cemented w/600 Sx Class C Cement. Cement circulated. Job complete 12:15 A.M., 6-18-77.
- Tested cement, w/800# for 30 minutes, from 6:15 6:45 P.M., 6-18-77. Tested ok. Job Complete 6:45 P.M., 6-18-77.

| 7 | | |
|----------------------------------------------------------|----------------------------------------------|---------------------|
| 18. I hereby certify that the foregoing is true and corr | TITLE Asst, Dist. Supt. | DATE 6-20-77 |
| (This space for Federal or State office use) | TITLE | ACCEPTED FOR RECORD |
| CONDITIONS OF APPROVAL, IF ANY: | | JUN 21 1977 |
| | U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO | |

Control of the second s