

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company OXY USA Inc.	Contact Eric Maestas
Address 770 Rosebud Rd. Amistad NM 88410	Telephone No. 575-420-7825
Facility Name Bravo Dome Gathering System	Facility Type Carbon Dioxide Gathering System

Surface Owner Libby	Mineral Owner Libby	API No. Pipe Line Vent
---------------------	---------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	20 ^N	32 ^E	1700	South	1700	West	Harding

D 36 Latitude N 35.92518833 Longitude W -103.603355

NATURE OF RELEASE

Type of Release Carbon Dioxide Gas	Volume of Release 910MCF	Volume Recovered None
Source of Release Pipeline Vent	Date and Hour of Occurrence 2/10/2016 8:00 AM	Date and Hour of Discovery 2/10/2016 8:10AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? William Jones and Leonard Lowe	
By Whom? Eric Maestas	Date and Hour 2/10/2016 9:10 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Internal Corrosion on 24" Steel Pipeline developing pinhole leak. Pipeline was depressurized and repaired.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Eric Maestas	Approval Date: 02/18/16	Expiration Date: 02/18/16
Title: HES Coordinator	Conditions of Approval:	
E-mail Address: Eric-Maestas@oxy.com	Attached <input type="checkbox"/>	
Date: 2/10/2016 Phone: 575-420-7825		

* Attach Additional Sheets If Necessary

4RP-9

Facility: OXY- 910 MCF Release