

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report


Name of Company OXY USA Inc.	Contact Eric Maestas	
Address 770 Rosebud Rd. Amistad NM 88410	Telephone No. 575-420-7825	
Facility Name Bravo Dome Gathering System	Facility Type Carbon Dioxide Gathering System	
Surface Owner State	Mineral Owner State	API No. Pipeline Vent

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>N</u>	5	19	32	258	North	390	East	Harding

0 Latitude N 35.90199 Longitude W -103.561722

NATURE OF RELEASE

Type of Release Carbon Dioxide Gas	Volume of Release 635MCF	Volume Recovered None
Source of Release Pipeline Vent	Date and Hour of Occurrence 2/17/2016 7:00 AM	Date and Hour of Discovery 2/17/2016 7:00AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? William Jones and Leonard Lowe	
By Whom? Eric Maestas	Date and Hour 2/17/2016 7:36 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Internal Corrosion on 24" Steel Pipeline developing pinhole leak. Pipeline was depressurized and repaired.		
Describe Area Affected and Cleanup Action Taken.*		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Eric Maestas	Approved by Environmental Specialist: 	
Title: HES Coordinator	Approval Date: 2/18/16	Expiration Date: 2/18/16
E-mail Address: Eric-Maestas@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/17/2016	Phone: 575-420-7825	

* Attach Additional Sheets If Necessary

4RP-10

FACILITY: OXY-635 MCF Release