

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pGRL1011656482

1RP - 2488
SOUTHERN UNION GAS COMPANY

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

			Rele	ease Notific	cation	and Co	rrective A	ction	l			N 10		
		OPERATOR				al Report	\boxtimes	Final Report						
Name of Co		Contact Rose Slade												
							Telephone No. 432.940.5147 Facility Type 6" Lateral							
Surface Ow	ner Gerald	Doom		Mineral C	API No. 30-025-38822.00.00									
						OF REI								
Unit Letter	Section	Township	Range	Feet from the	North/	South Line Feet from the East/			West Line County					
L	26	24S	37E							Lea				
	Latitude_32 11.384Longitude_103 08.154													
NATURE OF RELEASE														
Type of Release Crude Oil/Produced Water Source of Release 6 inch pipeline						Volume of		Volume Recovered none						
Was Immediate Notice Given?						Date and Hour of Occurrence 4/19/2010 at 11:30 pm (not			Date and Hour of Discovery 4/20/2010 at 7:45 am					
						reportable at the time)								
was Immedi	ate Notice (Yes [No Not R	If YES, To Whom? Geoffrey Leking									
By Whom? Rose Slade						Date and Hour 4/20/2010 at 8:58 am								
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.								
☐ Yes ☐ No						HOBBS OCD								
If a Watercourse was Impacted, Describe Fully.* DEC 1 2 7012														
Describe Car	Describe Cause of Problem and Remedial Action Taken.*													
The line developed a split on the 6 inch steel line. Line was replaced with approximately 100 feet of poly pipe. EHS was notified and I immediately dispatched an environmental company to the site to conduct remediation activities.														
Describe Area Affected and Cleanup Action Taken.* An area measuring approximately 3' x 25' was impacted by the leak. The site was excavated, soil samples were collected from the excavation and submitted to the laboratory for benzene, BTEX, TPH and chloride analysis. Laboratory results indicated benzene, BTEX, TPH, and chloride concentrations were less than the NMOCD Regulatory Guidelines. Approximately 468 cubic yards of impacted soil was transported to Doom Land Farm, LLC for disposal. The excavation was backfilled with locally obtained non-impacted soil. Please reference the NOVA Safety and Environmental Soil Remediation Summary and Site Closure Request dated November 2012 for further details. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or-local laws and/or regulations.														
Signature: Printed Name: Rose Slade							OIL CONSERVATION DIVISION Survivor Service Se							
Title: EH&S Specialist						Approval Dat	Approval Date: 12/12/12 Expiration Date: -							
							Conditions of Approval: Attached							
Date: 12/13/12 Phone: 432.940.5147											1RP-10.4.2488			
* Attach Add	itional She	ets If Neces	sarv											