


Case Number

4109

Large

Exhibits





A
SW

SKELLY OIL
NO. 1-P NEW MEXICO FEDERAL
EI. 3178 DF



Projected Into Line of Section


OLSEN OILS
NO. 1 FEDERAL
EI. 2997 DF Est.

PROPOSED
LOCATION
EI. 2950 Est.


SINCLAIR
NO. 1 SOUTHWEST JAL UNIT
EI. 3000 DF

A'
NE







- LEGEND**
- ☼ Significant gas show TSTM on test
 - ☼ Measurable gas on test
 - ☼ Production
 - ☼ Show of gas in samples
 - ☼ Measurable oil on test





HUMBLE OIL AND REFINING COMPANY
 SW-NE STRUCTURAL CROSS-SECTION
 SOUTH LEA UNIT
 LEA COUNTY, NEW MEXICO

January 1969

BEFORE EXAMINER UTZ
 OIL CONSERVATION COMMISSION
 CASE NO. 4101





A
SW

SKELLY OIL
NO. 1-P NEW MEXICO FEDERAL
El. 3178 DF

Projected into Line of Section

OLSEN OILS
NO. 1 FEDERAL
El. 2997 DF Est.

PROPOSED
LOCATION
El. 2950 Est.

SINCLAIR
NO. 1 SOUTHWEST JAL UNIT
El. 3000 DF

A'
NE

