

State of New Mexico
Energy Minerals and Natural Resources
Department Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
<https://www.emnrd.nm.gov/ocd/ocd-e-permitting/>

Form C-147
Revised October 11, 2022

Recycling Facility and/or Recycling Containment

Type of Facility: ☐ Recycling Facility ☐ Recycling Containment*
Type of action: ☐ Permit ☐ Registration
☐ Modification ☒ Extension
☐ Closure ☐ Other (explain) _____

*** At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.

Operator: EOG Resources Inc. (For multiple operators attach page with information) OGRID #: 7377
 Address: 5509 Champions Drive Midland, TX 79707
 Facility or well name (include API# if associated with a well): Galaxy Reuse Water Recycling Facility and Containment Pit
 OCD Permit Number: 1RF-25-0 (For new facilities the permit number will be assigned by the district office)
 U/L or Qtr/Qtr D Section 16 Township 24S Range 33E County: LEA
 Surface Owner: ☐ Federal ☒ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.

☐ **Recycling Facility:**
 Location of recycling facility (if applicable): Latitude 32.2214792 Longitude -103.5825816 NAD83
 Proposed Use: ☐ Drilling* ☒ Completion* ☐ Production* ☐ Plugging*
**The re-use of produced water may NOT be used until fresh water zones are cased and cemented*
☐ Other, *requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.*
☐ Fluid Storage
☐ Above ground tanks ☐ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type _____
☐ Activity permitted under 19.15.36 NMAC explain type: _____ ☐ Other explain _____
☐ For multiple or additional recycling containments, attach design and location information of each containment
☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: _____

3.

☒ **Recycling Containment:**
☒ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)
 Center of Recycling Containment (if applicable): Latitude _____ Longitude _____ NAD83
☐ For multiple or additional recycling containments, attach design and location information of each containment
☒ Lined ☒ Liner type: Thickness 60 mil ☐ LLDPE ☒ HDPE ☐ PVC ☐ Other _____
☐ String-Reinforced
 Liner Seams: ☒ Welded ☐ Factory ☐ Other _____ Volume: 1mm bbl Dimensions: L 600 x W 600 x D 16
☐ Recycling Containment Closure Completion Date: _____

4.

Bonding:

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ _____ (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify _____

6.

Signs:

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

- ☒ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

If a Variance is requested, it must be approved prior to implementation.

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting**Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☐ No
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☐ No
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☐ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☐ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☐ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☐ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☐ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☐ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☐ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

Recycling Facility and/or Containment Checklist:

Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☒ Design Plan - based upon the appropriate requirements.
- ☒ Operating and Maintenance Plan - based upon the appropriate requirements.
- ☒ Closure Plan - based upon the appropriate requirements.
- ☒ Site Specific Groundwater Data -
- ☒ Siting Criteria Compliance Demonstrations –
- ☒ Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Patricia Donald Title: Regulatory Specialist
Signature: Patricia Donald Date: 12/01/2023
e-mail address: patricia_donald@eogresources.com Telephone: 432-488-7684

11.

OCD Representative Signature: Victoria Venegas Approval Date: 11/30/2023

Title: Environmental Specialist OCD Permit Number: 1RF-25

- ☒ OCD Conditions
- ☐ Additional OCD Conditions on Attachment



Forms Report

Forms Summary

Total Forms: 51

| Form Date | Status | Form ID | Form Type | Application Name |
|------------|-----------|--------------------------|---------------------------|------------------|
| 11/20/2023 | Completed | 10980894 | Reuse Pit Inspection - NM | iEnvironmental |
| 11/13/2023 | Completed | 10962949 | Reuse Pit Inspection - NM | iEnvironmental |
| 11/06/2023 | Completed | 10950428 | Reuse Pit Inspection - NM | iEnvironmental |
| 10/31/2023 | Completed | 10931118 | Reuse Pit Inspection - NM | iEnvironmental |
| 10/23/2023 | Completed | 10918893 | Reuse Pit Inspection - NM | iEnvironmental |
| 10/17/2023 | Completed | 10897394 | Reuse Pit Inspection - NM | iEnvironmental |
| 10/09/2023 | Completed | 10885306 | Reuse Pit Inspection - NM | iEnvironmental |
| 10/03/2023 | Completed | 10868791 | Reuse Pit Inspection - NM | iEnvironmental |
| 09/25/2023 | Completed | 10848508 | Reuse Pit Inspection - NM | iEnvironmental |
| 09/18/2023 | Completed | 10833409 | Reuse Pit Inspection - NM | iEnvironmental |
| 09/11/2023 | Completed | 10820429 | Reuse Pit Inspection - NM | iEnvironmental |
| 09/05/2023 | Completed | 10796682 | Reuse Pit Inspection - NM | iEnvironmental |
| 08/28/2023 | Completed | 10790044 | Reuse Pit Inspection - NM | iEnvironmental |
| 08/22/2023 | Completed | 10784620 | Reuse Pit Inspection - NM | iEnvironmental |
| 08/21/2023 | Completed | 10770775 | Reuse Pit Inspection - NM | iEnvironmental |
| 08/14/2023 | Completed | 10737828 | Reuse Pit Inspection - NM | iEnvironmental |
| 07/31/2023 | Completed | 10724161 | Reuse Pit Inspection - NM | iEnvironmental |
| 07/24/2023 | Completed | 10706792 | Reuse Pit Inspection - NM | iEnvironmental |
| 07/17/2023 | Completed | 10682840 | Reuse Pit Inspection - NM | iEnvironmental |
| 07/10/2023 | Completed | 10667856 | Reuse Pit Inspection - NM | iEnvironmental |
| 07/03/2023 | Completed | 10647109 | Reuse Pit Inspection - NM | iEnvironmental |
| 06/26/2023 | Completed | 10615688 | Reuse Pit Inspection - NM | iEnvironmental |
| 06/19/2023 | Completed | 10615619 | Reuse Pit Inspection - NM | iEnvironmental |
| 06/13/2023 | Completed | 10594379 | Reuse Pit Inspection - NM | iEnvironmental |
| 06/05/2023 | Completed | 10571572 | Reuse Pit Inspection - NM | iEnvironmental |
| 05/29/2023 | Completed | 10571509 | Reuse Pit Inspection - NM | iEnvironmental |
| 05/24/2023 | Completed | 10533698 | Reuse Pit Inspection - NM | iEnvironmental |
| 05/15/2023 | Completed | 10525960 | Reuse Pit Inspection - NM | iEnvironmental |
| 05/10/2023 | Completed | 10504368 | Reuse Pit Inspection - NM | iEnvironmental |
| 05/01/2023 | Completed | 10485072 | Reuse Pit Inspection - NM | iEnvironmental |
| 04/24/2023 | Completed | 10469863 | Reuse Pit Inspection - NM | iEnvironmental |
| 04/18/2023 | Completed | 10451582 | Reuse Pit Inspection - NM | iEnvironmental |
| 04/10/2023 | Completed | 10436990 | Reuse Pit Inspection - NM | iEnvironmental |
| 04/03/2023 | Completed | 10419647 | Reuse Pit Inspection - NM | iEnvironmental |
| 03/27/2023 | Completed | 10409844 | Reuse Pit Inspection - NM | iEnvironmental |
| 03/20/2023 | Completed | 10394483 | Reuse Pit Inspection - NM | iEnvironmental |
| 03/13/2023 | Completed | 10379530 | Reuse Pit Inspection - NM | iEnvironmental |
| 03/12/2023 | Completed | 10349449 | Reuse Pit Inspection - NM | iEnvironmental |
| 02/27/2023 | Completed | 10321057 | Reuse Pit Inspection - NM | iEnvironmental |
| 02/20/2023 | Completed | 10306194 | Reuse Pit Inspection - NM | iEnvironmental |
| 02/13/2023 | Completed | 10291393 | Reuse Pit Inspection - NM | iEnvironmental |
| 02/06/2023 | Completed | 10281307 | Reuse Pit Inspection - NM | iEnvironmental |
| 01/30/2023 | Completed | 10272156 | Reuse Pit Inspection - NM | iEnvironmental |
| 01/23/2023 | Completed | 10236396 | Reuse Pit Inspection - NM | iEnvironmental |
| 01/10/2023 | Completed | 10226068 | Reuse Pit Inspection - NM | iEnvironmental |
| 01/09/2023 | Completed | 10215074 | Reuse Pit Inspection - NM | iEnvironmental |
| 01/02/2023 | Completed | 10199834 | Reuse Pit Inspection - NM | iEnvironmental |
| 12/27/2022 | Completed | 10183095 | Reuse Pit Inspection - NM | iEnvironmental |
| 12/19/2022 | Completed | 10156979 | Reuse Pit Inspection - NM | iEnvironmental |



| Form Date | Status | Form ID | Form Type | Application Name |
|------------|-----------|--------------------------|---------------------------|------------------|
| 12/12/2022 | Completed | 10146082 | Reuse Pit Inspection - NM | iEnvironmental |
| 12/06/2022 | Completed | 10146039 | Reuse Pit Inspection - NM | iEnvironmental |



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | Property ID | | |
| RH GALAXY REUSE PIT | 074829000 | | |
| Form Description | Form ID | | |
| Reuse Pit Inspection - NM | 10980894 | | |
| Scheduled | Completed | | |
| 11/22/2023 | 11/20/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | Jorge Gutierrez | 10962949 |
| Comments | | | |

Last Modified By

Jorge Gutierrez

Last Modified Date

11/20/2023

Created By

Alexandra Pedrique

Created Date

11/13/2023

General**Visual inspection conducted:**

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM**Property**

RH GALAXY REUSE PIT

Property ID

074829000

Form Description**Form ID**

10962949

Scheduled

11/15/2023

Completed

11/13/2023

Status

Completed

Assigned GroupNM - Water Reuse & Pipeline
Team**Assigned Member**

Alexandra Pedrique

Previous Form

10950428

Comments**Last Modified By**
Alexandra Pedrique**Last Modified Date**
11/13/2023**Created By**
Alexandra Pedrique**Created Date**
11/06/2023**General****Visual inspection
conducted:**

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

**Is there a visible layer of
oil on the surface of the
recycling containment?:**

No

**Is there at least 3 feet of
freeboard at the
containment?:**

Yes

**Is leak detection system
working properly?:**

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM**Property**

RH GALAXY REUSE PIT

Property ID

074829000

Form Description**Form ID**

10950428

Scheduled

11/08/2023

Completed

11/06/2023

Status

Completed

Assigned GroupNM - Water Reuse & Pipeline
Team**Assigned Member**

Alexandra Pedrique

Previous Form

10931118

Comments**Last Modified By**

Alexandra Pedrique

Last Modified Date

11/06/2023

Created By

Jorge Gutierrez

Created Date

10/31/2023

General**Visual inspection
conducted:**

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

**Is there a visible layer of
oil on the surface of the
recycling containment?:**

No

**Is there at least 3 feet of
freeboard at the
containment?:**

Yes

**Is leak detection system
working properly?:**

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM**Property**

RH GALAXY REUSE PIT

Property ID

074829000

Form Description**Form ID**

10931118

Scheduled

11/01/2023

Completed

10/31/2023

Status

Completed

Assigned GroupNM - Water Reuse & Pipeline
Team**Assigned Member**

Alexandra Pedrique

Previous Form

10918893

Comments**Last Modified By**

Jorge Gutierrez

Last Modified Date

10/31/2023

Created By

Ryan Eldridge

Created Date

10/23/2023

General**Visual inspection
conducted:**

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

**Is there a visible layer of
oil on the surface of the
recycling containment?:**

No

**Is there at least 3 feet of
freeboard at the
containment?:**

Yes

**Is leak detection system
working properly?:**

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description**Form ID**

10918893

Scheduled

10/25/2023

Completed

10/23/2023

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Omar Hinojos Team

Assigned Member**Previous Form**

10897394

Comments**Last Modified By**

Ryan Eldridge

Last Modified Date

10/23/2023

Created By

Jorge Gutierrez

Created Date

10/17/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

No

Repair Request:

It's stuck in the pipe, issues is being worked on

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM**Property**

RH GALAXY REUSE PIT

Property ID

074829000

Form Description**Form ID**

10897394

Scheduled

10/18/2023

Completed

10/17/2023

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Team

Assigned Member

Omar Hinojos

Previous Form

10885306

Comments**Last Modified By**

Jorge Gutierrez

Last Modified Date

10/17/2023

Created By

Omar Hinojos

Created Date

10/09/2023

General**Visual inspection conducted:**

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|-------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| | | | 10885306 |
| Scheduled | Completed | | |
| 10/11/2023 | 10/09/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | Omar Hinojos | 10868791 |
| Comments | | | |

Last Modified By

Omar Hinojos

Last Modified Date

10/09/2023

Created By

Alan Ramirez

Created Date

10/03/2023

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description**Form ID**

10868791

Scheduled

10/04/2023

Completed

10/03/2023

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Team

Assigned Member

Omar Hinojos

Previous Form

10848508

Comments**Last Modified By**

Alan Ramirez

Last Modified Date

10/03/2023

Created By

Omar Hinojos

Created Date

09/25/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10848508 |
| Scheduled | Completed | | |
| 09/27/2023 | 09/25/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | Omar Hinojos | 10833409 |
| Comments | | | |

Last Modified By

Omar Hinojos

Last Modified Date

09/25/2023

Created By

Alan Ramirez

Created Date

09/18/2023

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10833409 |
| Scheduled | Completed | | |
| 09/20/2023 | 09/18/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10820429 |
| Comments | | | |

Last Modified By

Alan Ramirez

Last Modified Date

09/18/2023

Created By

Carlos Trevino

Created Date

09/11/2023

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10820429 |
| Scheduled | Completed | | |
| 09/13/2023 | 09/11/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10796682 |
| Comments | | | |

Last Modified By

Carlos Trevino

Last Modified Date

09/11/2023

Created By

Alan Ramirez

Created Date

09/05/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10796682 |
| Scheduled | Completed | | |
| 09/06/2023 | 09/05/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10790044 |
| Comments | | | |

Last Modified By

Alan Ramirez

Last Modified Date

09/05/2023

Created By

Jorge Gutierrez

Created Date

08/28/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

No

Repair Request:

Leak detection pump is stuck and not moving water. Need to get it pulled and replaced.

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10790044 |
| Scheduled | Completed | | |
| 08/28/2023 | 08/28/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10784620 |
| Comments | | | |

Last Modified By

Omar Hinojos

Last Modified Date

08/28/2023

Created By

Jorge Gutierrez

Created Date

08/22/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10784620 |
| Scheduled | Completed | | |
| 08/23/2023 | 08/22/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10770775 |
| Comments | | | |

Last Modified By

Jorge Gutierrez

Last Modified Date

08/22/2023

Created By

Joe Sanchez

Created Date

08/22/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10770775 |
| Scheduled | Completed | | |
| 08/16/2023 | 08/21/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10737828 |
| Comments | | | |

Last Modified By

Joe Sanchez

Last Modified Date

08/22/2023

Created By

Jorge Gutierrez

Created Date

08/14/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10737828 |
| Scheduled | Completed | | |
| 08/09/2023 | 08/14/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10724161 |
| Comments | | | |

Last Modified By

Jorge Gutierrez

Last Modified Date

08/14/2023

Created By

Ivone Rodriguez

Created Date

07/31/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10724161 |
| Scheduled | Completed | | |
| 08/02/2023 | 07/31/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10706792 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

07/31/2023

Created By

Ivone Rodriguez

Created Date

07/24/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

Yes

Repair Request:

Fence poles bent, south west side of Pit

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10706792 |
| Scheduled | Completed | | |
| 07/26/2023 | 07/24/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10682840 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

07/24/2023

Created By

Jorge Gutierrez

Created Date

07/17/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

10682840

Scheduled

07/19/2023

Completed

07/17/2023

Status

Completed

Assigned GroupNM - Water Reuse & Pipeline
Team**Assigned Member****Previous Form**

10667856

Comments**Last Modified By**

Jorge Gutierrez

Last Modified Date

07/17/2023

Created By

Ivone Rodriguez

Created Date

07/10/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

10667856

Scheduled

07/12/2023

Completed

07/10/2023

Status

Completed

Assigned GroupNM - Water Reuse & Pipeline
Team**Assigned Member****Previous Form**

10647109

Comments**Last Modified By**

Ivone Rodriguez

Last Modified Date

07/10/2023

Created By

Ivone Rodriguez

Created Date

07/03/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10647109 |
| Scheduled | Completed | | |
| 07/05/2023 | 07/03/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10615688 |

Comments

Liner extra plastic laying around needs to be trashed (clean up).

Last Modified By

Ivone Rodriguez

Last Modified Date

07/03/2023

Created By

Ivone Rodriguez

Created Date

06/26/2023

General

| | | | |
|--|---|--|----------------------|
| Visual inspection conducted: | Bird Deterrent Issue: | Berm or Line issue: | Fence Issues: |
| Yes | No | No | No |
| Is there a visible layer of oil on the surface of the recycling containment?: | Is there at least 3 feet of freeboard at the containment?: | Is leak detection system working properly?: | Attachments: |
| No | Yes | Yes | |



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10615688 |
| Scheduled | Completed | | |
| 06/28/2023 | 06/26/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10615619 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

06/26/2023

Created By

Ivone Rodriguez

Created Date

06/19/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10615619 |
| Scheduled | Completed | | |
| 06/21/2023 | 06/19/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10594379 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

06/19/2023

Created By

Ivone Rodriguez

Created Date

06/19/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

10594379

Scheduled

06/14/2023

Completed

06/13/2023

Status

Completed

Assigned GroupNM - Water Reuse & Pipeline
Team**Assigned Member****Previous Form**

10571572

Comments**Last Modified By**

Ivone Rodriguez

Last Modified Date

06/19/2023

Created By

Ivone Rodriguez

Created Date

06/07/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | Property ID | | |
| RH GALAXY REUSE PIT | 074829000 | | |
| Form Description | Form ID | | |
| Reuse Pit Inspection - NM | 10571572 | | |
| Scheduled | Completed | | |
| 06/07/2023 | 06/05/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10571509 |

Comments

Liner needs to be power washed.

Last Modified By

Ivone Rodriguez

Last Modified Date

06/07/2023

Created By

Alfred Perez

Created Date

05/29/2023

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10571509 |
| Scheduled | Completed | | |
| 05/31/2023 | 05/29/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10533698 |
| Comments | | | |

Last Modified By

Alfred Perez

Last Modified Date

05/29/2023

Created By

Ivone Rodriguez

Created Date

05/29/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10533698 |
| Scheduled | Completed | | |
| 05/24/2023 | 05/24/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10525960 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

05/29/2023

Created By

Ivone Rodriguez

Created Date

05/15/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

Yes

Repair Request:

On left side of entry gate, fence damaged

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10525960 |
| Scheduled | Completed | | |
| 05/17/2023 | 05/15/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10504368 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

05/15/2023

Created By

Ivone Rodriguez

Created Date

05/10/2023

General

| | | | |
|-------------------------------------|--|--|--|
| Visual inspection conducted: | Bird Deterrent Issue: | Repair Request: | Berm or Line issue: |
| Yes | Yes | Back SE side, bird deterrent too low on sound. (Replace speaker) Battery charged and volume at max, panel cleaned. | No |
| Fence Issues: | Is there a visible layer of oil on the surface of the recycling containment?: | Is there at least 3 feet of freeboard at the containment?: | Is leak detection system working properly?: |
| No | No | Yes | Yes |
| Attachments: | | | |



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10504368 |
| Scheduled | Completed | | |
| 05/10/2023 | 05/10/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10485072 |
| Comments | | | |
| Pit Liner needs cleaning when convenient. | | | |

Last Modified By
Ivone Rodriguez

Last Modified Date
05/10/2023

Created By
Ivone Rodriguez

Created Date
05/01/2023

General

| | | | |
|--|---|--|----------------------|
| Visual inspection conducted: | Bird Deterrent Issue: | Berm or Line issue: | Fence Issues: |
| Yes | No | No | No |
| Is there a visible layer of oil on the surface of the recycling containment?: | Is there at least 3 feet of freeboard at the containment?: | Is leak detection system working properly?: | Attachments: |
| No | Yes | Yes | |



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10485072 |
| Scheduled | Completed | | |
| 05/03/2023 | 05/01/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10469863 |

Comments

Aerator SW of pit not working, makes a sound when start but fails to turn on.

Last Modified By

Ivone Rodriguez

Last Modified Date

05/01/2023

Created By

Ivone Rodriguez

Created Date

04/25/2023

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10469863 |
| Scheduled | Completed | | |
| 04/26/2023 | 04/24/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10451582 |

Comments

Around pit clean up, vegetation around pit.

Last Modified By

Ivone Rodriguez

Last Modified Date

04/25/2023

Created By

Ivone Rodriguez

Created Date

04/18/2023

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
Yes

Repair Request:
Entrance gate needs to be fixed.

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10451582 |
| Scheduled | Completed | | |
| 04/19/2023 | 04/18/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10436990 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

04/18/2023

Created By

Ivone Rodriguez

Created Date

04/10/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10436990 |
| Scheduled | Completed | | |
| 04/12/2023 | 04/10/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10419647 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

04/10/2023

Created By

Ivone Rodriguez

Created Date

04/03/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

Yes

Repair Request:

Bird deterrents low on volume. (2)

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10419647 |
| Scheduled | Completed | | |
| 04/05/2023 | 04/03/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10409844 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

04/03/2023

Created By

Ivone Rodriguez

Created Date

03/27/2023

General

| | | | |
|--|-------------------------------|--|---|
| Visual inspection conducted: | Bird Deterrent Issue: | Repair Request: | Berm or Line issue: |
| Yes | Yes | Bird deterrent sound very low, checked battery (good). Volume at max. Located SE back right corner of pit. | No |
| Fence Issues: | Repair Request: | Is there a visible layer of oil on the surface of the recycling containment?: | Is there at least 3 feet of freeboard at the containment?: |
| Yes | Entry right gate out of place | No | Yes |
| Is leak detection system working properly?: | Attachments: | | |
| Yes | | | |



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10409844 |
| Scheduled | Completed | | |
| 03/29/2023 | 03/27/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10394483 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

03/27/2023

Created By

Ivone Rodriguez

Created Date

03/21/2023

General

| | | | |
|-------------------------------------|--|---|--|
| Visual inspection conducted: | Bird Deterrent Issue: | Repair Request: | Berm or Line issue: |
| Yes | Yes | Bird deterrent sound very low, checked battery (good). Volume at max. | No |
| Fence Issues: | Is there a visible layer of oil on the surface of the recycling containment?: | Is there at least 3 feet of freeboard at the containment?: | Is leak detection system working properly?: |
| No | No | Yes | Yes |
| Attachments: | | | |



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10394483 |
| Scheduled | Completed | | |
| 03/22/2023 | 03/20/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10379530 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

03/21/2023

Created By

Ivone Rodriguez

Created Date

03/13/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10379530 |
| Scheduled | Completed | | |
| 03/15/2023 | 03/13/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10349449 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

03/13/2023

Created By

Ivone Rodriguez

Created Date

03/06/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10349449 |
| Scheduled | Completed | | |
| 03/08/2023 | 03/12/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10321057 |

Comments

Galaxy We are done with all pending jobs

Last Modified By

Jorge Gutierrez

Last Modified Date

03/12/2023

Created By

Michael Lopez

Created Date

02/27/2023

General

| | | | |
|--|---|--|----------------------|
| Visual inspection conducted: | Bird Deterrent Issue: | Berm or Line issue: | Fence Issues: |
| Yes | No | No | No |
| Is there a visible layer of oil on the surface of the recycling containment?: | Is there at least 3 feet of freeboard at the containment?: | Is leak detection system working properly?: | Attachments: |
| No | Yes | Yes | |



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10321057 |
| Scheduled | Completed | | |
| 03/01/2023 | 02/27/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10306194 |
| Comments | | | |

Last Modified By

Michael Lopez

Last Modified Date

02/27/2023

Created By

Ivone Rodriguez

Created Date

02/20/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10306194 |
| Scheduled | Completed | | |
| 02/22/2023 | 02/20/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10291393 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

02/20/2023

Created By

Ivone Rodriguez

Created Date

02/13/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10291393 |
| Scheduled | Completed | | |
| 02/15/2023 | 02/13/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10281307 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

02/13/2023

Created By

Ivone Rodriguez

Created Date

02/06/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10281307 |
| Scheduled | Completed | | |
| 02/08/2023 | 02/06/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10272156 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

02/06/2023

Created By

Ivone Rodriguez

Created Date

01/31/2023

General

| | | | |
|--|---|--|------------------------|
| Visual inspection conducted: | Bird Deterrent Issue: | Berm or Line issue: | Fence Issues: |
| Yes | No | No | No |
| Is there a visible layer of oil on the surface of the recycling containment?: | Is there at least 3 feet of freeboard at the containment?: | Is leak detection system working properly?: | Repair Request: |
| No | Yes | No | In progress. |
| Attachments: | | | |



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10272156 |
| Scheduled | Completed | | |
| 02/01/2023 | 01/30/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10236396 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

01/31/2023

Created By

Ivone Rodriguez

Created Date

01/25/2023

General

| | | | |
|--|---|--|------------------------|
| Visual inspection conducted: | Bird Deterrent Issue: | Berm or Line issue: | Fence Issues: |
| Yes | No | No | No |
| Is there a visible layer of oil on the surface of the recycling containment?: | Is there at least 3 feet of freeboard at the containment?: | Is leak detection system working properly?: | Repair Request: |
| No | Yes | No | In progress. |
| Attachments: | | | |



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10236396 |
| Scheduled | Completed | | |
| 01/25/2023 | 01/23/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10226068 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

01/25/2023

Created By

Ivone Rodriguez

Created Date

01/10/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

Yes

Repair Request:

Bird deterrents not working.

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

No

Repair Request:

Repair in progress.

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | | | |
|-------------------------|---------------------------|-----------------------|----------------------------------|------------------------|-----------|
| Property | RH GALAXY REUSE PIT | | | Property ID | 074829000 |
| Form Description | Reuse Pit Inspection - NM | | | Form ID | 10226068 |
| Scheduled | 01/18/2023 | Completed | 01/10/2023 | | |
| Status | Completed | Assigned Group | NM - Water Reuse & Pipeline Team | Assigned Member | |
| | | | | Previous Form | 10215074 |

Comments

Pit liner needs to be cleaned (power washed).

Last Modified By

Ivone Rodriguez

Last Modified Date

01/10/2023

Created By

Jorge Gutierrez

Created Date

01/09/2023

General

| | | | |
|-------------------------------------|--|---|--|
| Visual inspection conducted: | Bird Deterrent Issue: | Repair Request: | Berm or Line issue: |
| Yes | Yes | deterrents sound very low on both bird deterrents. | No |
| Fence Issues: | Is there a visible layer of oil on the surface of the recycling containment?: | Is there at least 3 feet of freeboard at the containment?: | Is leak detection system working properly?: |
| No | No | Yes | No |
| Repair Request: | Attachments: | | |
| In progress. | | | |



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

10215074

Scheduled

01/11/2023

Completed

01/09/2023

Status

Completed

Assigned GroupNM - Water Reuse & Pipeline
Team**Assigned Member****Previous Form**

10199834

Comments**Last Modified By**

Jorge Gutierrez

Last Modified Date

01/09/2023

Created By

Ivone Rodriguez

Created Date

01/03/2023

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

No

Repair Request:

The leak detector is not working

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10199834 |
| Scheduled | Completed | | |
| 01/04/2023 | 01/02/2023 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10183095 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

01/03/2023

Created By

Ivone Rodriguez

Created Date

12/27/2022

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

Yes

Repair Request:

Cement base where pipe lays damaged.

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

No

Repair Request:

Waiting to be able to empty pit per Jorge Guetierrez.

Attachments:

1672747847554124.jpg



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10183095 |
| Scheduled | Completed | | |
| 12/28/2022 | 12/27/2022 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10156979 |
| Comments | | | |
| Clean up around pit (location). | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

12/27/2022

Created By

Ivone Rodriguez

Created Date

12/19/2022

General

| | | | |
|--|--|---|--|
| Visual inspection conducted: | Bird Deterrent Issue: | Repair Request: | Berm or Line issue: |
| Yes | Yes | Bird deterrents sound too low (reset both and sounds still low at max volume). | No |
| Fence Issues: | Is there a visible layer of oil on the surface of the recycling containment?: | Is there at least 3 feet of freeboard at the containment?: | Is leak detection system working properly?: |
| No | No | Yes | No |
| Repair Request: | Attachments: | | |
| Leak detector not working properly. Waiting to be able to drain pit. | | | |



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10156979 |
| Scheduled | Completed | | |
| 12/21/2022 | 12/19/2022 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10146082 |
| Comments | | | |

Last Modified By

Ivone Rodriguez

Last Modified Date

12/19/2022

Created By

Jorge Gutierrez

Created Date

12/12/2022

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

No

Repair Request:

Leak detector not working properly. Advised by Jorge Gutierrez Still in progress.

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

| | | | |
|---------------------------|----------------------------------|------------------------|----------------------|
| Property | | | Property ID |
| RH GALAXY REUSE PIT | | | 074829000 |
| Form Description | | | Form ID |
| Reuse Pit Inspection - NM | | | 10146082 |
| Scheduled | Completed | | |
| 12/14/2022 | 12/12/2022 | | |
| Status | Assigned Group | Assigned Member | Previous Form |
| Completed | NM - Water Reuse & Pipeline Team | | 10146039 |
| Comments | | | |

Last Modified By

Jorge Gutierrez

Last Modified Date

12/12/2022

Created By

Ivone Rodriguez

Created Date

12/06/2022

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

No

Repair Request:

The leak detector needs to be replaced (we need to empty the pit to replace it)

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

10146039

Scheduled

12/07/2022

Completed

12/06/2022

Status

Completed

Assigned GroupNM - Water Reuse & Pipeline
Team**Assigned Member****Comments****Last Modified By**

Patricia Donald

Last Modified Date

12/07/2022

Created By

Patricia Donald

Created Date

12/06/2022

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

No

Repair Request:

Leak detect needs to be replaced.

Attachments:



P.O. Box 2267, Midland, Texas 79702
Phone: (432) 848-9133

December 1, 2023

Ms. Victoria Venegas, Environmental Specialist
EMNRD- Oil Conservation Division
506 W. Texas Artesia, NM 88210

Re: EOG Galaxy Pit 1RF-25-0

Dear Ms. Venegas:

Thank you for allowing EOG to continue to promote water reuse in the State of New Mexico for our operations. EOG plans to continue active completion operations near this pit location well into 2025 and would like to formally request an extension to our currently approved permit.

Sincerely,

Patricia Donald

Patricia Donald
Regulatory Specialist

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Thursday, November 30, 2023 1:45 PM
To: Patricia Donald
Subject: 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871]
Attachments: C-147 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871].pdf

1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871]

Good afternoon Ms. Donald,

NMOCD has reviewed the determination of registration/permit annual extension request for 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871] received from [7377] EOG RESOURCES INC on November 27, 2023. The registration/permit annual extension request is approved with the following conditions of approval:

- 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of January 2, 2024. The new registration/permit expiration date is January 2, 2025.
- [7377] EOG RESOURCES INC will continue to operate, maintain, and close the 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871] in compliance with 19.15.34 NMAC, to include but not limited to the performance of weekly inspections regardless of fluid levels in the containment; recording of detailed inspection reports; removal of debris, foreign objects and oil from the containment; and monthly reporting of recycling and reuse of produced water, drilling fluids, and liquid oil field waste via from C-148.
- [7377] EOG RESOURCES INC will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. [7377] EOG RESOURCES INC may maintain a higher liquid level if they choose.
- If less than 20% of the total fluid capacity is utilized every consecutive six months, operation of the facility is considered ceased and notification of cessation of operations should be sent electronically form through the [OCD Online](#). An extension to extend the cessation of operations, not to exceed six months, may be submitted using a C-147 form via [OCD Online](#).
- The recycling containment is bonded pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC. Water reuse and recycling from 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871] is limited to wells owned or operated by [7377] EOG RESOURCES INC.
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times.
- [7377] EOG RESOURCES INC will comply with 19.15.29 NMAC Releases in the event of any release of produced water or produced water or other oil field wastes at 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871]. [7377] EOG RESOURCES INC will comply with all other OCD rules.
- [7377] EOG RESOURCES INC must perform weekly inspections of the containment and leak detection system.
- If [7377] EOG RESOURCES INC wishes to extend the registration/permit past January 2, 2025, a registration/permit extension request must be submitted to OCD. Extension requests are reviewed on a case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of one year.
- Additional requests must be submitted to OCD through the [OCD Online](#) system on a Form C-147 (long form) as an Extension request and should include a formal extension request letter, a summary of the prior registration/permit period inspection reports, and the copies of the detailed inspection records for the prior permit period. The extension request should be submitted no later than December 2, 2024.

Please let me know if you have any additional questions.

Regards,

Victoria Venegas • Environmental Specialist
Environmental Bureau
EMNRD - Oil Conservation Division
506 W. Texas Ave. Artesia, NM 88210
(575) 909-0269 | Victoria.Venegas@emnrd.nm.gov
<https://www.emnrd.nm.gov/oed/>



District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 288363

CONDITIONS

| | |
|--|---|
| Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702 | OGRID: 7377 |
| | Action Number: 288363 |
| | Action Type: [C-147] Water Recycle Long (C-147L) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|---|----------------|
| vvenegas | • 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [f0Y1801852871] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of January 2, 2024. The new registration/permit expiration date is January 2, 2025. • If [7377] EOG RESOURCES INC wishes to extend the registration/permit past January 2, 2025, a registration/permit extension request must be submitted to OCD no later than December 2, 2024 | 11/30/2023 |