

State of New Mexico
Energy Minerals and Natural Resources
Department Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
https://www.emnrd.nm.gov/ocd/ocd-e-permitting/

Recycling Facility and/or Recycling Containment

Type of Facility: [x] Recycling Facility [x] Recycling Containment*
Type of action: [x] Permit [] Registration
[] Modification [x] Extension
[] Closure [] Other (explain)

* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1. Operator: EOG Resources Inc. (For multiple operators attach page with information) OGRID #: 7377
Address: 5509 Champions Drive Midland, TX 79707
Facility or well name (include API# if associated with a well): Galaxy Reuse Water Recycling Facility and Containment Pit
OCD Permit Number: 1RF-25-0 (For new facilities the permit number will be assigned by the district office)
U/L or Qtr/Qtr D Section 16 Township 24S Range 33E County: LEA
Surface Owner: [] Federal [x] State [] Private [] Tribal Trust or Indian Allotment

2. [] Recycling Facility:
Location of recycling facility (if applicable): Latitude 32.2214792 Longitude -103.5825816 NAD83
Proposed Use: [] Drilling* [x] Completion* [] Production* [] Plugging *
*The re-use of produced water may NOT be used until fresh water zones are cased and cemented
[] Other, requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.
[] Fluid Storage
[] Above ground tanks [] Recycling containment [] Activity permitted under 19.15.17 NMAC explain type
[] Activity permitted under 19.15.36 NMAC explain type: [] Other explain
[] For multiple or additional recycling containments, attach design and location information of each containment
[] Closure Report (required within 60 days of closure completion): [] Recycling Facility Closure Completion Date:

3. [x] Recycling Containment:
[x] Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)(01/02/25-01/02/26)
Center of Recycling Containment (if applicable): Latitude Longitude NAD83
[] For multiple or additional recycling containments, attach design and location information of each containment
[x] Lined [x] Liner type: Thickness 60 mil [] LLDPE [x] HDPE [] PVC [] Other
[] String-Reinforced
Liner Seams: [x] Welded [] Factory [] Other Volume: 1mm bbl Dimensions: L 600 x W 600 x D 16
[] Recycling Containment Closure Completion Date:

4.

Bonding:

Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)

Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ _____ (work on these facilities cannot commence until bonding amounts are approved)

Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

Four foot height, four strands of barbed wire evenly spaced between one and four feet

Alternate. Please specify _____

6.

Signs:

12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers

Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

If a Variance is requested, it must be approved prior to implementation.

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

<u>General siting</u>	
<u>Ground water is less than 50 feet below the bottom of the Recycling Containment.</u> NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> NA
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; written approval obtained from the municipality	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> NA
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division	<input type="checkbox"/> Yes <input type="checkbox"/> No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map	<input type="checkbox"/> Yes <input type="checkbox"/> No
Within a 100-year floodplain. FEMA map	<input type="checkbox"/> Yes <input type="checkbox"/> No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input type="checkbox"/> No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; aerial photo; satellite image	<input type="checkbox"/> Yes <input type="checkbox"/> No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input type="checkbox"/> No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input type="checkbox"/> No

9.

Recycling Facility and/or Containment Checklist:

Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- Design Plan - based upon the appropriate requirements.
- Operating and Maintenance Plan - based upon the appropriate requirements.
- Closure Plan - based upon the appropriate requirements.
- Site Specific Groundwater Data -
- Siting Criteria Compliance Demonstrations -
- Certify that notice of the C-147 (only) has been sent to the surface owner(s)**

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Patricia Donald Title: Regulatory Specialist

Signature: *Patricia Donald* Date: 12/17/2024

e-mail address: patricia_donald@eogresources.com Telephone: 432-488-7684

11.

OCD Representative Signature: *Victoria Venegas* Approval Date: 12/20/2024

Title: Environmental Specialist OCD Permit Number: 1RF-25

OCD Conditions

Additional OCD Conditions on Attachment



P.O. Box 2267, Midland, Texas 79702
Phone: (432) 848-9133

December 17, 2024

Ms. Victoria Venegas, Environmental Specialist
EMNRD- Oil Conservation Division
506 W. Texas Artesia, NM 88210

Re: EOG Galaxy Pit 1RF-25-0

Dear Ms. Venegas:

Thank you for allowing EOG to continue to promote water reuse in the State of New Mexico for our operations. EOG plans to continue active completion operations near this pit location well into 2026 and would like to formally request an extension to our currently approved permit.

Sincerely,

Patricia Donald

Patricia Donald
Regulatory Specialist

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Friday, December 20, 2024 8:48 AM
To: Patricia Donald
Subject: 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871]
Attachments: C-147 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT [fOY1801852871].pdf

1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871]

Ms. Donald,

NMOCD has reviewed the determination of registration/permit annual extension request for 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871] received from [7377] EOG RESOURCES INC on 12/17/2024, Action ID 412954. The registration/permit annual extension request is approved with the following conditions of approval:

- 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of January 2, 2025. The new registration/permit expiration date is January 2, 2026.
- [7377] EOG RESOURCES INC will continue to operate, maintain, and close the 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871] in compliance with 19.15.34 NMAC to include but not limited to the performance of weekly inspections regardless of fluid levels in the containment; recording of detailed inspection reports; removal of debris, foreign objects and oil from the containment; and monthly reporting of recycling and reuse of produced water, drilling fluids, and liquid oil field waste via from C-148.
- [7377] EOG RESOURCES INC will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. [7377] EOG RESOURCES INC may maintain a higher liquid level if they choose.
- If less than 20% of the total fluid capacity is utilized every consecutive six months, operation of the facility is considered ceased and notification of cessation of operations should be sent electronically form through the OCD Permitting. An extension to extend the cessation of operations, not to exceed six months, may be submitted using a C-147 form via OCD Permitting.
- The recycling containment is bonded pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC. Water reuse and recycling from 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871] is limited to wells owned or operated by [7377] EOG RESOURCES INC.
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times.
- [7377] EOG RESOURCES INC will comply with 19.15.29 NMAC Releases in the event of any release of produced water or produced water or other oil field wastes at 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871]. [7377] EOG RESOURCES INC will comply with all other OCD rules.
- [7377] EOG RESOURCES INC must perform weekly inspections of the containment and leak detection system.
- If [7377] EOG RESOURCES INC wishes to extend the registration/permit past January 2, 2026, a registration/permit extension request must be submitted to OCD. Extension requests are reviewed on a case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of one year.

- Additional requests must be submitted to OCD through the OCD Permitting on a Form C-147 (long form) as an Extension request and should include a formal extension request letter, a summary of the prior registration/permit period inspection reports, and the copies of the detailed inspection records for the prior permit period. The extension request should be submitted no later than December 2, 2025.

Please let me know if you have any additional questions.

Regards,

Victoria Venegas • Environmental Specialist Advanced
EMNRD - Oil Conservation Division
506 W. Texas Ave. Artesia, NM 88210
575.909.0269 | Victoria.Venegas@emnrn.nm.gov



Forms Report

Forms Summary

Total Forms: 42

Form Date	Status	Form ID	Form Type	Application Name
10/28/2024	Completed	11895159	Reuse Pit Inspection - NM	iEnvironmental
09/02/2024	Completed	11781495	Reuse Pit Inspection - NM	iEnvironmental
08/13/2024	Completed	11818330	Reuse Pit Inspection - NM	iEnvironmental
07/29/2024	Completed	11773006	Reuse Pit Inspection - NM	iEnvironmental
07/22/2024	Completed	11749091	Reuse Pit Inspection - NM	iEnvironmental
07/22/2024	Completed	11728372	Reuse Pit Inspection - NM	iEnvironmental
07/08/2024	Completed	11706674	Reuse Pit Inspection - NM	iEnvironmental
07/08/2024	Completed	11694938	Reuse Pit Inspection - NM	iEnvironmental
06/26/2024	Completed	11669392	Reuse Pit Inspection - NM	iEnvironmental
06/26/2024	Completed	11649489	Reuse Pit Inspection - NM	iEnvironmental
06/24/2024	Completed	11694937	Reuse Pit Inspection - NM	iEnvironmental
06/17/2024	Completed	11669391	Reuse Pit Inspection - NM	iEnvironmental
06/11/2024	Completed	11620593	Reuse Pit Inspection - NM	iEnvironmental
06/10/2024	Completed	11649327	Reuse Pit Inspection - NM	iEnvironmental
06/03/2024	Completed	11620592	Reuse Pit Inspection - NM	iEnvironmental
05/28/2024	Completed	11586953	Reuse Pit Inspection - NM	iEnvironmental
05/20/2024	Completed	11559019	Reuse Pit Inspection - NM	iEnvironmental
05/13/2024	Completed	11528282	Reuse Pit Inspection - NM	iEnvironmental
05/06/2024	Completed	11499462	Reuse Pit Inspection - NM	iEnvironmental
04/29/2024	Completed	11499454	Reuse Pit Inspection - NM	iEnvironmental
04/29/2024	Completed	11475807	Reuse Pit Inspection - NM	iEnvironmental
04/22/2024	Completed	11450852	Reuse Pit Inspection - NM	iEnvironmental
04/15/2024	Completed	11425774	Reuse Pit Inspection - NM	iEnvironmental
04/09/2024	Completed	11392583	Reuse Pit Inspection - NM	iEnvironmental
04/02/2024	Completed	11367235	Reuse Pit Inspection - NM	iEnvironmental
03/25/2024	Completed	11338247	Reuse Pit Inspection - NM	iEnvironmental
03/18/2024	Completed	11295110	Reuse Pit Inspection - NM	iEnvironmental
03/11/2024	Completed	11260318	Reuse Pit Inspection - NM	iEnvironmental
03/04/2024	Completed	11242990	Reuse Pit Inspection - NM	iEnvironmental
02/26/2024	Completed	11223909	Reuse Pit Inspection - NM	iEnvironmental
02/19/2024	Completed	11197114	Reuse Pit Inspection - NM	iEnvironmental
02/12/2024	Completed	11186119	Reuse Pit Inspection - NM	iEnvironmental
02/05/2024	Completed	11166356	Reuse Pit Inspection - NM	iEnvironmental
01/29/2024	Completed	11145551	Reuse Pit Inspection - NM	iEnvironmental
01/22/2024	Completed	11130083	Reuse Pit Inspection - NM	iEnvironmental
01/15/2024	Completed	11114274	Reuse Pit Inspection - NM	iEnvironmental
01/08/2024	Completed	11091604	Reuse Pit Inspection - NM	iEnvironmental
01/01/2024	Completed	11083785	Reuse Pit Inspection - NM	iEnvironmental
12/25/2023	Completed	11062445	Reuse Pit Inspection - NM	iEnvironmental
12/18/2023	Completed	11043440	Reuse Pit Inspection - NM	iEnvironmental
12/11/2023	Completed	11024427	Reuse Pit Inspection - NM	iEnvironmental
12/04/2023	Completed	11009952	Reuse Pit Inspection - NM	iEnvironmental



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11895159	
Scheduled	Completed		
10/28/2024	10/28/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Ricardo Villegas	11781495
Comments			

Last Modified By Ricardo Villegas	Created By Ricardo Villegas
Last Modified Date 10/28/2024	Created Date 09/02/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11781495	
Scheduled	Completed		
09/02/2024	09/02/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Ricardo Villegas	11773006
Comments			

Last Modified By Ricardo Villegas	Created By Oscar Jimenez
Last Modified Date 09/02/2024	Created Date 07/29/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property	RH GALAXY REUSE PIT		Property ID	074829000
Form Description	Reuse Pit Inspection - NM		Form ID	11818330
Scheduled	08/19/2024	Completed	08/13/2024	
Status	Completed	Assigned Group	NM - Water Reuse & Pipeline Omar Hinojos Team	
Assigned Member				
Comments				

Last Modified By	Omar Hinojos	Created By	Omar Hinojos
Last Modified Date	08/13/2024	Created Date	08/13/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11773006	
Scheduled	Completed		
08/05/2024	07/29/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11749091
Comments			

Last Modified By Oscar Jimenez	Created By Joe Sanchez
Last Modified Date 07/29/2024	Created Date 07/22/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID
RH GALAXY REUSE PIT		074829000
Form Description		Form ID
Reuse Pit Inspection - NM		11749091
Scheduled	Completed	
07/22/2024	07/22/2024	
Status	Assigned Group	Assigned Member
Completed	NM - Water Reuse & Pipeline Team	Joe Sanchez
		Previous Form
		11728372
Comments		

Last Modified By	Created By
Joe Sanchez	Oscar Jimenez
Last Modified Date	Created Date
07/22/2024	07/15/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID
RH GALAXY REUSE PIT		074829000
Form Description		Form ID
Reuse Pit Inspection - NM		11728372
Scheduled	Completed	
07/15/2024	07/22/2024	
Status	Assigned Group	Assigned Member
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez
		Previous Form
		11706674
Comments		

Last Modified By	Created By
Oscar Jimenez	Joe Sanchez
Last Modified Date	Created Date
07/15/2024	07/08/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11706674	
Scheduled	Completed		
07/08/2024	07/08/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Joe Sanchez	11694938
Comments			

Last Modified By Joe Sanchez	Created By Oscar Jimenez
Last Modified Date 07/08/2024	Created Date 07/01/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11694938	
Scheduled	Completed		
07/01/2024	07/08/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11694937
Comments			

Last Modified By Oscar Jimenez	Created By Oscar Jimenez
Last Modified Date 07/01/2024	Created Date 06/24/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11669392	
Scheduled	Completed		
06/25/2024	06/26/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	11669391
Comments			

Last Modified By Jorge Gutierrez	Created By Oscar Jimenez
Last Modified Date 06/26/2024	Created Date 06/17/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11649489	
Scheduled	Completed		
06/25/2024	06/26/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	11620593
Comments			

Last Modified By Jorge Gutierrez	Created By Jorge Gutierrez
Last Modified Date 06/26/2024	Created Date 06/11/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property	RH GALAXY REUSE PIT		Property ID	074829000	
Form Description	Reuse Pit Inspection - NM		Form ID	11694937	
Scheduled	06/24/2024	Completed	06/24/2024		
Status	Completed	Assigned Group	NM - Water Reuse & Pipeline Team	Assigned Member	Oscar Jimenez
Comments	Good to go				

Last Modified By
Oscar Jimenez
Last Modified Date
06/24/2024

Created By
Oscar Jimenez
Created Date
06/24/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property	RH GALAXY REUSE PIT		Property ID	074829000
Form Description	Reuse Pit Inspection - NM		Form ID	11669391
Scheduled	06/17/2024	Completed	06/17/2024	
Status	Completed	Assigned Group	NM - Water Reuse & Pipeline Team	
Assigned Member				
Comments				

Last Modified By	Oscar Jimenez	Created By	Oscar Jimenez
Last Modified Date	06/17/2024	Created Date	06/17/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11620593	
Scheduled	Completed		
06/11/2024	06/11/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11620592
Comments			

Last Modified By Jorge Gutierrez	Created By Oscar Jimenez
Last Modified Date 06/11/2024	Created Date 06/03/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property	RH GALAXY REUSE PIT		Property ID	074829000
Form Description	Reuse Pit Inspection - NM		Form ID	11649327
Scheduled	06/10/2024	Completed	06/10/2024	
Status	Completed	Assigned Group	NM - Water Reuse & Pipeline Oscar Jimenez Team	
Assigned Member				
Comments				

Last Modified By	Oscar Jimenez	Created By	Oscar Jimenez
Last Modified Date	06/10/2024	Created Date	06/10/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property	RH GALAXY REUSE PIT		Property ID	074829000	
Form Description	Reuse Pit Inspection - NM		Form ID	11620592	
Scheduled	06/03/2024	Completed	06/03/2024		
Status	Completed	Assigned Group	NM - Water Reuse & Pipeline Team	Assigned Member	Oscar Jimenez
Comments					

Last Modified By	Oscar Jimenez	Created By	Oscar Jimenez
Last Modified Date	06/03/2024	Created Date	06/03/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11586953	
Scheduled	Completed		
05/27/2024	05/28/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11559019
Comments			

Last Modified By Jorge Gutierrez	Created By Oscar Jimenez
Last Modified Date 05/28/2024	Created Date 05/20/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11559019	
Scheduled	Completed		
05/20/2024	05/20/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11528282
Comments			

Last Modified By	Created By
Oscar Jimenez	Joe Sanchez
Last Modified Date	Created Date
05/20/2024	05/13/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID
RH GALAXY REUSE PIT		074829000
Form Description		Form ID
Reuse Pit Inspection - NM		11528282
Scheduled	Completed	
05/13/2024	05/13/2024	
Status	Assigned Group	Assigned Member
Completed	NM - Water Reuse & Pipeline Team	Joe Sanchez
		Previous Form
		11499462
Comments		

Last Modified By	Created By
Joe Sanchez	Oscar Jimenez
Last Modified Date	Created Date
05/13/2024	05/06/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11499462	
Scheduled	Completed		
05/06/2024	05/06/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11499454
Comments			

Last Modified By Oscar Jimenez	Created By James Kelley
Last Modified Date 05/06/2024	Created Date 04/29/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11499454	
Scheduled	Completed		
04/29/2024	04/29/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11475807
Comments			

Last Modified By James Kelley	Created By Alan Ramirez
Last Modified Date 04/29/2024	Created Date 04/29/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property	RH GALAXY REUSE PIT		Property ID	074829000
Form Description	Reuse Pit Inspection - NM		Form ID	11475807
Scheduled	04/29/2024	Completed	04/29/2024	
Status	Completed	Assigned Group	Assigned Member	Previous Form
		NM - Water Reuse & Pipeline Team	Alfred Perez	11450852
Comments				

Last Modified By	Alan Ramirez	Created By	Alfred Perez
Last Modified Date	04/29/2024	Created Date	04/22/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID
RH GALAXY REUSE PIT		074829000
Form Description		Form ID
Reuse Pit Inspection - NM		11450852
Scheduled	Completed	
04/22/2024	04/22/2024	
Status	Assigned Group	Assigned Member
Completed	NM - Water Reuse & Pipeline Team	Alfred Perez
		Previous Form
		11425774
Comments		

Last Modified By	Created By
Alfred Perez	Oscar Jimenez
Last Modified Date	Created Date
04/22/2024	04/15/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11425774	
Scheduled	Completed		
04/15/2024	04/15/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11392583
Comments			

Last Modified By Oscar Jimenez	Created By Michael Lopez
Last Modified Date 04/15/2024	Created Date 04/09/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11392583	
Scheduled	Completed		
04/08/2024	04/09/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11367235
Comments			

Last Modified By Michael Lopez	Created By Oscar Jimenez
Last Modified Date 04/09/2024	Created Date 04/02/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID
RH GALAXY REUSE PIT		074829000
Form Description		Form ID
Reuse Pit Inspection - NM		11367235
Scheduled	Completed	
04/01/2024	04/02/2024	
Status	Assigned Group	Assigned Member
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez
		Previous Form
		11338247
Comments		

Last Modified By	Created By
Oscar Jimenez	Oscar Jimenez
Last Modified Date	Created Date
04/02/2024	03/25/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11338247	
Scheduled	Completed		
03/25/2024	03/25/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11295110
Comments			

Last Modified By Oscar Jimenez	Created By Oscar Jimenez
Last Modified Date 03/25/2024	Created Date 03/18/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11295110	
Scheduled	Completed		
03/18/2024	03/18/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11260318
Comments			

Last Modified By Oscar Jimenez	Created By Oscar Jimenez
Last Modified Date 03/18/2024	Created Date 03/11/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11260318	
Scheduled	Completed		
03/11/2024	03/11/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Oscar Jimenez	11242990
Comments			

Last Modified By Oscar Jimenez	Created By Oscar Jimenez
Last Modified Date 03/11/2024	Created Date 03/04/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: Yes	Repair Request: Small hole on south west of pit. It has been reported
Fence Issues: No	Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes

Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11242990	
Scheduled	Completed		
03/04/2024	03/04/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Joe Sanchez	11223909
Comments			

Last Modified By Oscar Jimenez	Created By Jorge Gutierrez
Last Modified Date 03/04/2024	Created Date 02/26/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11223909	
Scheduled	Completed		
02/26/2024	02/26/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Joe Sanchez	11197114
Comments			

Last Modified By Jorge Gutierrez	Created By Joe Sanchez
Last Modified Date 02/26/2024	Created Date 02/19/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11197114	
Scheduled	Completed		
02/19/2024	02/19/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Joe Sanchez	11186119
Comments			

Last Modified By Joe Sanchez	Created By Alfred Perez
Last Modified Date 02/19/2024	Created Date 02/12/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID
RH GALAXY REUSE PIT		074829000
Form Description		Form ID
Reuse Pit Inspection - NM		11186119
Scheduled	Completed	
02/12/2024	02/12/2024	
Status	Assigned Group	Assigned Member
Completed	NM - Water Reuse & Pipeline Team	Alfred Perez
		Previous Form
		11166356
Comments		

Last Modified By	Created By
Alfred Perez	Joe Sanchez
Last Modified Date	Created Date
02/12/2024	02/05/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11166356	
Scheduled	Completed		
02/05/2024	02/05/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Joe Sanchez	11145551
Comments			

Last Modified By Joe Sanchez	Created By Jorge Gutierrez
Last Modified Date 02/05/2024	Created Date 01/29/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11145551	
Scheduled	Completed		
01/29/2024	01/29/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	11130083
Comments			

Last Modified By Jorge Gutierrez	Created By James Kelley
Last Modified Date 01/29/2024	Created Date 01/22/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11130083	
Scheduled	Completed		
01/22/2024	01/22/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	James Kelley	11114274
Comments			

Last Modified By	Created By
James Kelley	Joel Najar
Last Modified Date	Created Date
01/22/2024	01/15/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Repair Request:
No	Yes	No	Stuck in pipe needs to be looked at

Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property	RH GALAXY REUSE PIT		Property ID	074829000
Form Description	Reuse Pit Inspection - NM		Form ID	11114274
Scheduled	01/15/2024	Completed	01/15/2024	
Status	Completed	Assigned Group	Assigned Member	Previous Form
		NM - Water Reuse & Pipeline Team	Joel Najar	11091604
Comments				

Last Modified By
Joel Najar
Last Modified Date
01/15/2024

Created By
James Kelley
Created Date
01/08/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property RH GALAXY REUSE PIT	Property ID 074829000
Form Description Reuse Pit Inspection - NM	Form ID 11091604
Scheduled 01/08/2024	Completed 01/08/2024
Status Completed	Assigned Group NM - Water Reuse & Pipeline Team
	Assigned Member Joe Sanchez
	Previous Form 11083785

Comments

Last Modified By
James Kelley
Last Modified Date
01/08/2024

Created By
Jorge Gutierrez
Created Date
01/01/2024

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11083785	
Scheduled	Completed		
01/03/2024	01/01/2024		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	11062445
Comments			

Last Modified By Jorge Gutierrez	Created By Ryan Eldridge
Last Modified Date 01/01/2024	Created Date 12/25/2023

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11062445	
Scheduled	Completed		
12/27/2023	12/25/2023		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	11043440
Comments			

Last Modified By Ryan Eldridge	Created By Ryan Eldridge
Last Modified Date 12/25/2023	Created Date 12/18/2023

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11043440	
Scheduled	Completed		
12/20/2023	12/18/2023		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	11024427
Comments			

Last Modified By Ryan Eldridge	Created By Alan Ramirez
Last Modified Date 12/18/2023	Created Date 12/11/2023

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11024427	
Scheduled	Completed		
12/13/2023	12/11/2023		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	11009952
Comments			

Last Modified By Alan Ramirez	Created By Jorge Gutierrez
Last Modified Date 12/11/2023	Created Date 12/04/2023

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:



Site ID: 33876
 Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
RH GALAXY REUSE PIT		074829000	
Form Description		Form ID	
Reuse Pit Inspection - NM		11009952	
Scheduled	Completed		
12/06/2023	12/04/2023		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	10998304
Comments			

Last Modified By Jorge Gutierrez	Created By Carlos Trevino
Last Modified Date 12/04/2023	Created Date 11/27/2023

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 412954

CONDITIONS

Operator: EOG RESOURCES INC 5509 Champions Drive Midland, TX 79706	OGRID: 7377
	Action Number: 412954
	Action Type: [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
venegas	<ul style="list-style-type: none"> 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY ID [fOY1801852871] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of January 2, 2025. The new registration/permit expiration date is January 2, 2026. • If [7377] EOG RESOURCES INC wishes to extend the registration/permit past January 2, 2026, a registration/permit extension request must be submitted to OCD no later than December 2, 2025. 	12/20/2024