

SND JAVELINA UNIT 10 15 P607 (607H, 505H, 608H, 609H, 506H) Facility ID - fJMB2232147044 (OPS Weekly Drilling inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
11/7/2024	good	yes	<1"	no	no	no	yes	no issues
11/13/2024	good	yes	<1"	no	no	no	yes	no issues
11/20/2024	good	yes	<1"	no	no	no	yes	no issues
11/27/2024	good	yes	<1"	no	no	no	yes	no issues
12/4/2024	good	yes	<1"	no	no	no	yes	no issues
12/11/2024	good	yes	<1"	no	no	no	yes	no issues
12/18/2024	good	yes	<1"	no	no	no	yes	no issues
12/25/2024	good	yes	<1"	no	no	no	yes	no issues
12/31/2024	good	yes	<1"	no	no	no	yes	no issues
1/8/2025	good	yes	<1"	no	no	no	yes	no issues
1/15/2025	good	yes	<1"	no	no	no	yes	no issues
1/22/2025	good	yes	<1"	no	no	no	yes	no issues
1/29/2025	good	yes	<1"	no	no	no	yes	no issues

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 432115

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 432115
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	2/14/2025