

SD 24 13 FED P366 (424H, 425H, 426H, 311H, 312H, 209H, 210H) Facility ID-fJMB2221639957 (Daily drilling inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
1/22/2025	good	OK	<1"	no	none	no	yes	no issues
1/29/2025	good	OK	<1"	no	none	no	yes	no issues
2/5/2025	good	OK	<1"	no	none	no	yes	no issues
2/12/2025	good	OK	<1"	no	none	no	yes	no issues
2/19/2025	good	OK	<1"	no	none	no	yes	no issues
2/26/2025	good	OK	<1"	no	none	no	yes	no issues
3/5/2025	good	OK	<1"	no	none	no	yes	no issues
3/12/2025	good	OK	<1"	no	none	no	yes	no issues
3/19/2025	good	OK	<1"	no	none	no	yes	no issues
3/26/2025	good	OK	<1"	no	none	no	yes	no issues
4/2/2025	good	OK	<1"	no	none	no	yes	no issues
4/9/2025	good	OK	<1"	no	none	no	yes	no issues
4/23/2025	good	OK	<1"	no	none	no	yes	no issues

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 455851

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 455851
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	4/25/2025