

Javelina Unit 433 (433H, 434H, 435H) Facility ID fVV2214553037(Weekly Inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
1/8/2025	yes	yes	<1"	no	no	no	yes	no issures to report
1/15/2025	yes	yes	<1"	no	no	no	yes	no issures to report
1/22/2025	yes	yes	<1"	no	no	no	yes	no issures to report
1/29/2025	yes	yes	<1"	no	no	no	yes	no issures to report
2/5/2025	yes	yes	<1"	no	no	no	yes	no issures to report
2/12/2025	yes	yes	<1"	no	no	no	yes	no issures to report
2/19/2025	yes	yes	<1"	no	no	no	yes	no issures to report
2/26/2025	yes	yes	<1"	no	no	no	yes	no issures to report
3/5/2025	yes	yes	<1"	no	no	no	yes	no issures to report
3/12/2025	yes	yes	<1"	no	no	no	yes	no issures to report
3/19/2025	yes	yes	<1"	no	no	no	yes	no issures to report
3/26/2025	yes	yes	<1"	no	no	no	yes	no issures to report

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 455844

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 455844
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	4/25/2025