Received by OCD: 8/12/2025 7:07:02 AM

Page 1

SD 24 13 FED P366 (424H, 425H, 426H, 311H, 312H, 209H, 210H) Facility ID-fJMB2221639957 (Daily drilling inspection log)										
NSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES		
/30/2025	good	OK	<1'	no	none	no	no	Fence damage on south and southwest corner		
/7/2025	good	OK	<1'	no	none	no	no	Fence damage on south and southwest corner		
14/2025	good	OK	<1'	no	none	no	no	Fence damage on south and southwest corner		
21/2025	good	OK	<1'	no	none	no	no	Fence damage on south and southwest corner		
28/2025	good	OK	<1'	no	none	no	no	Fence damage on south and southwest corner		
4/2025	good	OK	<1'	no	none	no	no	Fence damage on south and southwest corner		
11/2025	good	OK	<1'	no	none	no	no	Fence damage on south and southwest corner		
18/2025	good	OK	<1'	no	none	no	no	Fence damage on south and southwest corner		
25/2025	good	OK	<1'	no	none	no	no	Fence repaired no issuse		
2/2025	good	OK	<1'	no	none	no	no	Fence repaired no issuse		
9/2025	good	OK	<1'	no	none	no	no	no issues		
16/2025	good	OK	<1'	no	none	no	no	no issues		
23/2025	good	OK	<1'	no	none	no	no	no issues		
30/2025	good	OK	<1'	no	none	no	no	no issues		
6/2025	good	OK	<1'	no	none	no	no	no issues		

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 494592

CONDITIONS

Operator:	OGRID:
CHEVRON U S A INC	4323
6301 Deauville Blvd	Action Number:
Midland, TX 79706	494592
	Action Type:
	[C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By		Condition Date
joel.stone	None	8/15/2025