District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party				OGRID	RID		
Contact Nam	ne			Contact Telephone			
Contact emai	nail Incident # (assigned by OCD)						
Contact mail	ing address			•			
				47.	~		
			Location	of Release S	Source		
Latitude				Longitude			
			(NAD 83 in dec	cimal degrees to 5 deci	imal places)		
Site Name				Site Type			
Date Release	Discovered			API# (if ap	pplicable)		
Unit Letter	Section	Township	Range	Cou	unty		
		2225			y		
Surface Owner	r: State	☐ Federal ☐ Tr	ibal Private (/	Vame:)		
			Natura and	l Volume of	Palanca		
			Nature and	i voiume of	Release		
Crude Oil		l(s) Released (Select al Volume Release		calculations or specifi	Volume Recovered (bbls)		
Produced		Volume Release			Volume Recovered (bbls)		
			ion of dissolved c	hloride in the	Yes No		
produced water >10,000 mg/l?		moride in the					
Condensa Condensa	ate	Volume Release	d (bbls)		Volume Recovered (bbls)		
☐ Natural G	das	Volume Release	d (Mcf)		Volume Recovered (Mcf)		
Other (describe) Volume/Weight Released (provide unit		e units)	Volume/Weight Recovered (provide units)				
Cause of Rele	ease						
L							

Received by OCD: 12/10/2020 4:19:04 PM Form C-14-1 State of New Mexico Page 2 Oil Conservation Division

P	ag	e	2	o	f	á

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the responsib	le party consider this a major release?
19.15.29.7(A) NMAC?		
☐ Yes ☐ No		
If YES, was immediate no	tice given to the OCD? By whom? To whom	? When and by what means (phone, email, etc)?
,	S S	, a series of
	Initial Resp	oonse
The responsible p	party must undertake the following actions immediately un	less they could create a safety hazard that would result in injury
☐ The source of the rele	ease has been stopped.	
☐ The impacted area has	s been secured to protect human health and the	environment.
Released materials ha	we been contained via the use of berms or dike	s, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and m	anaged appropriately.
If all the actions described	d above have <u>not</u> been undertaken, explain why	<i>'</i> :
		ediation immediately after discovery of a release. If remediation orts have been successfully completed or if the release occurred
		se attach all information needed for closure evaluation.
		of my knowledge and understand that pursuant to OCD rules and tions and perform corrective actions for releases which may endanger
public health or the environn	ment. The acceptance of a C-141 report by the OCD	does not relieve the operator of liability should their operations have
addition, OCD acceptance of		o groundwater, surface water, human health or the environment. In consibility for compliance with any other federal, state, or local laws
and/or regulations.		
Printed Name		Title:
Signature:	tan Jopanne	Date:
email:		elephone:
OCD Only		
Received by:	D	ate:

		***** <i>LI</i>	QUID SPILLS	S - VOL	UME CALCULATIO	NS *****			
Locati	ion of spill:	Patron 23 F	ederal 4H	_	Date of Spill:	15-Nov-2	2020		
		If the leak/spill	is associated with	productio	n equipment, i.e wellhead	d, stuffing box,			
		flowline, tank batte	ery, production vess	el, transfer _l	pump, or storage tank place	e an "X" here:			
				Input	Data:	OIL:	WATER:		
			-		own enter the volumes here:	0.0 BBL	0.0 BBL		
If "known"		es are given, input da	ta for the followin	g "Area Ca	dculations" is optional. Th		ide the calculated vo	lumes.	
Total Surface Area	width	length	wet soil depth	oil (%)	Standing Liquid Area	width	length	liquid depth	oil (%)
Rectangle Area #1	100 ft	200 ft	X 0.10 in	0%	Standing Liquid Area Rectangle Area #1		X 0 ft X	0 in	0%
Rectangle Area #2			X 0.00 in	0%	Rectangle Area #2			0 in	0%
Rectangle Area #3			X 0.00 in	0%	Rectangle Area #3		X 0 ft X	0 in	0%
Rectangle Area #4		X 0 ft	X 0 in	0%	Rectangle Area #4		X Oft X	0 in	0%
Rectangle Area #5 Rectangle Area #6		X 0 ft X 0 ft	X 0 in X 0 in	0% 0%	Rectangle Area #5 Rectangle Area #6		X	0 in 0 in	0% 0%
Rectangle Area #7		X 0 ft	X 0 in	0%	Rectangle Area #7		X Oft X	0 in	0%
Rectangle Area #8		X 0 ft	X 2 in	0%	Rectangle Area #8			0 in	0%
				okay					
		producti	ion system leak - [DUCTION DATA REQUIRE	D			
Average Daily Production:	Oil 0	BBL Water 0	BBL 0 Ga	as (MCFD)					
		_	Ī		Total Hydrocarbon C		(1		
Did leak occur before the sepa	rator?:	YES	N/A (place an ")	(")	H2S Content in F H2S Content in				
Amount of Free Liquid					Percentage of Oil	in Free Liquid			
Recovered:	0 BBL		okay		. orocinago or on	Recovered: 09	(percentage)		
Liquid holding factor *:	<mark>0.14</mark> gal ր		following when the spill				the liquid completely fills t		
			= 0.08 gallon (gal.) liqui				soaked soil is contained by		ot).
			lly (caliche) loam = 0.14 clay loam soil = 0.14 ga				. liquid per gal. volume of som = 0.25 gal. liquid per gal		
			pam = 0.16 gal. liquid pe				l. liquid per gal. volume of s		
Total Solid/Liquid Volume:	20,000 sq.	ft. 167 cu. ft.	cu	. ft.	Total Free Liquid Volume:	sq. f	t. cu. ft.	cu.	ft.
Estimated Volumes	Spilled				Estimated Productio	n Volumes Lost			
	in Soil:	<u>H2O</u> 4.2 BBL	OIL 0.0 BB		Estimated Prod	uction Spilled:	<u>H2O</u> 0.0 BBL	<u>OIL</u> 0.0 BBL	_
	Liquid: Totals:	0.0 BBL 4.2 BBL	0.0 BB 0.0 BE		Estimated Surfa	ce Damage			
	Totals.	4.2 002	0.0 BE	,_	Surface Area:		t.		
Total Liquid Spill	Liquid:	4.2 BBL	0.00 BE	BL	Surface Area:	.4591 acre			
Recovered Volum	<u>nes</u>				Estimated Weights	and Volumes			
Estimated oil recovered:	BBL		k - okay		Saturated Soil =	18,667 lbs	167 cu. ft.	6 cu.	yds.
Estimated water recovered:	BBL	chec	k - okay		Total Liquid =	4 BBL	175 gallon	1,452 lbs	
Air Emission from flow	line leake:				Air Emission of Report	ina Requiremente:			
Volume of oil spill:	BBL				All Lillission of Report	New Mexico	Texas		
Separator gas calculated:	- MCF				HC gas release reportable?		NO		
Separator gas released:	- MCF				H2S release reportable?		NO		
Gas released from oil:	- lb								
H2S released:	- lb								
Total HC gas released:	- lb								
Total HC gas released:	- MCF	=							

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 11369

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
COG OPERATING LLC	600 W Illinois Ave	Midland, TX79701	229137	11369	C-141

OCD Reviewer	Condition
rmarcus	None