District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2035630853
District RP	
Facility ID	
Application ID	

# **Release Notification**

#### **Responsible Party**

Responsible Party Chevron U.S.A., Inc.					OGRID 4323			
Contact Name Jessica Zemen				Contact Telephone 432-530-9187				
Contact email jessicazemen@chevron.com				Incident # (assigned by OCD)				
Contact mailin		6301 Deauville B Midland, TX 797			1			
			Location	n of R	elease So	ource		
Latitude 32.31	136				Longitude -			
			(NAD 83 in 6	decimal de	grees to 5 decin	mal places)		
Site Name: Cu	ulebra Bluf	f West CTB			Site Type:	Tank Battery		
Date Release I	Discovered	12/13/2020			API# (if app	plicable): N/A		
Unit Letter	Section	Township	Range		Coun	nty		
В	15	23S	28E	Eddy				
	Materia	l(s) Released (Select a	Nature ar			Release  : justification for the volumes provided below)		
Crude Oil		Volume Release				Volume Recovered (bbls)		
Produced V	Water	Volume Release	ed (bbls)			Volume Recovered (bbls)		
		Is the concentra produced water	tion of dissolved >10,000 mg/l?	l chloride	e in the	☐ Yes ☐ No		
Condensat	e	Volume Release	ed (bbls)			Volume Recovered (bbls)		
Natural Ga	ıs	Volume Release	ed (Mcf) 66 MCI	F		Volume Recovered (Mcf) 0 MCF		
Other (describe) Volume/Weight Released (provide units					)	Volume/Weight Recovered (provide units)		
Cause of Rele A compressor		due to a fischer va	alve malfunction.	. This sh	utdown resul	lted in a flaring event.		

- 73			~		•
···	an	0	•	A 1	
- 1	uz	С.	4	vi	
	- 0	_			

Incident ID	NAPP2035630853
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?
release as defined by 19.15.29.7(A) NMAC?	N/A
☐ Yes ⊠ No	
If VEC was immediate n	postion sixten to the OCD2 Dr. whom? To whom? When and by what means (phone amail ata)?
II YES, was immediate no	notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
	Initial Response
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.
☐ The impacted area ha	as been secured to protect human health and the environment.
Released materials ha	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.
☐ All free liquids and re	recoverable materials have been removed and managed appropriately.
If all the actions described	ed above have <u>not</u> been undertaken, explain why:
Dalaca danata dalama	
Released material was no	ot a liquid therefore the fourth option does not apply.
has begun, please attach	MAC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurrent area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
	ormation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and
	required to report and/or file certain release notifications and perform corrective actions for releases which may endanger ment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have
failed to adequately investig	gate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
and/or regulations.	if a C-141 report does not reneve the operator of responsibility for comphance with any other rederal, state, or local laws
Printed Name:Jess	sica Zemen Title:Lead Environmental Specialist, Field Support
0	$\sim N_{\odot}$
Simulation	iva X Zemen Date:12/20/2020
Signature:/	Date:12/20/2020
email:jessicazen	men@chevron.com Telephone:432-530-9187
OCD Only	
Received by:Ramon	na Marcus Date: 12/23/2020

	Page 3 of	5
Incident ID	NAPP2035630853	
District RP		
Facility ID		
Application ID		

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.  N/A due to release report is a flare event.
☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
☐ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
Description of remediation activities
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.  Printed Name:
OCD Only
Received by: Ramona Marcus Date: 12/23/2020
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.
Closure Approved by: Date: 12/31/2020
Printed Name: Cristina Eads Title: Environmental Specialist

Received by OCD: 12/22/2020 9:43:26 AM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 of
Incident ID	NAPP2035630853
District RP	
Facility ID	
Application ID	

3. Time o	3. Time of Event					1. Vented   2. Calculating Volumetric Release Rate for YRU Releases Incapable of				3. Gaseous Volumetric Release			
Date discor	Time of Discover Schedu  Activity	start of	Time of Start of Even Schedu Activity	Date of end of even Schedt	actual end of event or Schedule	Duration of F	Vent or F	Is Volume Metered, Estimated or Otherw Known?	Daily Product  (barrels o  / day	Site-specific GOR Available?	Site-specfic GOR (scf gas / b oil)	Value <b>▼</b>	Units
12/13/2020	23:45:00	12/13/2020	23:45:00	12/13/2020	23:59:00	0.23	Flare					66	msof/event

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

### **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 12902

#### **CONDITIONS OF APPROVAL**

Operator:			OGRID:	Action Number:	Action Type:
CHEVRON USA INC	6301 Deauville Blvd	Midland, TX79706	4323	12902	C-141

OCD Reviewer	Condition
ceads	None