

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2036459251
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	Legacy Reserves, LP	OGRID	240974
Contact Name	Brian Cunningham	Contact Telephone	432-234-9450
Contact email	bcunningham@legacyp.com	Incident # (assigned by OCD)	NAPP2036459251
Contact mailing address	303 West Wall Street, Suite 1300 Midland, TX 79701		

Location of Release Source

Latitude 32.77837 Longitude -103.79574
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Walker Federal 1 & 2 Battery	Site Type	Battery
Date Release Discovered	12/21/2020	API# (if applicable)	30-025-00841 (Closest Well)

Unit Letter	Section	Township	Range	County
E	5	18S	32E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 19	Volume Recovered (bbls) 0
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release
Illegal dump. The release affected an area of the battery pad and adjacent pasture measuring approximately 2,600 square feet.


State of New Mexico
Oil Conservation Division

Incident ID	NAPP2036459251
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Brian Cunningham</u> Signature: <u></u> email: <u>bcunningham@legacylp.com</u>	Title: <u>Production Foreman</u> Date: <u>1/4/2021</u> Telephone: <u>432-234-9450</u>
<u>OCD Only</u> Received by: _____ Date: _____	



Volume Calculation

ID	Area (Ft ²)	Depth (Ft)	%Porosity/ Saturation	Volume (Ft ³)	Volume (bbls)	
Area #1	2,600	0.16	0.25	104.00	19.0	
Volume of Liquid Remaining in Soil:					19	bbls
Volume Recovered:					0	bbls
Total Volume:					19	bbls
Oil (Approximate)					100.0	%
Volume of Oil Released:					19.0	bbls
Volume of Water Released:					0.0	bbls
Volume of Oil Recovered:					0.00	
Volume of Water Recovered:					0.0	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 14516

CONDITIONS OF APPROVAL

Operator: LEGACY RESERVES OPERATING, LP Suite 1800 Midland, TX79701	303 W Wall	OGRID: 240974	Action Number: 14516	Action Type: C-141
OCD Reviewer rmarcus	Condition None			