District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2101458051
District RP	
Facility ID	
Application ID	

# **Release Notification**

## **Responsible Party**

Responsible Party EOG Resources		OGRID 7377						
Contact Name Todd Wells		Contact Telephone (432) 686-3613						
Contact email Todd_Wells@eogresources.com		Incident #	t # (assigned by OCD)					
Contact mail 79706	ing address	5509 Champions	Drive Midland,	TX				
			Location	n of R	Release S	Source		
Latitude 32.230421° Longitude -103.561631° (NAD 83 in decimal degrees to 5 decimal places)								
Site Name N	eptune 10 S	tate CTB			Site Type	Site Type CTB		
Date Release Discovered 12/19/20 A		API# (if ap	applicable)					
Unit Letter	ter Section Township Range Cou		ounty					
K	10	24S	33E	Lea				
	Surface Owner: State Federal Tribal Private (Name:)  Nature and Volume of Release  Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)							
Crude Oil Volume Released (bbls)			Volume Recovered (bbls)					
Produced	Water	Volume Releas	ed (bbls) 5			Volume Recovered (bbls) 0		
Is the concentration of dissolved chloride in produced water >10,000 mg/l?		e in the	⊠ Yes □ No					
Condensa	Condensate Volume Released (bbls)			Volume Recovered (bbls)				
Natural Gas Volume Released (Mcf)			Volume Recovered (Mcf)					
Other (describe) Volume/Weight Released (provide units)		)	Volume/Weight Recovered (provide units)					
						water being released from the failed seal on the transfer the pad and 0 bbls recovered.		

Received by OCD: 1/15/2021 1:12:27 PM Form C-141 State of New Mexico Page 2 Oil Conservation Division

	Page 2 of	f 7
Incident ID	NAPP2101458051	
District RP		
Facility ID		
Application ID		

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?		
☐ Yes ⊠ No			
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?		
	Initial Response		
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury		
The source of the rele	ease has been stopped.		
The impacted area ha	s been secured to protect human health and the environment.		
Released materials ha	we been contained via the use of berms or dikes, absorbent pads, or other containment devices.		
All free liquids and recoverable materials have been removed and managed appropriately.			
	d above have <u>not</u> been undertaken, explain why:		
has begun, please attach within a lined containment	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.		
regulations all operators are public health or the environr failed to adequately investige	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have atteand remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws		
Printed Name: Todd	Wells Title: Environmental Specialist		
Signature: Todd	<i>Wells</i> Date: <u>1-15-21</u>		
email:Todd_Wells@	<u></u>		
OCD Only			
Received by:	Date:		

Incident ID NAPP2101458051

District RP

Facility ID

Application ID

## **Site Assessment/Characterization**

This information must be provided to the appropriate district of fice no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)		
Did this release impact groundwater or surface water?	☐ Yes ☐ No		
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No		
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No		
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No		
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No		
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No		
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No		
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No		
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No		
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No		
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No		
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?	☐ Yes ☐ No		
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.			
Characterization Report Checklist: Each of the following items must be included in the report.			
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.  Field data  Data table of soil contaminant concentration data  Depth to water determination  Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release  Boring or excavation logs  Photographs including date and GIS information  Topographic/Aerial maps  Laboratory data including chain of custody			

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 1/15/2021 1:12:27 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 of	7
Incident ID	NAPP2101458051	
District RP		
Facility ID		
Application ID		

I hereby certify that the information given above is true and complete to the regulations all operators are required to report and/or file certain release not public health or the environment. The acceptance of a C-141 report by the failed to adequately investigate and remediate contamination that pose a threaddition, OCD acceptance of a C-141 report does not relieve the operator of and/or regulations.	tifications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have reat to groundwater, surface water, human health or the environment. In
Printed Name:	
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:

Incident ID NAPP2101458051 District RP Facility ID Application ID

# **Remediation Plan**

Remediation Plan Checklist: Each of the following items must b	e included in the plan.			
<ul> <li>□ Detailed description of proposed remediation technique</li> <li>□ Scaled sitemap with GPS coordinates showing delineation points</li> <li>□ Estimated volume of material to be remediated</li> <li>□ Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC</li> <li>□ Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required)</li> </ul>				
Deferral Requests Only: Each of the following items must be con-	nfirmed as part of any request for deferral of remediation.			
Contamination must be in areas immediately under or around predeconstruction.	roduction equipment where remediation could cause a major facility			
Extents of contamination must be fully delineated.				
Contamination does not cause an imminent risk to human health	n, the environment, or groundwater.			
	e and remediate contamination that pose a threat to groundwater, acceptance of a C-141 report does not relieve the operator of			
Printed Name:	Title:			
Signature:	Date:			
email:	Telephone:			
OCD Only				
Received by:	Date:			
☐ Approved ☐ Approved with Attached Conditions of	Approval Denied Deferral Approved			
Signature:	Date:			

Received by OCD: 1/15/2021 1:12:27 PM Form C-141 State of New Mexico
Page 6 Oil Conservation Division

Incident ID NAPP2101458051

District RP
Facility ID

Application ID

# Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

☐ A scaled site and sampling diagram as described in 19.15.29.1	1 NMAC	
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
☐ Laboratory analyses of final sampling (Note: appropriate ODC	C District office must be notified 2 days prior to final sampling)	
☐ Description of remediation activities		
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of	nediate contamination that pose a threat to groundwater, surface water, a C-141 report does not relieve the operator of responsibility for tions. The responsible party acknowledges they must substantially nditions that existed prior to the release or their final land use in	
Printed Name:		
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.	
Closure Approved by:	Date:	
Printed Name:	Title:	

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 13379

#### **CONDITIONS OF APPROVAL**

Operator:					Action Type:
EOG RESOURCES INC	P.O. Box 2267	Midland, TX79702	7377	13379	C-141

OCD Reviewer	Condition
rmarcus	None