Page 1 of 5

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

NAPP2107751622
_
•

## **Release Notification**

## **Responsible Party**

Responsible 1	Responsible Party: ETC Texas Pipeline, Ltd. OGF		OGRID: 3	371183		
Contact Name: Carolyn Blackaller		Contact To	Contact Telephone: (432) 203-8920			
Contact email: Carolyn.blackaller@energytransfer.com		Incident #	(assigned by OCD)	)		
Contact mail	Contact mailing address: 600 N. Marienfeld St., Suite 700, Midland, TX 79701		dland, TX 79701			
	10665		Location o	of Release S		3
atitude <u> 32.47</u>	18665		(NAD 83 in decin	Longitude <sub>.</sub> mal degrees to 5 decir	-103.160681 mal places)	
Site Name: MF Pipeline Site Type: Pipeline						
Date Release	Discovered:	3/5/2021	7	API# (if app	plicable)	
Unit Letter	Section	Township	Range	Cour	ntv	7
P	S16	T21S	R37E	Lea	•	1
	2		2 22			1
Crude Oil	Water	Volume Release Volume Release Is the concentrat produced water	d (bbls) d (bbls) ion of dissolved chi >10,000 mg/l?		Volume Reco	overed (bbls)
Condensate Volume Released (bbls)			Volume Reco			
X Natural Gas Volume Released (Mcf): 68 mcf		24.5		overed (Mcf): 0 mcf		
Otner (de:	Other (describe) Volume/Weight Released (provide units)		units)	Volume/wei	ght Recovered (provide units)	
Cause of Rele	ease: The rel	ease was attribute	d to a pipeline purg	ge in order to shut	t-in the line segu	nent for repair.

Form C-141 Page 2

# State of New Mexico Oil Conservation Division

Incident ID	NAPP2107751622
District RP	
Facility ID	77 MACHE W. ACC. 11 - 12
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the respon	nsible party consider this a major release?
If YES, was immediate no	otice given to the OCD? By whom? To who	om? When and by what means (phone, email, etc)?
	Initial R	esponse
The responsible	party must undertake the following actions immediated	ly unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.	
The impacted area ha	as been secured to protect human health and	the environment.
X Released materials ha	ave been contained via the use of berms or	dikes, absorbent pads, or other containment devices.
X All free liquids and r	ecoverable materials have been removed an	d managed appropriately.
If all the actions describe	d above have <u>not</u> been undertaken, explain	why:
has begun, please attach	a narrative of actions to date. If remedial	remediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred blease attach all information needed for closure evaluation.
		best of my knowledge and understand that pursuant to OCD rules and fications and perform corrective actions for releases which may endanger
public health or the environ	ment. The acceptance of a C-141 report by the C	CD does not relieve the operator of liability should their operations have
addition, OCD acceptance o		eat to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws
and/or regulations.		
Printed Name: Carolyn B	lackaller	Title: Sr. Environmental Specialist
Signature:	Society	Date: 3/18/2021
email: <u>Carolyn, blackaller</u>	r@energytransfer.com	Telephone: (432) 203-8920
OCD Only	<i>∓</i>	
Received by: Cristina E	Eads	Date:03/18/2021

50	,
S)	
Form C-141	
Page 6	

# State of New Mexico Oil Conservation Division

Incident ID	NAPP2107751622
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a partative of the remedial activities. Refer to 19.15.29.12 NMAC.

	tive of the remedial activities. Refer to 19.15.29.12 NMAC.
Closure Report Attachment Checklist: Each of the following	llowing items must be included in the closure report.
A scaled site and sampling diagram as described in 1	9.15.29.11 NMAC
Photographs of the remediated site prior to backfill of must be notified 2 days prior to liner inspection)	or photos of the liner integrity if applicable (Note: appropriate OCD District office
☐ Laboratory analyses of final sampling (Note: approp	riate ODC District office must be notified 2 days prior to final sampling)
Description of remediation activities	
and regulations all operators are required to report and/or is may endanger public health or the environment. The accept should their operations have failed to adequately investigate human health or the environment. In addition, OCD accept compliance with any other federal, state, or local laws and restore, reclaim, and re-vegetate the impacted surface area	In to the OCD when reclamation and re-vegetation are complete.
Printed Name: Carolyn Blackaller	Title: Sr. Environmental Specialist
Signature: Carol 1800 and account	Date: <u>3/18/2021</u>
email: Carolyn.blackaller@energytransfer.com	Telephone: (432) 203-8920
OCD Only	
Received by: Cristina Eads	Date:03/18/2021
	ible party of liability should their operations have failed to adequately investigate and r, surface water, human health, or the environment nor does not relieve the responsible laws and/or regulations.
Closure Approved by:	Date:04/01/2021 Title: _Environmental Specialist
Printed Name: Cristina Eads	Title: Environmental Specialist
18/2	
<u>;;</u>	
<u> </u>	
erved by OCD: 3/18/2	n de la companya de

Received by OCD: 3/18/2021 2:22:44 PM

# Released to Imaging: 4/1/2021 9:18:16 AM

### **Purge Time Calculation**

Diameter (in inches)	16	RECOMMENDED PURGE TIME	45	
Length (in miles)	1.000	ACTUAL PURGE TIME (in min)	20	
Pipeline Pressure (psia)	15	VOLUME OF PURGE GAS (Mcf)	68	Volume of Purge Gas = (Purge time)*(Blowoff CoE)*(Pipeline Pressure)/60
Blowdown Size (valve)	4			
K (Blowoff Coefficient)	13.50			

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

### **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 21283

### **CONDITIONS OF APPROVAL**

Operator:		OGRID:	Action Number:	Action Type:
ETC TEXAS PIPELINE, LTD	. 8111 Westchester Drive	371183	21283	C-141
Suite 600 Dallas, TX75225				

OCD Reviewer	Condition
ceads	None