District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Incident ID	NAPP2108232108
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party OCCIDENTAL PERMIAN LTD.	OGRID 157984	
Contact Name Richard Alvarado	Contact Telephone 432-209-2659	
Contact email <u>Richard Alvarado2@oxy.com</u>	Incident # (assigned by OCD)	
Contact mailing address 1017 W. Stanolind Road	1	

Location of Release Source

Latitude		
Site Name SHURCF	Site Type OIL AND GAS PRODUCTION FACILITY	
Date Release Discovered 03/22/2021	API# (if applicable) N/A	

Unit Letter	Section	Township	Range	County
F	9	19-S	38-E	LEA

Surface Owner: X State Federal Tribal Private (Name: ______

Nature and Volume of Release

Materi	ial(s) Released (Select all that apply and attach calculations or specific	c justification for the volumes provided below)
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf) 1590	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

THE SOUTH PLANT EXPERIENCED A FLARING EVENT WHEN A LARGE DUST STORM PASSED THROUGH AND SHUT DOWN ALL COMPRESSORS. THE POWER ISSUE THAT CAUSED THE SHUTDOWN WAS "POWER UNBALANCE IN THE MCC".

Oil Conservation Division

	Page 2	? of 5
Incident ID	NAPP2108232108	
District RP		
Facility ID		Ī
Application ID		

If YES, for what reason(s) does the responsible party consider this a major release?
otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \square The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Restarted Unit

STEPS 2-4 WAS NOT APPLICABLE

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name:Richard Alvarado	Title:HES Specialist Date:03/23/2021
email:Richard_Alvarado2@oxy.com	Telephone:432-209-2659
OCD Only	
Received by: Ramona Marcus	Date: 4/16/2021

Page 6

59	Page 3 of
Incident ID	NAPP2108232108
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following ite	rms must be included in the closure report.	
A scaled site and sampling diagram as described in 19.15.29.11	NMAC	
Photographs of the remediated site prior to backfill or photos of must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office	
Laboratory analyses of final sampling (Note: appropriate ODC	District office must be notified 2 days prior to final sampling)	
Description of remediation activities		
<u></u>		
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of a should their operations have failed to adequately investigate and rem human health or the environment. In addition, OCD acceptance of a compliance with any other federal, state, or local laws and/or regulati restore, reclaim, and re-vegetate the impacted surface area to the com accordance with 19.15.29.13 NMAC including notification to the OC Printed Name:	ediate contamination that pose a threat to groundwater, surface water, C-141 report does not relieve the operator of responsibility for ions. The responsible party acknowledges they must substantially ditions that existed prior to the release or their final land use in	
OCD Only Received by: Ramona Marcus	Date: 4/16/2021	
	Date:	
	f liability should their operations have failed to adequately investigate and ater, human health, or the environment nor does not relieve the responsible regulations.	
Closure Approved by: Justundes	Date:04/23/2021	
Printed Name:Cristina Eads	Title:Environmental Specialist	

NAPP2108232108

OCCIDENTAL PERMIAN LTD.

Event ID:	111639	Reporting Employee:	RICHARD ALVARADO
Lease Name:	SOUTH HOBBS UNIT RCF	Account Number:	33207
Equipment:	Plant Inlet	NSR Permit Number:	5418-R2
EPN:	RCF - FLARE - MALF	Title V Permit Number:	
EPN Name	RCF flare - Malfunctions	Reg Lease Number:	
Flare Point:	Plant Inlet		

Explanation of the Cause:

THE SOUTH PLANT EXPERIENCED A FLARING EVENT WHEN A LARGE DUST STORM PASSED THROUGH AND SHUT DOWN ALL COMPRESSORS. THE POWER ISSUE THAT CAUSED THE SHUTDOWN WAS "POWER UNBALANCE IN THE MCC".

Corrective Actions Taken to Minimize Emissions:

OPERATIONS RESET ALL COMPRESSORS AND PUT THE UNITS BACK ONLINE AS QUICKLY AS POSSIBLE.

Actions taken to prevent recurrence:

OPERATIONS RESET ALL COMPRESSORS AND PUT THE UNITS BACK ONLINE AS QUICKLY AS POSSIBLE.

Emission Start Date	Emission End Date	Duration
3/22/2021 2:53:00 PM	3/22/2021 3:21:00 PM	0:28 hh:mm

NMED

Pollutant	Duration (hh:mm)	Avging Period	Excess	Number of Exceedances Limit	Permit	Average Emission		Total	Tons Per Year		
			Emission		Rate	Rate Pounds		Total	Next Drop off Date	Date Permit Exceeded	
CO	0:28	1	0 LBS	0	448.60	510.25	LBS/HR	238.11	0.11906	5/14/2021	
H2S	0:28	1	0 LBS	0	38.90	33.93	LBS/HR	15.83	0.007918	5/14/2021	
NOX	0:28	1	0 LBS	0	79.30	59.S1	LBS/HR	27.77	0.013886	5/14/2021	
SO2	0:28	1	0 LBS	0	3659.00	3130.06	LBS/HR	1460.69	0.730349	5/14/2021	
VOC	0:28	1	0 LBS	0	520.30	341.2	LBS/HR	159.22	0.079615	5/14/2021	

Reporting Status: Non-Reportable

NMOCD

Flare Stream Total Total MCF		EPN	Latitude	Longitude	Reporting Status	
	1410 MCF	1590 MCF	RCF flare - Malfunctions	32"40'40.890	103°9'35.360	Major Release

LEPC

Total MCF	H2S %	Unit Letter Se	Section	Township		Range		
1590	0.626	ε	09	19	S	39	Ê	
Pollutant	Emission rate Reg				Reporta	portable Qty		
SO2	1460.69 LBS/DAY			500 LBS/DAY				
SO2	1460.69 LBS/DAY 500			00 LBS	DAY			
SO2	1460.69 LBS/DAY			500 LBS/DAY				

Reporting Status: Reportable

Emissions Calculations:

NOx = MCF flared x NOx factor from RG-109 x BTU/scf x 1000 scf/MCF x MMBTU/1000000 BTU CO = MCF flared x CO factor from RG-109 x BTU/scf x 1000 scf/MCF x MMBTU/1000000 BTU Gas was flared to reduce the hydrocarbon and/or H2S emissions to the atmosphere. NMNE NG = MCF flared x 50 lb/mole x mole/.379 MCF x mol % NMNE NG x 0.02 NMNE NG % = 100% - Methane % - Ethane % - Carbon Dioxide % - Nitrogen % H2S = MCF flared x 34 lb/mole x mole/.379 MCF x mol % H2S/100 x 0.02 SO2 = MCF flared x 64 lb/mole x mole/.379 MCF x mol % H2S/100 x 0.98 Event Type Malfunction Malfunction Malfunction District I 1625 N. French Dr., Hobbs, NM 88240

District II

District IV

Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410 CONDITIONS

Action 21647

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS OF APPROVAL

Operator:				OGRID:	Action Number:	Action Type:
OCCIDENTAL PERMIAN LTD	P.O. Box 4294	Houston, TX772104294		157984	21647	C-141
OCD Reviewer			Condition			
ceads			None			