District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

)

Page 1 of 4

Incident ID	NAPP2108544357
District RP	
Facility ID	
Application ID	

# **Release Notification**

### **Responsible Party**

Responsible Party	OGRID
Contact Name	Contact Telephone
Contact email	Incident # (assigned by OCD)
Contact mailing address	

#### **Location of Release Source**

Longitude

Latitude	

Site Name	Site Type
Date Release Discovered	API# (if applicable)

(NAD 83 in decimal degrees to 5 decimal places)

Unit Letter	Section	Township	Range	County

Surface Owner: State Federal Tribal Private (Name:

#### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)				
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)		
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)		
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	Yes No		
Condensate	Volume Released (bbls)	Volume Recovered (bbls)		
🗌 Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)		
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)		
causir	attery VRU shut down causing residual conc ng a small fire. The release was onto permea een retained for remediation activities.			

	Page 2 of
Incident ID	NAPP2108544357
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?
🗌 Yes 🗌 No	
If YES, was immediate ne	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

#### **Initial Response**

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name:	Title:
Signature: african Dafris	Date:
email:	Telephone:
OCD Only	
Received by: Ramona Marcus	Date: <u>5/4/2021</u>

Location:	Thriller Battery			
Spill Date:	3/19/2021			
	Area 1			
Approximate A	rea =	1236.00	sq. ft.	
Average Satura	ntion (or depth) of spill =	0.50	inches	
Average Porosity Factor = 0.03				
	VOLUME OF LEAK			
Total Condensa	ate =	0.28	bbls	
TOTAL VOLUME OF LEAK				
<b>Total Condens</b>	ate =	0.28	bbls	
TOTAL VOLUME RECOVERED				
Total Condens	ate =	0.00	bbls	

CONDITIONS

Page 4 of 4

.

Action 23791

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 <u>District IV</u> 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

#### CONDITIONS OF APPROVAL

Operator: XTO ENERGY, INC 6401 Holiday Hill Road	OGRID: 5380	Action Number: 23791	Action Type: C-141	
ATO ENERGIF, INC 6401 Holiday Fill Road	5500	23/91	0-141	
Building #5 Midland, TX79707				
OCD Reviewer	Condition			
rmarcus	None	None		