

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2110232030
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Marathon Oil Permian LLC	OGRID 372098
Contact Name Melodie Sanjari	Contact Telephone 575-988-8753
Contact email msanjari@marathonoil.com	Incident # (assigned by OCD)
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 8220	

Location of Release Source

Latitude 32.26979799

Longitude -104.12062402
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: HERMES FEE 23 28 30 TB #009H	Site Type: Oil & Gas Facility
Date Release Discovered: 4/11/2021	API# (if applicable) 30-015-44606

Unit Letter	Section	Township	Range	County
P	30	23S	28E	Eddy

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 25	Volume Recovered (bbls) 25
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Incorrect installation of a Victaulic valve off of the 9H separator resulted in the release of approx.. 25 bbl. of produced water inside of the lined, secondary containment. Repairs were made and all standing fluid was recovered.

Incident ID	nAPP2110232030
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Volume
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? NOR submitted 4/12/2021	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Melodie Sanjari</u>	Title: <u>Environmental Professional</u>
Signature: <u>Melodie Sanjari</u>	Date: 4/12/2021
email: <u>msanjari@marathonoil.com</u>	Telephone: <u>575-988-8753</u>
<u>OCD Only</u> Received by: _____ Date: _____	

Transportation Services, Inc.
accounting@agavetransportation.com

910-K E. Redd Rd. # 443 • El Paso, TX 79912

M 19846

BILL TO

MARATHON OIL CO.

DISPOSAL
NUMBER

1194.20902

DATE

4.11

COST
CENTER

ORDERED BY

DELIVERED
FROM:

TO:

LOCATION
LEASE

TRUCK OR
UNIT NO.:

Hermes Fee 23 28 30 wa 10t

AMOUNT
HAULED:

25

GAUGE: TOP:

☐ RIG

☒ BATTERY

☐ COMPLETION

☐ FLOW BACK

TIMES

DESCRIPTION

BOTTOM:

BATTERY

ARRIVE

8:00

☒ A.M.
☐ P.M.

DEPART

7:00

☐ A.M.
☒ P.M.

DISPOSAL

ARRIVE

☐ A.M.
☐ P.M.

DEPART

☐ A.M.
☐ P.M.

Clean water spill on
Battery Pool

API # 30.015.44607

BILLING

RATE

AMOUNT

11 Hrs.

F/W

B/W

P/W

CRI

SUB TOTAL

TAX

TOTAL

Thank You!

DRIVER PRINT NAME

COMPANY MAN PRINT NAME

DRIVER SIGNATURE

COMPANY MAN SIGNATURE

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 23820

CONDITIONS OF APPROVAL

Operator: MARATHON OIL PERMIAN LLC Permian Regulatory Team	5555 San Felipe St. Houston, TX77056	OGRID: 372098	Action Number: 23820	Action Type: C-141
OCD Reviewer rmarcus	Condition None			