

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

| | |
|----------------|----------------|
| Incident ID | nAPP2110654878 |
| District RP | |
| Facility ID | |
| Application ID | |

Release Notification

Responsible Party

| | |
|--|--------------------------------|
| Responsible Party Hilcorp Energy Company | OGRID 372171 |
| Contact Name Mitch Killough | Contact Telephone 713-757-5247 |
| Contact email mkillough@hilcorp.com | Incident # nAPP2110654878 |
| Contact mailing address 1111 Travis Street, Houston, Texas 77002 | |

Location of Release Source

Latitude 36.9598312 _____ Longitude -108.0700531 _____
(NAD 83 in decimal degrees to 5 decimal places)

| | |
|---|-------------------|
| Site Name Moore LS 2A | Site Type Well |
| Date Release Discovered 4/1/2021 @ 11:00am (MT) | API# 30-045-22827 |

| Unit Letter | Section | Township | Range | County |
|-------------|---------|----------|-------|----------|
| E | 26 | 32N | 12W | San Juan |

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

| | | |
|--|--|--|
| <input type="checkbox"/> Crude Oil | Volume Released (bbls) | Volume Recovered (bbls) |
| <input type="checkbox"/> Produced Water | Volume Released (bbls) | Volume Recovered (bbls) |
| | Is the concentration of dissolved chloride in the produced water >10,000 mg/l? | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| <input checked="" type="checkbox"/> Condensate | Volume Released (bbls) 20 bbls | Volume Recovered (bbls) 0 bbls |
| <input type="checkbox"/> Natural Gas | Volume Released (Mcf) | Volume Recovered (Mcf) |
| <input type="checkbox"/> Other (describe) | Volume/Weight Released (provide units) | Volume/Weight Recovered (provide units) |

Cause of Release


A release of approximately 20 bbls condensate was released from a hole in the production storage tank that developed due to corrosion. The spill amount was determined by operator's monthly tank gauging data. The released fluids remained on location and inside the bermed area. 0 bbls were recovered. OCD will be notified 48 hours prior to sampling.

| | |
|----------------|----------------|
| Incident ID | nAPP2110654878 |
| District RP | |
| Facility ID | |
| Application ID | |

| | |
|---|--|
| Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, for what reason(s) does the responsible party consider this a major release? |
| If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? | |

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

| |
|--|
| <input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately. |
| If all the actions described above have <u>not</u> been undertaken, explain why: |
| Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation. |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. |
| Printed Name: <u>Mitch Killough</u> Title: <u>Environmental Specialist</u> |
| Signature: <u></u> Date: <u>4/16/2021</u> |
| email: <u>mkillough@hilcorp.com</u> Telephone: <u>713-757-5247</u> |
| <u>OCD Only</u> |
| Received by: <u>Ramona Marcus</u> Date: <u>5/9/2021</u> |

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 24389

CONDITIONS OF APPROVAL

| | | | | | |
|--|--|--|--------|----------------|--------------|
| Operator: | | | OGRID: | Action Number: | Action Type: |
| HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX77002 | | | 372171 | 24389 | C-141 |
| OCD Reviewer | Condition | | | | |
| marcus | When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141 | | | | |