District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2111233052
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party EOG Resources, Inc.				OGRID 73	377		
Contact Name Chase Settle			Contact Telephone 575-748-1471				
Contact email Chase_Settle@eogresources.com			Incident #	(assigned by OCD)			
Contact mail	ing address	104 S. 4th Str	eet, Artesia,	NM 88	8210		
			Location	ı of R	telease So	ource	
Latitude 32.67384				Longitude .	-104.56533		
			(NAD 83 in d	lecimal de	grees to 5 decim	nal places)	
Site Name D	avis NC (Com #2			Site Type	Batterv	
		04/08/2021				licable) 30-015-23	
			_				<u> </u>
Unit Letter	Section	Township	Range		Coun	ty	
L	11	19S	24E	Edd	у		
Symfo a a Oyyma	Ctoto	Federal T	wihal Duivata	(Name)			,
Surface Owne	r: State	rederal 11	ribai 🔽 Private	(wame:)
			Nature an	d Vo	lume of F	Release	
	Materia	1(c) Released (Select a	ll that annly and attac	sh calculat	tions or specific	justification for the vol	lumes provided below)
Crude Oi			ed (bbls) Unknov		nons or specific	Volume Recover	
Produced	Water	Volume Release				Volume Recover	red (bbls)
	Is the concentration of dissolved chlorid		chloride	e in the	Yes No		
	. 4 .	produced water				W. L. D.	. 1/111
Condensa		Volume Released (bbls)			Volume Recover		
Natural C		Volume Released (Mcf)			Volume Recover		
Other (describe) Volume/Weight Released (provide units))	Volume/Weight	Recovered (provide units)			
Cause of Rel	^{ease} Histor unkno	ical impacts dis	scovered durin	ig the I	P&A of the	battery. Relea	se volume and date are
	unkno	WII.					
1							

77		-		-
Pag	0	7	0	t '
1 42	C	4	\boldsymbol{v}	Ι.

Incident ID	NAPP2111233052
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☐ Yes ☑ No	If YES, for what reason(s) does the respon	sible party consider this a major release?
ICVEC i 1:-4	-tiitthOCD9 December 9 To see	2 W/L 1 L (L
II YES, was immediate no	once given to the OCD? By whom? To wr	om? When and by what means (phone, email, etc)?
	Initial Ro	esponse
The responsible	party must undertake the following actions immediatel	vunless they could create a safety hazard that would result in injury
✓ The source of the rele	ease has been stopped.	
☑ The impacted area ha	s been secured to protect human health and	the environment.
✓ Released materials has	we been contained via the use of berms or c	ikes, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and	l managed appropriately.
		emediation immediately after discovery of a release. If remediation
		efforts have been successfully completed or if the release occurred lease attach all information needed for closure evaluation.
regulations all operators are public health or the environr failed to adequately investig	required to report and/or file certain release noti ment. The acceptance of a C-141 report by the C ate and remediate contamination that pose a thre	pest of my knowledge and understand that pursuant to OCD rules and fications and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws
Printed Name: Chase	Settle	Title: Rep Safety & Environmental Sr
Signature: Chan	ettle	Date: 04/21/2021
email: Chase_Settle	@eogresources.com	Telephone: <u>575-748-1471</u>
OCD Only		
Received by: Ramona	Marcus	Date:

Received by OCD: 4/22/2021 9:30:52 AM Form C-141 State of New Mexico
Page 3 Oil Conservation Division

	Page 3 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)	
Did this release impact groundwater or surface water?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No	
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	Yes No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No	
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No	
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No	
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No	
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No	
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No	
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ☐ No	
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.		
Characterization Report Checklist: Each of the following items must be included in the report.		
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody		

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 4/22/2021 9:30:52 AM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 of	^e 7
Incident ID		
District RP		
Facility ID		
Application ID		

I hereby certify that the information given above is true and complete to the regulations all operators are required to report and/or file certain release not public health or the environment. The acceptance of a C-141 report by the failed to adequately investigate and remediate contamination that pose a thr addition, OCD acceptance of a C-141 report does not relieve the operator of and/or regulations.	ifications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have eat to groundwater, surface water, human health or the environment. In
Printed Name:	_ Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:

Received by OCD: 4/22/2021 9:30:52 AM Form C-141 State of New Mexico Page 5 Oil Conservation Division

	Page 5 of	7
Incident ID		
District RP		
Facility ID		
Application ID		

Remediation Plan

D. H. J. DI. Cl. III. J. T. J. C.J. C.H. J. J.	
Remediation Plan Checklist: Each of the following items must be	pe included in the plan.
 □ Detailed description of proposed remediation technique □ Scaled sitemap with GPS coordinates showing delineation poin □ Estimated volume of material to be remediated □ Closure criteria is to Table 1 specifications subject to 19.15.29 □ Proposed schedule for remediation (note if remediation plan ting) 	12(C)(4) NMAC
<u>Deferral Requests Only</u> : Each of the following items must be co	nfirmed as part of any request for deferral of remediation.
Contamination must be in areas immediately under or around p deconstruction.	production equipment where remediation could cause a major facility
Extents of contamination must be fully delineated.	
Contamination does not cause an imminent risk to human healt	h, the environment, or groundwater.
	te and remediate contamination that pose a threat to groundwater, acceptance of a C-141 report does not relieve the operator of
Printed Name:	Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:
Approved	Approval Denied Deferral Approved
Signature:	<u>Date:</u>

Received by OCD: 4/22/2021 9:30:52 AM Form C-141 State of New Mexico
Page 6 Oil Conservation Division

	Page 6 of
Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

☐ A scaled site and sampling diagram as described in 19.15.29.1	1 NMAC				
Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office st be notified 2 days prior to liner inspection)				
☐ Laboratory analyses of final sampling (Note: appropriate ODC	aboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)				
☐ Description of remediation activities					
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of	nediate contamination that pose a threat to groundwater, surface water, a C-141 report does not relieve the operator of responsibility for tions. The responsible party acknowledges they must substantially neditions that existed prior to the release or their final land use in CD when reclamation and re-vegetation are complete.				
Signature:	Date:				
email:	Telephone:				
OCD Only					
OCD Only Received by:	Date:				
Received by: Closure approval by the OCD does not relieve the responsible party	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible				
Received by: Closure approval by the OCD does not relieve the responsible party remediate contamination that poses a threat to groundwater, surface of the contamination of the	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.				

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 25119

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
EOG RESOURCES INC	P.O. Box 2267	Midland, TX79702	7377	25119	C-141

OCD Reviewer	Condition
rmarcus	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141