

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2111648575
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Marathon Oil Permian LLC	OGRID 372098
Contact Name Melodie Sanjari	Contact Telephone 575-988-8753
Contact email msanjari@marathonoil.com	Incident # (assigned by OCD)
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 8220	

Location of Release Source

Latitude 32.203647 Longitude -103.402314
(NAD 83 in decimal degrees to 5 decimal places)

Site Name BLUEBERRY HILL 19 WA FEE #006H	Site Type Oil & Gas Facility
Date Release Discovered: 4/25/2021	API# (if applicable) 30-025-44665

Unit Letter	Section	Township	Range	County
H	19	24S	35E	Lea

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 290	Volume Recovered (bbls) 290
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Corrosion caused a pinhole failure on the 90 of the production line that resulted in the release of approx. 290 bbl. of produced water inside of the lined, secondary containment. The failure was immediately isolated and all standing fluids were recovered from the containment. A 48 hour notification will be sent out prior to a liner integrity inspection.

Incident ID	nAPP2111648575
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Volume
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Yes – NOR submitted 4/26/2021	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Melodie Sanjari</u>	Title: <u>Environmental Professional</u>
Signature: <u>Melodie Sanjari</u>	Date: <u>5/3/2021</u>
email: <u>msanjari@marathonoil.com</u>	Telephone: <u>575-988-8753</u>
<u>OCD Only</u>	
Received by: <u>Ramona Marcus</u>	Date: <u>5/11/2021</u>

NAPP2111648575

AGA
Transportation Services, Inc.
www.agatrans.com
810 E. Rusk Rd. # 441 • El Paso, TX 79912

M 55042

MARATHON OIL CO.

DEPOSIT NUMBER: 04-25-21
CHECKED BY:

DELIVERED FROM: Blue Pump 1111 to 2435-1170 311 TO: 04/05/21

LOCATION: 311

TRUCK OR UNIT NO.: 0176 AMOUNT: 110 GAUGE: TOP: BOTTOM:

☐ RIG ☐ BATTERY ☐ COMPLETION ☐ FLOWBACK

	TIMES	DESCRIPTION	BATTERY			DISPOSAL		
			ARRIVE	DEPART	AMOUNT	ARRIVE	DEPART	AMOUNT
BATTERY	7:30	working at 1111 location						
		working at 1111 location						
		working at 1111 location						
DISPOSAL		working at 1111 location						
		working at 1111 location						
		working at 1111 location						

DRIVER PRINT NAME: John Smith COMPANY MAN PRINT NAME: John Smith
DRIVER SIGNATURE: John Smith COMPANY MAN SIGNATURE: John Smith

Thank You!

AGA
Transportation Services, Inc.
www.agatrans.com
810 E. Rusk Rd. # 441 • El Paso, TX 79912

M 20605

MARATHON OIL CO.

DEPOSIT NUMBER: 04-25
CHECKED BY: 04-25-21

DELIVERED FROM: Blue Pump 1111 to 2435-1170 311 TO: 04/05/21

LOCATION: 311

TRUCK OR UNIT NO.: 7462 AMOUNT: 120 GAUGE: TOP: BOTTOM:

☐ RIG ☐ BATTERY ☐ COMPLETION ☐ FLOWBACK

	TIMES	DESCRIPTION	BATTERY			DISPOSAL		
			ARRIVE	DEPART	AMOUNT	ARRIVE	DEPART	AMOUNT
BATTERY		cleaning spilled water from the container						
		cleaning spilled water from the container						
		cleaning spilled water from the container						
DISPOSAL		120 bags to one site and washout						
		120 bags to one site and washout						
		120 bags to one site and washout						

DRIVER PRINT NAME: John Smith COMPANY MAN PRINT NAME: John Smith
DRIVER SIGNATURE: John Smith COMPANY MAN SIGNATURE: John Smith

Thank You!

Transportation Services, Inc.
accounting@agavetransportation.com
910-K E. Redd Rd. # 443 • El Paso, TX 79912

BILL TO

MARATHON OIL CO.

M 6822

DISPOSAL NUMBER		DATE	4-26-21
COST CENTER		ORDERED BY	

DELIVERED FROM: Blueberry CTB

LOCATION LEASE

TRUCK OR UNIT NO: 4014

AMOUNT HAULED: 50

TO:

☐ RIG ☐ BATTERY ☐ COMPLETION ☐ FLOW BACK

GAUGE: TOP: BOTTOM:

TIMES			DESCRIPTION	BILLING	RATE		AMOUNT	
BATTERY	ARRIVE	6:30 <input type="radio"/> A.M. <input type="radio"/> P.M.	Drove to location from yard. Working on location cleaning spill in containment. Spill is 2360 To unload and without tanker.	Hrs.				
	DEPART	<input type="radio"/> A.M. <input type="radio"/> P.M.		FW				
DISPOSAL	ARRIVE	<input type="radio"/> A.M. <input type="radio"/> P.M.		BW				
	DEPART	<input type="radio"/> A.M. <input type="radio"/> P.M.		PW				
				CRI				

DRIVER PRINT NAME: [Signature]

DRIVER SIGNATURE: [Signature]

COMPANY MAN PRINT NAME: [Signature]

COMPANY MAN SIGNATURE: [Signature]

SUB TOTAL

TAX

TOTAL

Thank You!

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 26676

CONDITIONS OF APPROVAL

Operator: MARATHON OIL PERMIAN LLC 5555 San Felipe St. Permian Regulatory Team Houston, TX77056		OGRID: 372098	Action Number: 26676	Action Type: C-141
OCD Reviewer rmarcus		Condition None		