District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2112053226
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party EOG Resources, Inc.			OGRID 73	377				
Contact Name Chase Settle			Contact Te	elephone 575-7	748-1471			
Contact email Chase_Settle@eogresources.com			Incident #	(assigned by OCD)				
Contact mail	ing address	104 S. 4th Str	eet, Artesia,	NM 88	8210			
Location of Release Source								
Latitude 32	.42186					-104.54790		_
			(NAD 83 in d	ecimal de	grees to 5 decim	nal places)		
Site Name Zi	ngaro AN	IG Federal Ba	ittery		Site Type E	Battery		
Date Release	Discovered	04/19/2021			API# (if app			
				1				
Unit Letter	Section	Township	Range		Coun	ty	_	
Н	1	22S	22S 23S Eddy					
Surface Owne	r: State	✓ Federal ☐ Tı	ribal 🔲 Private	(Namo:			,	
Surface Owne	i. 🔝 State	V Tederar 11	illoar riivate	(ivame.			/	
			Nature an	d Vo	lume of F	Release		
	Materia	ul(s) Released (Select a	ll that apply and attac	h calculat	tions or specific	iustification for the	e volumes provided below)	
Crude Oi		Volume Release	ed (bbls) Unkno	wn		Volume Reco		
Produced	Water	Volume Release	ed (bbls)			Volume Reco	vered (bbls)	
			tion of dissolved	chloride	e in the	Yes N	o	
produced water >10,000 mg/l? Condensate Volume Released (bbls)			Volume Reco	wered (bbls)				
	· /			Volume Reco				
	tural Gas Volume Released (Mcf)							
Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units)								
C f D -1								
Cause of Ref	^{ease} Unkno activit	own historical re es where an oil	elease, no kno I tank was loca	wn vo	lume or da	te. Discovere	ed within the battery during	P&A
activites where arroll tank was located.								

The state of the s	~ ~
Paga	J of
1 426	. VI

Incident ID	nAPP2112053226
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the respon	nsible party consider this a major release?
☐ Yes ☑ No		
If YES, was immediate no	otice given to the OCD? By whom? To wh	om? When and by what means (phone, email, etc)?
	Initial R	esponse
The responsible p	party must undertake the following actions immediatel	y unless they could create a safety hazard that would result in injury
☐ The source of the rele	ease has been stopped.	
☑ The impacted area ha	s been secured to protect human health and	the environment.
✓ Released materials ha	we been contained via the use of berms or d	likes, absorbent pads, or other containment devices.
	ecoverable materials have been removed and	
If all the actions described	d above have <u>not</u> been undertaken, explain	vhy:
has begun, please attach	a narrative of actions to date. If remedial	emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred clease attach all information needed for closure evaluation.
		best of my knowledge and understand that pursuant to OCD rules and
public health or the environr	ment. The acceptance of a C-141 report by the C	fications and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have
		at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws
Printed Name: Chase	Settle	Title: Rep Safety & Environmental Sr
Signature: Chase	o Vettle	Date: 04/30/2021
email: Chase_Settle	@eogresources.com	Telephone: 575-748-1471
		•
OCD Only		
Received by:		Date:

Received by OCD: 5/4/2021 8:50:52 AM State of New Mexico
Page 3 Oil Conservation Division

	Page 3 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

 $This information \ must be provided \ to \ the \ appropriate \ district \ of fice \ no \ later \ than \ 90 \ days \ after \ the \ release \ discovery \ date.$

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)	
Did this release impact groundwater or surface water?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No	
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No	
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No	
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No	
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No	
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No	
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No	
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ☐ No	
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.		
Characterization Report Checklist: Each of the following items must be included in the report.		
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody		

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 5/4/2021 8:50:52 AM State of New Mexico
Page 4 Oil Conservation Division

	Page 4 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name:	_ Title:	
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	

Received by OCD: 5/4/2021 8:50:52 AM State of New Mexico
Page 5 Oil Conservation Division

	Page 5 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

Remediation Plan

Remediation Plan Checklist: Each of the following items must b	e included in the plan.
 □ Detailed description of proposed remediation technique □ Scaled sitemap with GPS coordinates showing delineation poin □ Estimated volume of material to be remediated □ Closure criteria is to Table 1 specifications subject to 19.15.29. □ Proposed schedule for remediation (note if remediation plan times) 	12(C)(4) NMAC
Deferral Requests Only: Each of the following items must be con	afirmed as part of any request for deferral of remediation.
	roduction equipment where remediation could cause a major facility
Extents of contamination must be fully delineated.	
Contamination does not cause an imminent risk to human health	n, the environment, or groundwater.
	e and remediate contamination that pose a threat to groundwater, acceptance of a C-141 report does not relieve the operator of
Printed Name:	Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:
Approved	Approval
Signature:	<u>Date:</u>

Received by OCD: 5/4/2021 8:50:52 AM State of New Mexico
Page 6 Oil Conservation Division

	Page 6 of
Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC					
Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office ust be notified 2 days prior to liner inspection)				
☐ Laboratory analyses of final sampling (Note: appropriate ODC	poratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)				
☐ Description of remediation activities					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name: Title: Title:					
Signature:	Date:				
email:	Telephone:				
OCD Only					
Received by:	Date:				
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.					
Closure Approved by:	Date:				
Printed Name:	Title:				

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 26784

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
EOG RESOURCES INC	P.O. Box 2267	Midland, TX79702	7377	26784	C-141

OCD Reviewer	Condition
rmarcus	None