

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2115531696
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: BTA Oil Producers, LLC	OGRID: 260297
Contact Name: Bob Hall	Contact Telephone: 432-682-3753
Contact email: bhall@btaoil.com	Incident # (assigned by OCD)
Contact mailing address: 104 S. Pecos St., Midland, TX 79701	

Location of Release Source

Latitude: **32.063888** Longitude: **-103.65331°**

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Mesa #2H Production Facility	Site Type: Production Facility
Date Release Discovered: 6/2/2021	API# (if applicable) Nearest well: Mesa #2H API #30-025-41289

Unit Letter	Section	Township	Range	County
D	11	26S	32E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 15 BBL	Volume Recovered (bbls) 0 BBL
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Structural Failure of Dump Valve


The body of the water dump valve on the Mesa 46H separator cut out and sent a stream of water across the floor of the unlined area of the production equipment. The water saturated the immediate area of the equipment, and no fluid was recovered.

The separator vessel was isolated, and the volume of the release was estimated by the size of the vessel compartment that was drained.

<p>Was this a major release as defined by 19.15.29.7(A) NMAC?</p> <p><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>	<p>If YES, for what reason(s) does the responsible party consider this a major release?</p>
<p>If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?</p>	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<div style="border-bottom: 1px solid black; padding-bottom: 5px;"><div style="display: flex; flex-direction: column; gap: 10px;"><div><input checked="" type="checkbox"/> The source of the release has been stopped.</div><div><input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment.</div><div><input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.</div><div><input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.</div></div></div>	
<div style="border-bottom: 1px solid black; margin-bottom: 10px;">If all the actions described above have <u>not</u> been undertaken, explain why:</div> <div style="border-bottom: 1px solid black; margin-bottom: 10px;">Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.</div> <div>I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.</div>	
<div style="display: flex; justify-content: space-between;"><div>Printed Name: Bob Hall Title: Environmental Manager</div><div>Signature: <u></u> Date: 6/4/2021</div></div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"><div>email: bhall@btaoil.com</div><div>Telephone: 432-682-3753</div></div>	
<div style="border-bottom: 1px solid black; margin-bottom: 10px;"><u>OCD Only</u></div> <div style="display: flex; justify-content: space-between;"><div>Received by: <u>Ramona Marcus</u></div><div>Date: <u>6/6/2021</u></div></div>	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 30621

CONDITIONS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 30621
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
marcus	None	6/6/2021