District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	OGRID
Contact Name	Contact Telephone
Contact email	Incident # (assigned by OCD)
Contact mailing address	

Location of Release Source

Latitude	Longitude				
	(NAD 83 in decimal degrees to 5 decimal places)				
Site Name	Site Type				

Site Name	Site Type
Date Release Discovered	API# (if applicable)

Unit Letter	Section	Township	Range	County

Surface Owner: State Federal Tribal Private (Name: _

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)			
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)			
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No			
Condensate	Volume Released (bbls)	Volume Recovered (bbls)			
Natural Gas	Volume Released (Mcf)	eleased (Mcf) Volume Recovered (Mcf)			
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)			
Cause of Release					

Incident ID	
District RP	
Facility ID	
Application ID	

Page 2 of 4

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate n	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

The source of the release has been stopped.

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name	Title:				
Signature:	Date:				
email:	Telephone:				
OCD Only					
Received by: Ramona Marcus	Date:6/30/2021				

APP211	7946158
	Page 3 of 4

			01 D36				Idilic Estilla	NAPP	211/946158 Page 3 of 4
Received by OCD: 6/28/2021F12:10 Name & Number: Raspberry State 1H					Page 3 of 4				
Asset Area:			176 East						
	Releas	e Disco	very Date & Time:	6/10/2021	6/10/2021				
			Release Type:	Produced Water	_				
Provide any known details about the even			s about the event:	corrosion on steal p	corrosion on steal pipe				
				Spill Calculation - On Pad Surface Pool Spill					
Convert Irregular shape into a series of rectangles	Length (ft.)	Width (ft_)	Deepest point in each of the areas (in.)	No. of boundaries of "shore" in each area	Estimated <u>Pool</u> Area (sq. ft.)	Estimated Average Depth (ft.)	Estimated volume of each pool area (bbl.)	Penetration allowance (fl.)	Total Estimated Volume of Spill (bbl.)
Rectangle A	20.0	20.0	1.00	4	400.000	0.021	1.483	0.001	1.485
Rectangle B	15.0	20.0	1.00	4	300.000	0.021	1.113	0.001	1.114
Rectangle C	10.0	40.0	1.00	4	400.000	0.021	1.483	0.001	1.485
Rectangle D	5.0	20.0	1.00	4	100.000	0.021	0.371	0.001	0.371
Rectangle E					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle F					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle G		L			0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle H					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle I					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle J	. 6/20/2	021 4.5	2.42.014		0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
- Released to Imaging	z. 0/30/2	021 4:3	2.43 1 1/1					Total Volume Release:	4.455

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
COG OPERATING LLC	229137
600 W Illinois Ave	Action Number:
Midland, TX 79701	34055
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	6/30/2021

CONDITIONS

Page 4 of 4

Action 34055