District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2117244241
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible	Party			OGRID		
Contact Name			Contact Te	Contact Telephone		
Contact email Incide		Incident #	(assigned by OCD)		
Contact mailing address						
			Location	of Release So	ource	
Latitude				Longitude _		
			(NAD 83 in dec	cimal degrees to 5 decin	nal places)	
Site Name				Site Type		
Date Release	Discovered			API# (if app	olicable)	
Unit Letter	Section	Township	Range	Coun	nty	
Surface Owner	r: State	□ Fadaral □ Tr	ribal 🔲 Private (<i>I</i>	Nama:		
Surface Owner	i. State		iloai 🔲 Fiivate (i	vame		
			Nature and	l Volume of l	Release	
	Material	(s) Released (Select al	ll that annly and attach	calculations or specific	justification for th	e volumes provided below)
Crude Oil		Volume Release		carculations of specific	Volume Reco	
Produced	Water	Volume Release	ed (bbls)		Volume Reco	overed (bbls)
		Is the concentrat	tion of total dissolv	ved solids (TDS)	Yes N	No
□ C - 1	4.		$\frac{\text{water} > 10,000 \text{ mg}}{1.0111}$:/1?	V. I D.	1/11)
Condensa		Volume Release			Volume Reco	
Natural Gas Volume Released (Mcf)			Volume Reco	· · · ·		
Other (describe) Volume/Weight Released (provide units)		e units)	Volume/Wei	ght Recovered (provide units)		
G 07.1						
Cause of Rele	ease					

Page 2 of 12

State of New Mexico

Incident ID	NAPP2117244241
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the respon	nsible party consider this a major release?
☐ Yes ☐ No		
If YES, was immediate no	otice given to the OCD? By whom? To wh	om? When and by what means (phone, email, etc)?
	Initial Ro	esponse
The responsible	party must undertake the following actions immediatel	y unless they could create a safety hazard that would result in injury
☐ The source of the rele	ease has been stopped.	
☐ The impacted area ha	s been secured to protect human health and	the environment.
Released materials ha	ave been contained via the use of berms or contained via the use of the use o	ikes, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and	d managed appropriately.
If all the actions described	d above have <u>not</u> been undertaken, explain	why:
Dog 10 15 20 9 D (4) NIM	[AC the magnetic leaves to the mountain many assume and a second	amodiation immediately often discovery of a valence. If namodiation
has begun, please attach	a narrative of actions to date. If remedial	emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred clease attach all information needed for closure evaluation.
		best of my knowledge and understand that pursuant to OCD rules and
public health or the environr	nent. The acceptance of a C-141 report by the C	fications and perform corrective actions for releases which may endanger DCD does not relieve the operator of liability should their operations have
		at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws
Printed Name:	12	Title:
	an Bako	Date:
email:		Telephone:
OCD Only		
Received by: Ramo	ona Marcus	Date: 6/28/2021

	Page 3 of 1	12
Incident ID	NAPP2117244241	
District RP		
Facility ID		
Application ID		

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

(ft bgs)			
☐ Yes ☐ No			
☐ Yes ☐ No			
☐ Yes ☐ No			
☐ Yes ☐ No			
☐ Yes ☐ No			
☐ Yes ☐ No			
☐ Yes ☐ No			
☐ Yes ☐ No			
☐ Yes ☐ No			
☐ Yes ☐ No			
☐ Yes ☐ No			
Yes No			
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.			
Characterization Report Checklist: Each of the following items must be included in the report.			
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody			

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 6/21/2021 1:56:03 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 of	<i>12</i>
Incident ID		
District RP		
Facility ID		
Application ID		

e best of my knowledge and understand that pursuant to OCD rules and tifications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have reat to groundwater, surface water, human health or the environment. In of responsibility for compliance with any other federal, state, or local laws
Title:
Date:
Telephone:
Date: <u>6/28/2021</u>

Page 5 of 12

	- "8" - ")
Incident ID	NAPP2117244241
District RP	
Facility ID	
Application ID	

Closure


The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

☐ A scaled site and sampling diagram as described in 19.15.29.1	11 NMAC
Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office
☐ Laboratory analyses of final sampling (Note: appropriate ODG	C District office must be notified 2 days prior to final sampling)
Description of remediation activities	
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and replacement human health or the environment. In addition, OCD acceptance of	ntions. The responsible party acknowledges they must substantially inditions that existed prior to the release or their final land use in
Printed Name:	Title:
Printed Name: Signature:	Date:
email:	Telephone:
OCD Only Received by: Ramona Marcus	Date: 6/28/2021
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible for regulations.
Closure Approved by:	Date:
Printed Name:	Title:

Location:	Corral Canyon 10 East			
Spill Date:	6/8/2021			
	Area 1			
Approximate Area =		28.07	cu. ft.	
	VOLUME OF LEAK			
Total Produced Water =		5.00	bbls	


TOTAL VOLUME OF LEAK			
Total Produced Water = 5.00 bbls			
TOTAL VOLUME RECOVERED			
Total Produced Water = 5.0			



NAPP2117244241



NAPP2117244241



NAPP2117244241



Page 11 of 12

Incident ID	NAPP2117244241
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

A scaled site and sampling diagram as described in 19.15.29.11 NMAC		
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
☐ Laboratory analyses of final sampling (Note: appropriate ODC	C District office must be notified 2 days prior to final sampling)	
☐ Description of remediation activities		
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and rer human health or the environment. In addition, OCD acceptance of compliance with any other federal, state, or local laws and/or regular restore, reclaim, and re-vegetate the impacted surface area to the coaccordance with 19.15.29.13 NMAC including notification to the O	ntions. The responsible party acknowledges they must substantially inditions that existed prior to the release or their final land use in OCD when reclamation and re-vegetation are complete.	
Printed Name:	Title:	
Signature:	Date:	
email:	Telephone:	
OCD Only Received by: Ramona Marcus	Date:6/28/2021	
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.	
Closure Approved by: Robert Hamlet	Date:	
Printed Name: Robert Hamlet	Title: Environmental Specialist - Advanced	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 32923

CONDITIONS

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	32923
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rhamlet	We have received your closure report and final C-141 for Incident #NAPP2117244241 CORRAL CANYON 10 EAST, thank you. This closure is approved.	7/7/2021