Analysis Certificate Report Lucid Energy Group-PURCHASER

3100 McKinnon St #800 Dallas, TX 75201 6/16/2021 5:05 AM

PGAS Admin

Analysis ID:	51943	Alternate	ID:	Use Cor	ntract Values: No
Name	PAINT 32 FEE #1H	Company	Name: Luci	id Energy Group	
Effective Date:	03/01/2021 08:00	Saturated HV:	1243.5	Sample Date:	03/30/2021
Valid Thru Date	e: 12/31/2078 00:00	As Del. HV:	1247.3	Sample ID:	6030-21040071- 005A
Fixed Edit Date	01/01/1900 00:00	Dry HV:	1264.1	Sample Type:	Spot
Last Update:	04/13/2021 09:05	Measured HV:	1264.1	Sample Pressure Base:	14.730
Data Acqusition	n:	WOBBE:	1401.6	Sample Temperature:	108.0
Data Source:	Lab Analysis	Water Content:	1.4	•	87.0
Real Relative D	Density: 0.8134	Status:	Active	Lab Code:	
Component	<u> </u>	GPM	Dry Gravity		
Methane	67.1038		Saturated G	Gravity	
Ethane	14.1958	3.8132			
Propane	6.0037	1.6613			
I Butane	0.7069	0.2323			
N Butane	1.6348	0.5177			
I Pentane	0.4102	0.1507			
N Pentane	0.3893	0.1417			
Hexanes +	0.7218	0.3164			
Nitrogen	0.9787				
CO2	4.4634				
Oxygen	0.0000				
H2O	1.4200				
CO	0.0000				
H2S	1.9716				
Hydrogen	0.0000				
Helium	0.0000				
Argon	0.0000				
Total	100.0000	6.8333			

Sample Comments:

Configuration Comments:

8/13/12 Meter number changed from 13589 to 51943. Numbered incorrectly.

FlareV1

Page 2 of 4

Printed: 6/29/2021 4:23 PM Date: 6/28/2021 to 6/28/2021

Unit Battery	Alloc Flare Gas (MCF)
PAINT 32 FEE OIL BATTERY	468.00

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 35285

QUESTIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	35285
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

QUESTIONS

Determination of Reporting Requirements			
Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide addional guidance.			
Was or is this venting or flaring caused by an emergency or malfunction	Yes		
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes		
Is this considered a submission for a notification of a major venting or flaring	Yes, answer to "eight hours or more" suggests this is at least a minor event.		
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under			
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	No		
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No		

Unregistered Facility Site		
Please provide the facility details, if the venting or flaring occurred or is occuring at a facility that does not have an Facility ID (f#) yet.		
Facility or Site Name Paint 32 Fee #1 CTB		
Facility Type	Tank Battery - (TB)	

Equipment Involved		
Primary Equipment Involved	Not answered.	
Additional details for Equipment Involved. Please specify	Not answered.	

Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.		
Methane (CH4) percentage	68	
Nitrogen (N2) percentage, if greater than one percent	1	
Hydrogen Sulfide (H2S) PPM, rounded up	19,790	
Carbon Dioxide (C02) percentage, if greater than one percent	2	
Oxygen (02) percentage, if greater than one percent	2	
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.		
Methane (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	
Oxygen (02) percentage quality requirement	Not answered.	

Date(s) and Time(s)		
Date venting or flaring was discovered or commenced	06/30/2021	
Time venting or flaring was discovered or commenced	12:00 AM	
Is the venting or flaring event complete	Yes	
Date venting or flaring was terminated	07/01/2021	
Time venting or flaring was terminated	12:00 AM	
Total duration of venting or flaring in hours, if venting or flaring has terminated	24	
Longest duration of cumulative hours within any 24-hour period during this event	24	

Measured or Estimated Volume of Vented or Flared Natural Gas		
Natural Gas Vented (Mcf) Details	Not answered.	
Natural Gas Flared (Mcf) Details	Cause: Midstream Emergency Maintenance Frac Tank Natural Gas Flared Spilled: 0 Mcf Recovered: 0 Mcf Lost: 0 Mcf]	
Other Released Details	Not answered.	
Additional details for Measured or Estimated Volume(s). Please specify	468 mcf/day flared. "Was there or will there be at least 50 mcf of natural gas vented or flared during this event" doesn't seem to work when marked yes. Yes, there was over 50 mcf flared during this event.	
Is this a gas only submission (i.e. only Mcf values reported)	More volume information must be supplied to determine if this will be treated as a "gas only" report.	

Venting or Flaring Resulting from Downstream Activity		
Was or is this venting or flaring a result of downstream activity	Not answered.	
Date notified of downstream activity requiring this venting or flaring	Not answered.	
Time notified of downstream activity requiring this venting or flaring	Not answered.	

Steps and Actions to Prevent Waste		
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True	
Please explain reason for why this event was beyond your operator's control	3rd party forced curtailments.	
Steps taken to limit the duration and magnitude of venting or flaring	Executed contract with midstream company to gather gas by 12/1/2021.	
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Executed contract with midstream company to gather gas by 12/1/2021.	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 35285

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	35285
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	7/7/2021