



Certificate of Analysis

Number: 6030-21030332-009A

Artesia Laboratory

200 E Main St.

Artesia, NM 88210

Phone 575-746-3481

Jerry Mathews
 Spur Energy
 1012 Marquez Place, Suite 106b
 Santa Fe, NM 87505

May 25, 2021

Station Name: Lakewood 5 Fed 21
 Station Number: N/A
 Station Location: Spur
 Sample Point: Meter Run
 Type of Sample: Spot-Cylinder
 Heat Trace Used: N/A
 Sampling Method: Fill and Purge
 Sampling Company: SPL
 Analyzed: 03/31/2021 07:12:18 by EJR

Sampled By: Donovan Miller
 Sample Of: Gas Spot
 Sample Date: 03/27/2021 12:52
 Sample Conditions: 78.3 psig, @ 72.8 °F Ambient: 63 °F
 Effective Date: 03/27/2021 12:52
 Method: GPA-2261M
 Cylinder No: 5030-00546
 Instrument: 70104251 (Inficon GC-MicroFusion)
 Last Inst. Cal.: 03/29/2021 0:00 AM

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.73 psia		
Hydrogen Sulfide	0.000	3.60000	4.495		GPM TOTAL C2+	11.060
Nitrogen	0.736	0.71351	0.732		GPM TOTAL C3+	5.413
Methane	54.325	52.65130	30.944		GPM TOTAL iC5+	0.848
Carbon Dioxide	4.250	4.11884	6.641			
Ethane	21.662	20.99447	23.127	5.647		
Propane	11.870	11.50393	18.584	3.188		
Iso-butane	1.470	1.42451	3.033	0.469		
n-Butane	2.954	2.86249	6.095	0.908		
Iso-pentane	0.671	0.65071	1.720	0.239		
n-Pentane	0.568	0.55021	1.454	0.201		
Hexanes Plus	0.960	0.93003	3.175	0.408		
	99.466	100.00000	100.000	11.060		

Calculated Physical Properties

Relative Density Real Gas	Total	C6+
	0.9479	3.2176
Calculated Molecular Weight	27.30	93.19
Compressibility Factor	0.9939	

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.73 psia & 60°F

Real Gas Dry BTU	1463	5141
Water Sat. Gas Base BTU	1438	5052
Ideal, Gross HV - Dry at 14.73 psia	1454.6	5141.1
Ideal, Gross HV - Wet	1428.7	5051.6

Comments: H2S Field Content 3.6 %

Report generated by: Krystle Fitzwater

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

Name of well or facility	Lat	Long	Daily Volume of Flared Natural Gas (MCF/D)	Commencement	Duration	Proposed Remedy
SHELBY 23 TANK BATTERY	32.636495	-104.449015	1655 MCF/D	7/23/2021	Continuous	ACO Requested
ROSS RANCH 09.13.14 BATTERY	32.636187	-104.47781	1480 MCF/D	7/23/2021	Continuous	ACO Requested
OSAGE BOYD 15 FED 09.12.13.14 TANK BATTERY	32.652839	-104.478905	984 MCF/D	7/23/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM NORTH BATTERY	32.625808	-104.469155	2623 MCF/D	7/23/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM SOUTH BATTERY	32.608649	-104.479201	1757 MCF/D	7/23/2021	Continuous	ACO Requested
DORAMI 33 FEDERAL COM 2H.4H.9H TANK BATTERY	32.614416	-104.478493	795 MCF/D	7/23/2021	Continuous	ACO Requested
HUBER 10, 11, 12 FEDERAL OIL TANK BATTERY	32.610648	-104.472851	805 MCF/D	7/23/2021	Continuous	ACO Requested
CLYDESDALE 1 FEE 6H TANK BATTERY	32.686736	-104.4301336	778 MCF/D	7/23/2021	Continuous	Gas Rerouted
MORRIS BOYD TANK BATTERY	32.6250267	-104.4488373	1200 MCF/D	7/23/2021	Continuous	Gas Rerouted
GOODMAN 22 TANK BATTERY	32.652759	-14.474246	1614 MCF/D	7/23/2021	Continuous	Gas Rerouted
PAINT 32 FEE OIL TANK BATTERY	32.7032661	-104.4124146	424 MCF/D	7/23/2021	Continuous	Gas Rerouted
B&B ROSS RANCH TANK BATTERY	32.648389	-104.471283	731 MCF/D	7/23/2021	Continuous	Gas Rerouted
CLYDESDALE 1 FEE 1H TANK BATTERY	32.6961899	-104.430336	207 MCF/D	7/23/2021	Continuous	Gas Rerouted
PATTON 5 FEE 8H TANK BATTERY	32.6836929	-104.4117508	80 MCF/D	7/23/2021	Continuous	Gas Rerouted
BONE YARD 11 FEE TANK BATTERY	32.5957685	-104.4593576	178 MCF/D	7/23/2021	Continuous	Gas Rerouted
STONEWALL 9 FEE 1H TANK BATTERY	32.6687469	-104.3944321	208 MCF/D	7/23/2021	Continuous	Gas Rerouted
ROSE 02.03.04.05.06 TANK BATTERY	32.680563	-104.427371	537 MCF/D	7/23/2021	Continuous	Gas Rerouted
SHERMAN 4 FEE 4H TANK BATTERY	32.682972	-104.3817902	145 MCF/D	7/23/2021	Continuous	Gas Rerouted
FALABELLA 31 FEE 1H TANK BATTERY	32.6976433	-104.4286118	171 MCF/D	7/23/2021	Continuous	Gas Rerouted
PINTO 36 STATE COM 1H TANK BATTERY	32.6977425	-104.4458389	233 MCF/D	7/23/2021	Continuous	Gas Rerouted
PINTO 36 STATE COM 4H TANK BATTERY	32.6976662	-104.4332275	201 MCF/D	7/23/2021	Continuous	Gas Rerouted
BRADLEY 8 FEE 3H TANK BATTERY	32.6683922	-104.428483	213 MCF/D	7/23/2021	Continuous	Gas Rerouted
OKLAHOMA 32 TANK BATTERY	32.7107811	-104.4011078	235 MCF/D	7/23/2021	Continuous	Gas Rerouted
OSAGE BOYD YESO TANK BATTERY	32.6590958	-104.4747391	547 MCF/D	7/23/2021	Continuous	Gas Rerouted
MORRIS 26 E & F TANK BATTERY	32.6335297	-104.460624	284 MCF/D	7/23/2021	Continuous	Gas Rerouted
TARPAN 33 FEE 1H TANK BATTERY	32.6975594	-104.3929749	104 MCF/D	7/23/2021	Continuous	Gas Rerouted
SHERMAN 4 FEE 6H TANK BATTERY	32.6829758	-104.3882675	120 MCF/D	7/23/2021	Continuous	Gas Rerouted
STONEWALL 9 FEE 8H TANK BATTERY	32.66831366	-104.3796728	117 MCF/D	7/23/2021	Continuous	Gas Rerouted
BRADLEY 8 FEE 2H TANK BATTERY	32.6684265	-104.4068375	109 MCF/D	7/23/2021	Continuous	Gas Rerouted
HUBER 3 FEDERAL TANK BATTERY	32.6087456	-104.4661942	148 MCF/D	7/23/2021	Continuous	Gas Rerouted
HUBER 5 FEDERAL TANK BATTERY	32.5952148	-104.4748154	87 MCF/D	7/23/2021	Continuous	Gas Rerouted
TEXAS 32 FEE TANK BATTERY	32.710804	-104.4096985	107 MCF/D	7/23/2021	Continuous	Gas Rerouted
MAYARO 22 STATE TANK BATTERY	32.814968	-104.161609	208 MCF/D	7/23/2021	Continuous	Gas Rerouted
MARACAS 22 STATE TANK BATTERY	32.8214569	-104.1570282	136 MCF/D	7/23/2021	Continuous	Gas Rerouted
ALASKA 29 FEE TANK BATTERY	32.7180519	-104.4055335	81 MCF/D	7/23/2021	Continuous	Gas Rerouted
GRAVE DIGGER STATE COM 8H TANK BATTERY	32.59576569	-104.4588697	78 MCF/D	7/23/2021	Continuous	Gas Rerouted
PATTON 5 FEE 2H TANK BATTERY	32.6943321	-104.4119949	80 MCF/D	7/23/2021	Continuous	Gas Rerouted

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 37722

QUESTIONS

Operator:	Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID:	328947
		Action Number:	37722
		Action Type:	[C-129] Venting and/or Flaring (C-129)

QUESTIONS**Determination of Reporting Requirements**

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting or flaring caused by an emergency or malfunction	No
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a notification of a major venting or flaring	Yes, answer to "eight hours or more" suggests this is at least a minor event.
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under 19.13.297 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	No
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No

Unregistered Facility Site

Please provide the facility details, if the venting or flaring occurred or is occurring at a facility that does not have an Facility ID (##) yet.

Facility or Site Name	LAKEWOOD FEDERAL COM NORTH BATTERY
Facility Type	Tank Battery - (TB)

Equipment Involved

Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	53
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	36,000
Carbon Dioxide (CO2) percentage, if greater than one percent	4
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting or flaring was discovered or commenced	07/23/2021
Time venting or flaring was discovered or commenced	12:00 AM
Is the venting or flaring event complete	Yes
Date venting or flaring was terminated	07/24/2021
Time venting or flaring was terminated	12:00 AM
Total duration of venting or flaring in hours, if venting or flaring has terminated	24
Longest duration of cumulative hours within any 24-hour period during this event	24

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Pipeline Quality Specifications Other (Specify) Natural Gas Flared Spilled: 0 Mcf Recovered: 0 Mcf Lost: 0 Mcf
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	2623 mcf/day flared. "Was there or will there be at least 50 mcf of natural gas vented or flared during this event" doesn't seem to work when marked yes. Yes, there was over 50 mcf flared during this event.
Is this a gas only submission (i.e. only Mcf values reported)	More volume information must be supplied to determine if this will be treated as a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting or flaring a result of downstream activity	Not answered.
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

Steps and Actions to Prevent Waste	
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	3rd party take away refusal due to capacity restraints.
Steps taken to limit the duration and magnitude of venting or flaring	Executed contract with midstream company to gather gas by 12/1/2021.
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Executed contract with midstream company to gather gas by 12/1/2021.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 37722

CONDITIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 37722
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	7/26/2021