District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2107457594
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Kaiser-Francis Oil Company OGRID			OGRID				
Contact Name Charles Lock Contact Te			lephone 918-491-4337				
Contact email Charlesl@kfoc.net Incident			Incident#	assigned by OCD) NAPP2107457594			
Contact mail	ing address	P.O. Box 21468 7	Tulsa, OK 74121				
			Location	of Ro	elease So	ource	
Latitude 32.332411							
Site Name B	ell Lake Uni	t North #327H			Site Type (Dil Production	
Date Release	Discovered	3/15/2021		21	API# (if appl	icable) 30-025-47853	
Unit Letter Section Township Range County				iy			
J	6	23S	34E	Lea			
Surface Owner: State Federal Tribal Private (Name: Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)							
Crude Oi		Volume Release				Volume Recovered (bbls)	
Produced	Water	Vater Volume Released (bbls)			Volume Recovered (bbls)		
		Is the concentra produced water	tion of dissolved >10,000 mg/I?	chloride	in the	Yes No	
Condensa	nte	Volume Release	ed (bbls)			Volume Recovered (bbls)	
☐ Natural C	ias	Volume Release	ed (Mcf)			Volume Recovered (Mcf)	
Other (de	ŕ	Volume/Weight	t Released (provi	de units)	100 bbls	Volume/Weight Recovered (provide units) 95 bbls	
Cause of Release Frac Tank cleanout cover started to leak with most of the fluid being contained inside the secondary containment with the exception of a small leak that occurred in the secondary containment allowing some to spill out to the ground. All fluid inside the secondary containment has been picked up and the fluids that leaked outside of the containment has been neutralized and is in the process of being removed.							

Received by OCD: 7/27/2021 4:13:41 PM Form C-141 State of New Mexico

Page 2

State of New Mexico
Oil Conservation Division

P	age	2	oj	r :

Incident ID NAPP2107457594
District RP
Facility ID
Application ID

Was this a major release as defined by 19.15.29.7(A) NMAC? ☐ Yes ☐ No	If YES, for what reason(s) does the responsible party consider this a major release? Spill was over 25 bbls.
If YES, was immediate n An NOR was filed.	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
	Initial Response
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.
The impacted area ha	s been secured to protect human health and the environment.
Released materials ha	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and managed appropriately.
If all the actions describe	d above have <u>not</u> been undertaken, explain why:
has begun, please attach	IAC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
regulations all operators are public health or the environi failed to adequately investig	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger ment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have gate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
Printed Name:Ch	aarles Lock Title: EH&S Manager
Signature:	Date: 7-27-21
email:charlesl@kfoc	.net
OCD Only	
Received by:Rame	ona Marcus Date: 7/30/2021

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 38458

CONDITIONS

Operator:	OGRID:
KAISER-FRANCIS OIL CO	12361
P.O. Box 21468	Action Number:
Tulsa, OK 74121	38458
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141	7/30/2021