

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2115931823
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party OCCIDENTAL PERMIAN LTD.	OGRID 157984
Contact Name Richard Alvarado	Contact Telephone 432-209-2659
Contact email Richard_Alvarado2@oxy.com	Incident # (assigned by OCD)
Contact mailing address 1017 W. Stanolind Road	

Location of Release Source

Latitude 32°43'14.96" Longitude 103°11'59.65"
(NAD 83 in decimal degrees to 5 decimal places)

Site Name NHURCF	Site Type OIL AND GAS PRODUCTION FACILITY
Date Release Discovered 06/06/2021	API# (if applicable) N/A

Unit Letter	Section	Township	Range	County
H	25	18-S	37-E	LEA

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Natural Gas	Volume Released (Mcf) 150	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

THE NORTH PLANT EXPERIENCED A FLARING EVENT WHEN TRAIN "E" WAS SHUT DOWN TO CHANGE OUT HOT VALVES ON CYLINDER 4, 1ST STAGE DISCHARGE VALVES AND INSPECT CYLINDER 1 AND 3 2ND STAGE SUCTION VALVES.


State of New Mexico
Oil Conservation Division

Incident ID	NAPP2115931823
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? 	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: Restarted Unit STEPS 2-4 WAS NOT APPLICABLE	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Richard Alvarado</u>	Title: <u>HES Specialist</u>
Signature: 	Date: <u>06/07/2021</u>
email: <u>Richard_Alvarado2@oxy.com</u>	Telephone: <u>432-209-2659</u>
<u>OCD Only</u>	
Received by: <u>NAPP2115931823</u>	Date: <u>6/8/2021</u>

State of New Mexico
Oil Conservation Division

Incident ID	NAPP2115931823
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- ☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☐ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☐ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Richard Alvarado Title: HES Specialist

Signature:  Date: 06/07/2021

email: Richard_Alvarado2@oxy.com Telephone: 432-209-2659

OCD Only

Received by: Ramona Marcus Date: 6/8/2021

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by:  Date: 08/10/2021

Printed Name: Chad Hensley Title: Environmental Specialist Advanced

NAPP2115931823

OCCIDENTAL PERMIAN LTD.

Event ID: 113052 Reporting Employee: RICHARD ALVARADO
 Lease Name: NORTH HOBBS UNIT RCF/WIB Account Number: 2415
 Equipment: RCF FLARE NSR Permit Number: 2656-M5
 EPN: RCF - FLR - SSM Title V Permit Number:
 EPN Name: RCF FLARE SSM EVENTS Reg Lease Number:
 Flare Point: RCF-FLR-SSM

Explanation of the Cause:

THE NORTH PLANT EXPERIENCED A FLARING EVENT WHEN TRAIN "E" WAS SHUT DOWN TO CHANGE OUT HOT VALVES ON CYLINDER 4, 1ST STAGE DISCHARGE VALVES AND INSPECT CYLINDER 1 AND 3 2ND STAGE SUCTION VALVES.

Event Type

Scheduled Maintenance
 Scheduled Maintenance
 Scheduled Maintenance

Corrective Actions Taken to Minimize Emissions:

THE UNIT WAS PUT BACK ONLINE AFTER THE REPAIRS WERE MADE TO MINIMIZE FLARING FOR THIS EVENT.

Actions taken to prevent recurrence:

THE UNIT WAS PUT BACK ONLINE AFTER THE REPAIRS WERE MADE TO MINIMIZE FLARING FOR THIS EVENT.

Emission Start Date	Emission End Date	Duration
6/6/2021 9:21:00 AM	6/6/2021 9:44:00 AM	0:23 hh: mm

NMED

Pollutant	Duration (hh:mm)	Aving Period	Excess Emission	Number of Exceedances	Permit Limit	Average Emission Rate	Total Pounds	Tons Per Year		
								Total	Next Drop off Date	Date Permit Exceeded
CO	0:23	1	0 LBS	0	152.10	77.1 LBS/HR	29.55	0.014778	6/8/2021	
H2S	0:23	1	0 LBS	0	14.60	4.56 LBS/HR	1.74	0.000874	6/8/2021	
NOX	0:23	1	0 LBS	0	27.10	8.99 LBS/HR	3.44	0.001724	6/8/2021	
SO2	0:23	1	0 LBS	0	1372.10	420.76 LBS/HR	161.29	0.080646	6/8/2021	
VOC	0:23	1	0 LBS	0	216.70	36.35 LBS/HR	13.93	0.006969	6/8/2021	

Reporting Status: Non-Reportable

NMOCD

Flare Stream Total	Total MCF	EPN	Latitude	Longitude	Reporting Status
124 MCF	150 MCF	RCF FLARE SSM EVENTS	32° 43' 14.96"	103° 11' 59.65"	Minor release

LEPC

Total MCF	H2S %	Unit Letter	Section	Township	Range
150	0.786	H	25	18 S	37 E

Pollutant	Emission rate	Reportable Qty
SO2	161.29 LBS/DAY	500 LBS/DAY
SO2	161.29 LBS/DAY	500 LBS/DAY
SO2	161.29 LBS/DAY	500 LBS/DAY

Reporting Status: Non-reportable

Emissions Calculations:

NOx = MCF flared x NOx factor from RG-109 x BTU/scf x 1000 scf/MCF x MMBTU/1000000 BTU

CO = MCF flared x CO factor from RG-109 x BTU/scf x 1000 scf/MCF x MMBTU/1000000 BTU

Gas was flared to reduce the hydrocarbon and/or H2S emissions to the atmosphere.

NMNE NG = MCF flared x 50 lb/mole x mole/.379 MCF x mol % NMNE NG x 0.02

NMNE NG % = 100% - Methane % - Ethane % - Carbon Dioxide % - Nitrogen %

H2S = MCF flared x 34 lb/mole x mole/.379 MCF x mol % H2S/100 x 0.02

SO2 = MCF flared x 64 lb/mole x mole/.379 MCF x mol % H2S/100 x 0.98

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 30947

CONDITIONS

Operator: OCCIDENTAL PERMIAN LTD P.O. Box 4294 Houston, TX 772104294	OGRID: 157984
	Action Number: 30947
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
chensley	The OCD is no longer accepting gaseous natural gas leaks via a C-141. Please use permit C-129 for all future releases.	8/10/2021