District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Incident ID	nAPP2123153867
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Marathon Oil Permian LLC	OGRID 372098
Contact Name Melodie Sanjari	Contact Telephone 575-988-8753
Contact email msanjari@marathonoil.com	Incident # (assigned by OCD)
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 8220	

Location of Release Source

Latitude 32.28208193

Longitude -104.28644227

(NAD 83 in decimal degrees to 5 decimal places)

Site Name RED LIGHT 27 34 STATE COM #002H	Site Type Oil & Gas Facility
Date Release Discovered: 8/19/2021	API# (if applicable) 30-015-43917

Unit Letter	Section	Township	Range	County
D	27	238	26E	Eddy

Surface Owner: State Federal Tribal Private (Name: _____

Nature and Volume of Release

Mater	ial(s) Released (Select all that apply and attach calculations or specifi	c justification for the volumes provided below)	
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)	
Produced Water	Volume Released (bbls) 332	Volume Recovered (bbls) 360	
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No	
Condensate	Volume Released (bbls)	Volume Recovered (bbls)	
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)	
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)	

Cause of Release

Operator arrived on location to a pinhole on the water leg off of the separator that resulted in the release of approx. 332 bbl. of produced water. The source of the failure was isolated and all standing fluid was recovered. It should be noted that it was actively raining the day of discovery – hence the higher volume of recovered fluid. A notice will be sent out to the Division prior to a liner inspection.

ceived by OCD: 8/23/202	<i>ived by OCD: 8/23/2021 7:46:14 AM</i> n C-141 State of New Mexico		Page 2
1111 (-141	Oil Conservation Division	Incident ID	nAPP2123153867
e 2		District RP	
		Facility ID	
		Application ID	
Was this a major release as defined by 19.15.29.7(A) NMAC? ⊠ Yes □ No	If YES, for what reason(s) does the responsible par Volume	rty consider this a major release	?
If YES, was immediate ne NOR submitted 8/19/202	otice given to the OCD? By whom? To whom? Wi 1	hen and by what means (phone, o	email, etc)?
	Initial Respons	se	

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \square The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: <u>Melodie Sanjari</u>	Title:Environmental Professional
Signature: <u>Melodie Sanjari</u>	Date: 8/23/2021
email: <u>msanjari@marathonoil.com</u>	Telephone: <u>575-988-8753</u>
OCD Only	
Received by: <u>Ramona Marcus</u>	Date: <u>8/23/2021</u>

Spill Calculation Tool



	Length (ft.)	Width (ft.)	Avg. Liquid Depth (in.)	% Oil	Total Volume (bbls)	Water Volume (bbls)	Oil Volume (bbls)
Rectangle Area #1	80	40	7		332.47	332.47	0.00
Rectangle Area #2					0.00	0.00	0.00
Rectangle Area #3					0.00	0.00	0.00
Rectangle Area #4					0.00	0.00	0.00
Rectangle Area #5					0.00	0.00	0.00
Rectangle Area #6					0.00	0.00	0.00
Tank Displacement					0.00	0.00	0.00
Tank Displacement					0.00	0.00	0.00
-				Liquid Volume:	332.47	332.47	0.00
-	Length (ft.)	Width (ft.)	Avg. Saturated Depth (in.)	% Oil	Total Volume (bbls)	Water Volume (bbls)	Oil Volume (bbls)
Saturated Soil Inputs:		Soil Type:					
_	Length (ft.)	Width (ft.)	Depth (in.)	% Oil	(bbls)	(bbls)	(bbls)
Rectangle Area #1				0%	0.00	0.00	0.00
Rectangle Area #2				0%	0.00	0.00	0.00
Rectangle Area #3				0%	0.00	0.00	0.00
Rectangle Area #4				0%	0.00	0.00	0.00
Rectangle Area #5				0%	0.00	0.00	0.00
Rectangle Area #6				0%	0.00	0.00	0.00
-							
Rectangle Area #7					0.00	0.00	0.00
-					0.00 0.00	0.00 0.00	0.00 0.00
Rectangle Area #7				Saturated Volume			
Rectangle Area #7 Rectangle Area #8	Recovered and no	t included in Stanc	ling Liguid Inputs :	ľ	0.00	0.00	0.00
Rectangle Area #7 Rectangle Area #8	Recovered and no	t included in Stanc		·	0.00 0.00 Total Volume	0.00 0.00 Water Volume	0.00 0.00 Oil Volume
Rectangle Area #7 Rectangle Area #8	Recovered and no	t included in Stanc		·	0.00 0.00 Total Volume	0.00 0.00 Water Volume	0.00 0.00 Oil Volume

Received by OCD: 8/23/2021 2:46:14 AM

NAPP2123153867

United Well Ser	VICES, LLV.
P.O. Box 2121 Carlsba	ad, NM 88221
P.O. Box 2121 Carlsba Phone# 575-649-5634 • uw	No 96050
28-19-21	132
Marathor OI	111
IL IT FIELD	ITTE OT
ation/Lease	
posal/Ticket #T	icket #
ter StationE	ottom Gage
Gage	10-
ick No. 4441	AM TOTAL PM HOURS
AM END TIME	Barrels
Fresh water	Barrels
Brine water	Barrels
Produced water	Barrels
Other	Barrels
KCL	
b Description	er hoy Me
TIENY CONTAINER	To disposed
Mercy CONTRIDUCE	
ne leaving yard	
ne arriving location	
ne leaving location	
e arriving disposal/water st.	
e leaving disposal/water st.	D AM D PM
e arriving yard	Weller,
er Name	15 Jacob Z.
	1 12 22 2

2

311

United Weil Servic P.O. Box 2121 Carlsbad, N Phone#575.649-5634 • uws199	es, LLC. M 88221 9@gmail.com Nº 95942
Date 8/19/2 DN/DN	all all markers
Company	2H
Location/Lease	1918
Disposal/Ticket #Ticket	
1600	
	m Gage
Top Gage	AM TOTAL
Truck No. 99 10	PM HOURE
START TIME 10:20	Barrels
Fresh water	Barrels
Brine water) Barrels
Produced water	Barrels
Other	Barrels
D KCL	
Job Description	TEK THE
FOR HELT ASSIS	T The SPill
CALLANDER - API	CIDON
Contrahout ere	
ROUSTABOUT ON	
ROUSTABOUT CAS WATER	
ROUSTAGOUT CAS WATER	
ROUSTAGUT CAS WATER Time leaving yard	D AM D PM
Time arriving location	
Time arriving location Time leaving location arriving disposal/water st.	AM PM AM PM AM PM AM PM
Time arriving location Time leaving location arriving disposal/water st.	AM D PM AM D PM
Time arriving location Time leaving location Time arriving disposal/water st. Time leaving disposal/water st.	AM PM AM PM AM PM AM PM
Time arriving location Time leaving location Time arriving disposal/water st. Time leaving disposal/water st. Time arriving yard	AM D PM AM D PM
Time arriving location Time leaving location Time arriving disposal/water st. Time leaving disposal/water st.	AM D PM AM D PM

1

100

	3
u convices, LLC	
United Well Services, LLC P.O. Box 2121 Carlsbad, NM 88221 P.O. Box 2121 Carlsbad, NM 88221 P.O. Box 3121 Carlsbad, NM 8999@gmail.com	The second
P.O. Box 2121 Carlsbad, NM 88221 P.O. Box 2121 Carlsbad, NM 88221 Phone# 575-649-5634 • uws1999@gmail.com	o 95943
Date 8/19/01/hop or C	
Company Marine Last 24	
Location/Lease	
Disposal/Ticket # Ticket #	The second second
Water StationBottom Gage	
Top Gage	
Truck No. 4438 AM	TOTAL 400
AM END TIME	
Barrels	
Brine water Do Barrels	
Produced water Barrels	
D OtherBarrels	
D KCL	Theret
Job Description	14th of MI
Jane of the thister	the former of the second secon
Althe Spill Chlor	
Minte	
Time leaving yard	
Time arriving location	MADW
Time leaving location	DAMOPM
Time arriving disposal/water st.	
Time leaving disposal/water st.	
Time arriving yard	UE
Driver Name	1-1
Co-Personnel	0
	A State of the second

Released to Imaging: 8/23/2021 8:23:09 AM

ersonnel _

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
MARATHON OIL PERMIAN LLC	372098
5555 San Felipe St.	Action Number:
Houston, TX 77056	43655
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	8/23/2021

CONDITIONS

Page 5 of 5

Action 43655