District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2124533703
District RP	
Facility ID	
Application ID	

# **Release Notification**

## **Responsible Party**

				OGRID: 2			
Contact Name: Thomas Long				Contact T	elephone: <b>505-599-2286</b>		
Contact em	ail: <b>tjlong@</b>	eprod.com		Incident #	(assigned by OCD) nAPP2124533703		
Contact ma	iling addres	ss: 614 Reilly Av	e, Farmington, l	NM			
Location of Release Source							
Latitude 36.845013 Longitude -107.870609 NAD 83 in decimal degrees to 5 decimal places)							
Site Name Atlantic BLS #22 Site Typ				Site Type	Natural Gas Gathering Pipeline		
Date Release Discovered: 09/01/2021				Serial # (if	applicable) N/A		
11:-:41 -44-:-	0+:	Tarrackia	D	0			
Unit Letter	Section	Township	Range	Coun			
С	3	30N	10W	San J	uan		
Surface Owner: State Federal Tribal Private (Name: Marc and Marcia Yoos  Nature and Volume of Release  Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)							
Crude Oil		Volume Released (bbls)			Volume Recovered (bbls)		
☐ Produced Water		Volume Released (bbls)			Volume Recovered (bbls)		
		Is the concentration of dissolved chlo produced water >10,000 mg/l?			☐ Yes ☐ No		
☐ Condensate Volume Released (bbls): Estimated			ed (bbls): Estima	ated 3-5 BBLs	Volume Recovered (bbls): None		
□ Natural Gas			ed (Mcf): <b>0.281 N</b>	MCF	Volume Recovered (Mcf): None		
Other (describe)		Volume/Weight Released (provide units)		de units)	Volume/Weight Recovered (provide units)		
Lubrication Oil							
during repairs service for the underground	s and remed he repairs a . Liquids are	iation activities ass and remediation fo present in the subs	ociated with a prev r the other releas surface. The releas	vious release on the e. No liquids wer se was located in a	e of natural gas liquids from the Atlantic BLS #22 pipeline he BLS #22 pipeline. The pipeline was temporarily out of the observed on the ground surface. The release was a small ephemeral wash (blue line) on a topographic map, activities are in progress. A third party corrective action		

report will be submitted with the "Final C-141."


## **Initial Response**

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Cory Smith -

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<ul> <li>☑ The source of the release has been stopped.</li> <li>☑ The impacted area has been secured to protect human health and the environment.</li> <li>☑ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.</li> <li>☑ All free liquids and recoverable materials have been removed and managed appropriately.</li> </ul>						
If all the actions described above have <u>not</u> been undertaken, explain why:						
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
Printed Name: Thomas J. Long Title: Senior Environmental Scientist						
Signature:						
email: tjlong@eprod.com Telephone: _505-599-2286_						
OCD Only						
Received by: Ramona Marcus  Date: 9/7/2021						

NMOCD on 9/1/2021 at 0835.



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 46052

#### **CONDITIONS**

Operator:	OGRID:
Enterprise Field Services, LLC	241602
PO Box 4324	Action Number:
Houston, TX 77210	46052
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	9/7/2021