District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2125640335
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party EOG Resources			OGRID 73	377			
Contact Name Todd Wells		(Contact Telephone (432) 686-3613				
Contact email Todd_Wells@eogresources.com		-	Incident # ((assigned by OCD)	nAPP2125640335		
Contact mailing address 5509 Champions Drive Midland, TX 79706							
			Location	of Re	lease So	ource	
Latitude 32.766876° Longitud			ongitude -	103.992526°			
<u></u>			(NAD 83 in de				
Site Name O	atmeal 8 Fe	d Com #2H		5	Site Type Tank Battery		
Date Release	Discovered	8/29/21		A	API# (if appl	licable)	
Unit Letter	Section	Township	Range		Count	tv	
В	8	18S	30E	Eddy	Coun	· y	
Surface Owner: State Federal Tribal Private (Name:) Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)							
Crude Oi		Volume Release	ed (bbls)			Volume Recov	,
Produced	Water	Volume Release	. ,			Volume Recov	` '
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?		n the	Yes No)		
Condensate Volume Released (bbls)			Volume Recov	vered (bbls)			
Natural Gas Volume Released (Mcf)			Volume Recov	vered (Mcf)			
Other (describe) Volume/Weight Released (provide units)			Volume/Weigl	ht Recovered (provide units)			
		nanway gasket on the first of t		failed rele	easing appr	oximately 20 bb	ols of produced water and oil around the

Received by OCD: 9/13/2021 11:23:47 AM Form C-141 State of New Mexico Oil Conservation Division Page 2

	Page 2 of
nt ID	NAPP2125640335
t RP	

Incident ID	NAPP2125640335
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) do	oes the responsible part	ty consider this a major release?	
☐ Yes ⊠ No				
If YES, was immediate no	otice given to the OCD? By w	hom? To whom? Wh	en and by what means (phone, ema	ail, etc)?
		Initial Respons	e	
The responsible p	party must undertake the following act	tions immediately unless the	y could create a safety hazard that would re	esult in injury
The source of the rele	ease has been stopped.			
The impacted area ha	s been secured to protect huma	an health and the environ	onment.	
			orbent pads, or other containment of	levices.
<u> </u>	ecoverable materials have been d above have <u>not</u> been undertal		d appropriately.	
D., 10 15 20 0 D. (4) NIM	AC the many like materials	1:4:		l If i'.d
has begun, please attach	a narrative of actions to date.	If remedial efforts ha	on immediately after discovery of a tive been successfully completed or such all information needed for closure.	r if the release occurred
regulations all operators are public health or the environmental to adequately investigated	required to report and/or file certa ment. The acceptance of a C-141 ate and remediate contamination t	in release notifications ar report by the OCD does re hat pose a threat to groun	knowledge and understand that pursual perform corrective actions for release not relieve the operator of liability should be adverted, surface water, human health of lity for compliance with any other federal performance.	ses which may endanger ald their operations have r the environment. In
Printed Name:Todd W	<u>'ells</u>	Title: <u>Environm</u>	ental Specialist	
Signature: Todd	Wells	Date: _	9-13-21	
email:Todd_Wells	@eogresources.com	Telephone: _	(432) 686-3613	_
OCD Only				
Received by: Ramona M	Marcus	Date:	9/13/2021	

Received by OCD: 9/13/2021 11:23:47 AM Form C-141 State of New Mexico
Page 3 Oil Conservation Division

	I uge 5 0
Incident ID	
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)	
Did this release impact groundwater or surface water?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No	
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No	
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No	
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No	
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No	
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No	
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No	
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ☐ No	
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.		
Characterization Report Checklist: Each of the following items must be included in the report.		
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody		

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 9/13/2021 11:23:47 AM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name:		
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by: Date:		

Received by OCD: 9/13/2021 11:23:47 AM Form C-141 State of New Mexico Page 5 Oil Conservation Division

	Page 5 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

Remediation Plan

Remediation Plan Checklist: Each of the following items must b	e included in the plan.	
 □ Detailed description of proposed remediation technique □ Scaled sitemap with GPS coordinates showing delineation points □ Estimated volume of material to be remediated □ Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC □ Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required) 		
Deferral Requests Only: Each of the following items must be con	nfirmed as part of any request for deferral of remediation.	
Contamination must be in areas immediately under or around p deconstruction.	roduction equipment where remediation could cause a major facility	
Extents of contamination must be fully delineated.		
Contamination does not cause an imminent risk to human health	n, the environment, or groundwater.	
	e and remediate contamination that pose a threat to groundwater, acceptance of a C-141 report does not relieve the operator of	
Printed Name:	Title:	
Signature:	Date:	
email:	Telephone:	
OCD Only		
OCD OILLY		
Received by:	Date:	
☐ Approved ☐ Approved with Attached Conditions of	Approval	
Signature:	Date:	

Received by OCD: 9/13/2021 11:23:47 AM Form C-141 State of New Mexico Page 6 Oil Conservation Division

	Page 6 of
Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

A scaled site and sampling diagram as described in 19.15.29.11 NMAC			
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)			
☐ Laboratory analyses of final sampling (Note: appropriate ODC	C District office must be notified 2 days prior to final sampling)		
☐ Description of remediation activities			
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name: Title:			
Signature:	Date:		
Signature:email:	Date: Telephone:		
email:			
OCD Only Received by: Closure approval by the OCD does not relieve the responsible party	Date: Of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible		
OCD Only Received by: Closure approval by the OCD does not relieve the responsible party remediate contamination that poses a threat to groundwater, surface	Date: Of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 48022

CONDITIONS

Operator:	OGRID:	
EOG RESOURCES INC	7377	
P.O. Box 2267	Action Number:	
Midland, TX 79702	48022	
	Action Type:	
	[C-141] Release Corrective Action (C-141)	

CONDITIONS

Created By	Condition	Condition Date
rmarcus	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141	9/13/2021