

1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources

Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

AUG 02 2016

Submit 1 Copy to appropriate District Office in
 accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Jake Harrington, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	432-214-5175
Facility Name	Cotton Draw Unit 11 Bone Spring CTB	Facility Type	Oil-Central Tank Battery

Surface Owner	Federal	Mineral Owner	Federal	API No	N/A
---------------	---------	---------------	---------	--------	-----

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	11	25S	31E	N/A	N/A	N/A	N/A	Eddy

Latitude: 32°08'57.706"N Longitude: 103°44'48.453"W

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	1200 BBLS	Volume Recovered	1200 BBLS
Source of Release	All water tanks and gun barrel	Date and Hour of Occurrence	7/31/2016 @ 5:40pm	Date and Hour of Discovery	7/31/2016 @ 5:40pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD- Mike Bratcher BLM- Shelly Tucker		
By Whom?	Hubert Perry, Night Production Foreman	Date and Hour	OCD- 7/31/2016 @ 10:03pm BLM- 7/31/2016 @ 10:05pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*
 The Central Tank Battery was struck by lightning resulting in a release of 1200 BBLS produced water and caused a small fire. The well that produces to this facility was shut in immediately and power to the affected equipment and well was turned off to prevent further release. The local Fire Department was called to ensure safety and to extinguish the fire.

Describe Area Affected and Cleanup Action Taken.*
 1200 BBLS of produced water was released when lightning struck the Central Tank Battery causing the water tanks to rupture and start a fire. Due to the fact that the water tanks were connected by equalizing lines produced water from all tanks was released. Fire died out before the local Fire Department arrived. The produced water was released into the surrounding lined containment. The liner was checked for holes, no holes were found in the liner. Due to the fact that no holes were found in the liners, it is assumed all the released fluid remained in the lined containment and did not leave location. Vacuum truck recovered approximately 1200 BBLS of fluid. Environmental agency will be contacted for remediation.

Liner and containment have been inspected and no deficiencies were found.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION	
Printed Name: Sarah Gallegos-Troublefield	Signed By: <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 8/2/16	Expiration Date: N/A
E-mail Address: Sarah.Gallegos-Troublefield@dm.com	Conditions of Approval:	
Date: 8/2/2016 Phone: 575.748.1864	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	

ATER THAN: 9/18/16

Attached ☐

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Gallegos-Troublefield, Sarah <Sarah.Gallegos-Troublefield@dmv.com>
Sent: Tuesday, August 02, 2016 1:31 PM
To: jamos@blm.gov; Tucker, Shelly; Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Fulks, Brett; Scrogum, Sandy
Subject: Cotton Draw Unit 11 Bone Springs Central Tank Battery_1200 BBLS PW_7-31-16_C-141
Attachments: Cotton Draw Unit 11 Bone Springs CTB_1200 BBLS PW_7-31-16_GIS Image.pdf; Cotton Draw Unit 11 Bone Spring CTB_1200 BBLS PW_7-31-16_Pic 10 of 10.JPG; Cotton Draw Unit 11 Bone Spring CTB_1200 BBLS PW_7-31-16_Pic 9 of 10.JPG; Cotton Draw Unit 11 Bone Spring CTB_1200 BBLS PW_7-31-16_Pic 8 of 10.JPG; Cotton Draw Unit 11 Bone Spring CTB_1200 BBLS PW_7-31-16_Pic 7 of 10.JPG; Cotton Draw Unit 11 Bone Spring CTB_1200 BBLS PW_7-31-16_Pic 6 of 10.JPG; Cotton Draw Unit 11 Bone Spring CTB_1200 BBLS PW_7-31-16_Pic 5 of 10.JPG; Cotton Draw Unit 11 Bone Spring CTB_1200 BBLS PW_7-31-16_Pic 4 of 10.JPG; Cotton Draw Unit 11 Bone Spring CTB_1200 BBLS PW_7-31-16_Pic 3 of 10.JPG; Cotton Draw Unit 11 Bone Spring CTB_1200 BBLS PW_7-31-16_Pic 2 of 10.JPG; Cotton Draw Unit 11 Bone Spring CTB_1200 BBLS PW_7-31-16_Pic 1 of 10.JPG; Cotton Draw Unit 11 Bone Spring CTB_1200 BBLS PW_7-31-16_Initial C-141.doc

Good afternoon,

Please find attached the Initial C-141, GIS Image and 10 photos of the Cotton Draw Unit 11 Bone Spring Central Tank Battery release of 1200 BBLS produced water that occurred on 7/31/2016. Please be advised that the blue dot in the GIS Image represents the approximate location of the origin of the release.
Please contact me with any questions you may have.

Thank you very much and have a great day.

Respectfully,

Sarah Gallegos-Troublefield
Field Admin Support
Production

Devon Energy Corporation
P.O. Box 250
Artesia, NM 88211
575 748 1864 Direct Line



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 4910

CONDITIONS

Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137
	Action Number: 4910
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
bbillings	None	9/14/2021