

GAS VOLUME STATEMENT**Spur Energy**

July, 2021

Meter #: 79410093

Name: Ross Ranch CTB Flare

Closed Data

Artesia-East

Pressure Base: 14.730 psia

Temperature Base: 60.00 °F

HV Cond:

Meter Type: EFM

Contract Hr.: Midnight

Status: In Service

WV Technique:

WV Method:

CO2	N2	H2O	H2S	O2	He	C1	C2	C3	I-C4	N-C4	I-C5	N-C5	C6+
4.850	2.713	0.000	1.9633	0.000	0.000	64.426	13.428	7.250	0.994	2.332	0.568	0.552	0.923
Tube I.D.	Interval	Tap Location		Tap Type		Atmos. Pressure		Calc. Method		Fpv Method			
3.068 in.	1 Hour	Upstream		Flange		13.140 psi		AGA3-1992		AGA8-Detail			

Day	Differential (In. H2O)	Pressure (psia)	Temperature (°F)	Hours Flow	Relative Density	Plate (inches)	Volume (Mcf)	Heating Value (Btu/scf)	Energy (MMBtu)	Edited
1	0.00	12.99	81.38	0.00	0.8342	2.000	0.00	1279.90	0.00	No
2	0.00	12.99	79.65	0.00	0.8342	2.000	0.00	1279.90	0.00	No
3	0.00	12.99	79.46	0.00	0.8342	2.000	0.00	1279.90	0.00	No
4	0.25	12.94	102.34	0.04	0.8342	2.000	0.07	1279.90	0.10	No
5	0.00	12.97	83.21	0.00	0.8342	2.000	0.00	1279.90	0.00	No
6	0.00	12.98	81.51	0.00	0.8342	2.000	0.00	1279.90	0.00	No
7	0.00	12.99	80.43	0.00	0.8342	2.000	0.00	1279.90	0.00	No
8	0.00	12.99	85.41	0.00	0.8342	2.000	0.00	1279.90	0.00	No
9	0.00	12.99	85.30	0.00	0.8342	2.000	0.00	1279.90	0.00	No
10	0.00	12.98	84.51	0.00	0.8342	2.000	0.00	1279.90	0.00	No
11	0.00	12.99	78.51	0.00	0.8342	2.000	0.00	1279.90	0.00	No
12	0.00	13.01	82.86	0.00	0.8342	2.000	0.00	1279.90	0.00	No
13	0.00	13.02	81.30	0.00	0.8342	2.000	0.00	1279.90	0.00	No
14	0.25	12.98	105.27	0.94	0.8342	2.000	1.67	1279.90	2.14	No
15	0.25	12.96	113.73	1.20	0.8342	2.000	2.12	1279.90	2.71	No
16	0.25	12.95	110.44	1.20	0.8342	2.000	2.12	1279.90	2.71	No
17	0.25	12.98	110.40	0.33	0.8342	2.000	0.58	1279.90	0.74	No
18	0.00	13.04	74.08	0.00	0.8342	2.000	0.00	1279.90	0.00	No
19	0.00	13.04	79.77	0.00	0.8342	2.000	0.00	1279.90	0.00	No
20	40.10	25.03	91.68	8.70	0.8342	2.000	261.69	1279.90	334.93	No
21	39.48	25.68	84.41	24.00	0.8342	2.000	731.19	1279.90	935.85	No
22	36.54	25.32	78.43	14.38	0.8342	2.000	410.06	1279.90	524.83	No
23	0.00	12.99	81.32	0.00	0.8342	2.000	0.00	1279.90	0.00	No
24	0.25	12.99	110.12	0.31	0.8342	2.000	0.56	1279.90	0.71	No
25	0.00	12.99	82.46	0.00	0.8342	2.000	0.00	1279.90	0.00	No
26	0.26	12.99	110.99	1.52	0.8342	2.000	2.70	1279.90	3.45	No
27	0.25	13.03	109.73	0.21	0.8342	2.000	0.38	1279.90	0.49	No
28	0.00	13.02	81.42	0.00	0.8342	2.000	0.00	1279.90	0.00	No
29	0.00	13.02	82.82	0.00	0.8342	2.000	0.00	1279.90	0.00	No
30	0.00	13.03	82.82	0.00	0.8342	2.000	0.00	1279.90	0.00	No
31	0.00	13.02	84.86	0.00	0.8342	2.000	0.00	1279.90	0.00	No
TOTAL	38.46	25.36	84.21	52.84	0.8342		1,413.12		1,808.65	

Name of well or facility	Lat	Long	Daily Volume of Flared Natural Gas (MCF/D)	Commencement	Duration	Proposed Remedy
SHELBY 23 TANK BATTERY	32.636495	-104.449015	787 MCF/D	9/23/2021	Continuous	ACO Requested
ROSS RANCH 09.13.14 BATTERY	32.636187	-104.47781	1041 MCF/D	9/23/2021	Continuous	ACO Requested
OSAGE BOYD 15 FED 09.12.13.14 TANK BATTERY	32.652839	-104.478905	1309 MCF/D	9/23/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM NORTH BATTERY	32.625808	-104.469155	2425 MCF/D	9/23/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM SOUTH BATTERY	32.608649	-104.479201	1609 MCF/D	9/23/2021	Continuous	ACO Requested
DORAMI 33 FEDERAL COM 2H.4H.9H TANK BATTERY	32.614416	-104.478493	844 MCF/D	9/23/2021	Continuous	ACO Requested
HUBER 10, 11, 12 FEDERAL OIL TANK BATTERY	32.610648	-104.472851	598 MCF/D	9/23/2021	Continuous	ACO Requested
SHORTY 2 STATE COM TANK BATTERY	32.8653287	-103.9504986	1237 MCF/D	9/23/2021	Continuous	Gas Rerouted

District I1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720**District II**811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720**District III**1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170**District IV**1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 51707

QUESTIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 51707
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Prerequisites**

Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.

Incident Well	Not answered.
Incident Facility	[fAPP2123533271] Ross Ranch 09.12.13.14 Tank Battery

Determination of Reporting Requirements

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting and/or flaring caused by an emergency or malfunction	No
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a venting and/or flaring event	Yes, major venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved

Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	64
Nitrogen (N2) percentage, if greater than one percent	3
Hydrogen Sulfide (H2S) PPM, rounded up	19,633
Carbon Dioxide (CO2) percentage, if greater than one percent	5
Oxygen (O2) percentage, if greater than one percent	0

If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.

Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting and/or flaring was discovered or commenced	09/23/2021
Time venting and/or flaring was discovered or commenced	12:00 AM
Time venting and/or flaring was terminated	12:00 AM
Cumulative hours during this event	24

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
----------------------------------	---------------

Natural Gas Flared (Mcf) Details	Cause: Pipeline Quality Specifications Other (Specify) Natural Gas Flared Released: 1,041 Mcf Recovered: 0 Mcf Lost: 1,041 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	flare stack
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting and/or flaring a result of downstream activity	Not answered.
Was notification of downstream activity received by you or your operator	Not answered.
Downstream OGRID that should have notified you or your operator	Not answered.
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	3rd party take away refusal due to capacity restraints.
Steps taken to limit the duration and magnitude of venting and/or flaring	Executed contract with midstream company to gather gas by 12/1/2021.
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Executed contract with midstream company to gather gas by 12/1/2021.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 51707

CONDITIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 51707
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
schapman01	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	9/24/2021