

| 9940G | | | 72085-000 | | \ | Wishbone 35/34 | B2PM FC #1H |
|------------------------------------|------------------------------|------------------------|-----------------|--|-----------------------|--|-------------|
| Sample Point Code | | | Sample Point Na | me | Sample Point Location | | t Location |
| | | | | | | | |
| Laboratory | Services | 2020030 | 615 | 1387 | | R Vega - Spo | t |
| Source Lab | oratory | Lab File I | No — | Container Identity | Sampler | | |
| USA | | USA USA | | New Mexico | | | |
| District | | Area Name | | Field Name | Facility Name | | |
| Mar 24, 2020 | 09:29 | Mar 24, | 2020 09:29 | Mar 24 | , 2020 11:51 | Mar 2 | 25, 2020 |
| Date Sample | ed | Date | e Effective | Dat | e Received | Date | Reported |
| 59.00 | | Torrand | ce | 277 @ 87 | | | |
| Ambient Temp (°F) | Flow Rate (Mcf) | Analysi | t | Press PSI @ Temp °F Source Conditions | | | |
| Mewbourne Oil | Company | | | | | NG | |
| Operato | r | | | | l | ab Source Descripti | on |
| Component | Normalized Mol % | Un-Normalized Mol % | GPM | Gro 14.696 PSI @ | _ | es (Real, BTU/ft | - |
| H2S (H2S) | 0.0000 | 0 | | Dry | Saturated | Dry | Saturated |
| Nitrogen (N2) | 4.2470 | 4.24727 | | 1,248.7 | 1,228.3 | 1,251.6 | 1,231.1 |
| CO2 (CO2) | 0.4630 | 0.46299 | | 1 1 | | ample Propertie at Contract Conditions | |
| Methane (C1) | 73.3030 | 73.30183 | | Relative Density Real Relative Density Ideal | | | |
| Ethane (C2) | 12.4460 | 12.44631 | 3.3280 | - 0.75 Molecular N | | 0.7 | 569 |
| Propane (C3) | 5.9780 | 5.97763 | 1.6470 | 21.92 | 248 | | |
| I-Butane (IC4) | 0.7310 | 0.73139 | 0.2390 | 1 | C6+ Group | Properties | |
| . , | 1.5240 | 1.52439 | 0.4800 | 66 60 0000 | Assumed Co | | 10.0000/ |
| N-Butane (NC4) | 0.3470 | 0.34694 | 0.1270 | C6 - 60.000% | C7 - 30. | | 3 - 10.000% |
| I-Pentane (IC5) | _ | ł – | | ┥ | 0 PF | | |
| N-Pentane (NC5) | 0.3010 | 0.30103 | 0.1090 | ┥ | | | |
| Hexanes Plus (C6+) | 0.6600 | 0.66021 | 0.2860 | PROTREND STATUS: | | DATA SOL | |
| TOTAL | 100.0000 | 100.0000 | 6.2160 | Passed By Validator PASSED BY VALIDATO | | 20 Imported | 1 |
| ethod(s): Gas C6+ - GPA 2261, Exte | nded Gas - GPA 2286, Calcula | tions - GPA 2172 | | First sample taken | | mposition looks | reasonable |
| | Analyzer Informa | tion | | VALIDATOR: | | | |

Device Type: Gas Chromatograph Device Make: Shimadzu Device Model: GC-2014 Last Cal Date: Mar 25, 2020 Dustin Armstrong

VALIDATOR COMMENTS:

OK

Mewbourne Oil Company

Natural Gas Flared Calculation Methodology

Metering low-pressure gas diverted from the Vapor Recovery Unit ("VRU") to backup flare is not technologically feasible. Gas volumes for VRU downtime events will be calculated using an average metered VRU gas to oil production ratio. This GOR is derived from available relevant data.

Average Metered VRU Gas to Oil Production GOR = 0.18 Mcf/BBL

Flared gas volume = GOR * Oil Production Volume (BBL)

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

MEWBOURNE OIL CO

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 49517

QUESTIONS

OGRID:

14744

| P.O. Box 5270 Hobbs, NM 88241 | Action Number: 49517 |
|---|--|
| 110525, 1111 002 11 | Action Type: |
| | [C-129] Venting and/or Flaring (C-129) |
| QUESTIONS | |
| Prerequisites | |
| Any messages presented in this section, will prevent submission of this application. Please resolve | these issues before continuing with the rest of the questions. |
| Incident Well | [30-015-46822] PHOENIX 21 22 B2KI FEDERAL COM #001H |
| Incident Facility | Not answered. |
| Determination of Reporting Requirements | |
| Answer all questions that apply. The Reason(s) statements are calculated based on your answers a | nd may provide addional guidance. |
| Was or is this venting and/or flaring caused by an emergency or malfunction | Yes |
| Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event | Yes |
| Is this considered a submission for a venting and/or flaring event | Yes, minor venting and/or flaring of natural gas. |
| An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during v | renting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC. |
| Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event | Yes |
| Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water | No |
| Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence | No |
| - | |
| Equipment Involved | |
| | Other (Specify) |
| Primary Equipment Involved Additional details for Equipment Involved. Please specify | Other (Specify) VRU |

| Representative Compositional Analysis of Vented or Flared Natural Gas | | |
|---|--------------------------|--|
| Please provide the mole percent for the percentage questions in this group. | | |
| Methane (CH4) percentage | 73 | |
| Nitrogen (N2) percentage, if greater than one percent | 4 | |
| Hydrogen Sulfide (H2S) PPM, rounded up | 0 | |
| Carbon Dioxide (C02) percentage, if greater than one percent | 0 | |
| Oxygen (02) percentage, if greater than one percent | 0 | |
| If you are venting and/or flaring because of Pipeline Specification, please provide the required spec | ifications for each gas. | |
| Methane (CH4) percentage quality requirement | Not answered. | |
| Nitrogen (N2) percentage quality requirement | Not answered. | |
| Hydrogen Sufide (H2S) PPM quality requirement | Not answered. | |
| Carbon Dioxide (C02) percentage quality requirement | Not answered. | |
| Oxygen (02) percentage quality requirement | Not answered. | |

| Date(s) and Time(s) | | |
|---|------------|--|
| Date venting and/or flaring was discovered or commenced | 09/08/2021 | |
| Time venting and/or flaring was discovered or commenced | 12:00 AM | |
| Time venting and/or flaring was terminated | 03:00 PM | |
| Cumulative hours during this event | 15 | |

| Measured or Estimated Volume of Vented or Flared Natural Gas | |
|--|---------------|
| Natural Gas Vented (Mcf) Details | Not answered. |
| Natural Sub-Ventod (Wor) Botalie | |

| Natural Gas Flared (Mcf) Details | | Cause: Equipment Failure Other (Specify) Natural Gas Flared Released: 266 Mcf Recovered: 0 Mcf Lost: 266 Mcf] |
|---|------------------------------|--|
| Other Released Details | | Not answered. |
| Additional details for Measured or Estimate | d Volume(s). Please specify | Volume calculated |
| Is this a gas only submission (i.e. only sign | ificant Mcf values reported) | Yes, according to supplied volumes this appears to be a "gas only" report. |

| Venting or Flaring Resulting from Downstream Activity | |
|--|---------------|
| Was or is this venting and/or flaring a result of downstream activity | Not answered. |
| Was notification of downstream activity received by you or your operator | Not answered. |
| Downstream OGRID that should have notified you or your operator | Not answered. |
| Date notified of downstream activity requiring this venting and/or flaring | Not answered. |
| Time notified of downstream activity requiring this venting and/or flaring | Not answered. |

| Steps and Actions to Prevent Waste | |
|--|--|
| For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control. | True |
| Please explain reason for why this event was beyond your operator's control | VRU malfunctioned |
| Steps taken to limit the duration and magnitude of venting and/or flaring | Repaired VRU |
| Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring | Continued routine preventive maintenance and daily operational inspections |

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 49517

CONDITIONS

| Operator: | OGRID: |
|------------------|--|
| MEWBOURNE OIL CO | 14744 |
| P.O. Box 5270 | Action Number: |
| Hobbs, NM 88241 | 49517 |
| | Action Type: |
| | [C-129] Venting and/or Flaring (C-129) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|--|----------------|
| zlacount | If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event. | 9/24/2021 |