

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company	Contact Randall Gladden, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-513-9463
Facility Name Bilbrey 27 A Federal #1	Facility Type Gas
Surface Owner Federal	Mineral Owner Federal
API No 30-025-31095	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	27	21S	32E	1980	North	1980	West	Lea

Latitude: N 32.4515839 **Longitude:** W 103.6647949

NATURE OF RELEASE

Type of Release Spill Produced water	Volume of Release 45 BBLS	Volume Recovered 40 BBLS
Source of Release Water load line	Date and Hour of Occurrence 2/15/2016 @ 4:06pm	Date and Hour of Discovery 2/15/2016 @ 4:06pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher BLM-Jim Amos	
By Whom? Santiago (Jim) Huerta, Assistant Foreman	Date and Hour OCD- 2/15/2016 @ 4:35pm BLM- 2/15/2016 @ 4:30pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

Water hauler backed into the water load line breaking the fiber glass collar resulting in a release from the water load line. The well was immediately shut in and all dump lines were closed going to the tank to prevent further release.

Describe Area Affected and Cleanup Action Taken.*

45 BBLS of produced water was released from the water load line into unlined bermed secondary containment. The approximate area affected was 25ft x 20ft within the bermed containment. All 45 BBLS produced water released remained in bermed containment. None of the released fluid left location. Vacuum truck recovered approximately 40 BBLS of the released produced water. The Trucking company has contacted an Environmental Agency for remediation.

This well has been plugged and abandoned, remediation activities were completed alongside reclamation activities. Closure report submitted 10/25/2018.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION	
Printed Name: Sarah Gallegos-Troublefield	Approved by Environmental Specialist: <i>Bradford Billings</i>	
Title: Field Admin Support	Approval Date: 09/28/2021	Expiration Date:
E-mail Address: Sarah.Gallegos-Troublefield@dm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/17/2016 Phone: 575.748.1864	None	

* Attach Additional Sheets If Necessary

nJXK1604933416 - Closure report in imaging file is not signed, the above 141 covers this issue.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 8096

CONDITIONS

Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137
	Action Number: 8096
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
bbillings	Report not attached but found in imaging file C-141 OLD style is now signed.	9/28/2021