District I 1625 N. French Dr., Hobbs, NM 88240 District III 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

32.2672272

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2126755564
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	OXY USA INC.	OGRID	16696
Contact Name	WADE DITTRICH	Contact Telephone	(575) 390-2828
Contact email	WADE_DITTRICH@OXY.COM	Incident # (assigned by OCD)	
Contact mailing address	PO BOX 4294; HOUSTON, TX	77210	

Location of Release Source

Latitude

Longitude ______ (NAD 83 in decimal degrees to 5 decimal places)

103.9744339

Site Name		CYPRESS 34 0007H			Site Type	
Date Release Discovered 9-19-21			API# (if applicable) 30-015-39219			
Unit Letter	Section	Township	Range		County	

Onn Letter	occuon	remanp	runge	County
	34	23S	29E	EDDY

Surface Owner: State Federal Tribal Private (Name:

Nature and Volume of Release

Crude Oil	Volume Released (bbls) 5bbls	Volume Recovered (bbls)
Produced Water	Volume Released (bbls) 29bbls	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

4" flowline -3rd party line strike

Received by OCD: 10/14/2021 5:27:02 PM

Form C-141	State of New Mexico		
	Oil Conservation Division	Incident ID	nAPP2126755564
Page 2	Oil Conservation Division	District RP	
		Facility ID	
		Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?
🗌 Yes 🔳 No	
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Wade Dittrich	Title: Environmental Coordinator
Signature: Kall Stock	Date: 9-29-21
email: wade_dittrich@oxy.com	Telephone: (575) 390-2828
OCD Only	
Received by: Ramona Marcus	Date: 10/18/2021

Received by OCD: 10/14/2021 5:27:02 PM Location of spill: Cy

****** LIQUID SPILLS - VOLUME CALCULATIONS ******

NAPP2126755564

9/19/2021

Page 3 of

Cypress 34 0007H

Date of Spill:

Site Soil Type: Fine Sand

					BBL Water	
	Tota	Area Calcul	ations			
Total Surface Area	width		length		wet soil depth	oil (%)
Rectangle Area #1	0 ft	Х	<mark>0</mark> ft	Х	0 in	17%
Rectangle Area #2	0 ft	Х	0 ft	Х	0 in	17%
Rectangle Area #3	0 ft	Х	0 ft	Х	0 in	0%
Rectangle Area #4	0 ft	Х	0 ft	Х	0 in	0%
Rectangle Area #5	0 ft	Х	0 ft	Х	0 in	0%
Rectangle Area #6	0 ft	Х	0 ft	Х	0 in	0%
Rectangle Area #7	0 ft	Х	0 ft	Х	0 in	0%
Rectangle Area #8	0 ft	Х	0 ft	Х	0 in	0%

Porosity_ 0.16 gal per gal

Saturated	Soil Volume Calculations:				
		<u>H2O</u>	OIL	Soil Type	Porosity
Area #1	0 sq. ft.	cu. ft.	cu. ft.	Clay	0.15
Area #2	0 sq. ft.	cu. ft.	cu. ft.	Peat	0.40
Area #3	0 sq. ft.	cu. ft.	cu. ft.	Glacial Sediment	s 0.13
Area #4	0 sq. ft.	cu. ft.	cu. ft	. Sandy Clay	0.12
Area #5	0 sq. ft.	cu. ft.	cu. ft	Silt	0.16
Area #6	0 sq. ft.	cu. ft.	cu. ft.	Loess	0.25
Area #7	0 sq. ft.	cu. ft.	cu. ft.	. Fine Sand	0.16
Area #8	0 sq. ft.	cu. ft.	cu. ft.	. Medium Sand	0.25
otal Solid/Liquid Volume:	sq. ft.	cu. ft.	cu. ft	t. Coarse Sand	0.26
				Gravely Sand	0.26
Estimated	Volumes Spilled			Fine Gravel	0.26
		<u>H2O</u>	OIL	Medium Gravel	0.25
Liquic	l in Soil:	0.0 BBL	0.0 BBL	Coarse Gravel	0.18
Liquid Rec	overed :	<u>0.0</u> BBL	<u>0.0</u> BBL	Sandstone	0.25
				Siltstone	0.18
Spi	ill Liquid	0.0 BBL	0.0 BBL	Shale	0.05
Total Spil	l Liquid:	0.0		Limestone	0.13
				Basalt	0.19
Recove	ered Volumes			Volcanic Tuff	0.20
Estimated oil recovered:	0.0 BBL			Standing Liquids	
stimated water recovered:	0.0 BBL				

Released to Imaging: 10/18/2021 8:57:27 AM

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	56203
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	10/18/2021

CONDITIONS

Page 4 of 4

.

Action 56203