State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Page 1 of 4

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	OGRID
Contact Name	Contact Telephone
Contact email	Incident # (assigned by OCD)
Contact mailing address	

Location of Release Source

1

Latitude	
	(NAD 83 in decimal degrees to 5 decimal places)
Site Name	Site Type

Site Name	Site Type
Date Release Discovered	API# (if applicable)

Unit Letter	Section	Township	Range	County

Surface Owner: State Federal Tribal Private (Name: _

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
Cause of Release		

Incident ID	
District RP	
Facility ID	
Application ID	

Page 2 of 4

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?
Yes No	
If YES, was immediate ne	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

The source of the release has been stopped.

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name	Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:Ramona Marcus	Date:

Page 2

E40 Opin Volume Estimate Form

Received by OCD: 10	OCD: 10/25/2021 8:28:154/ Altrine & Number: Eata Fajita C CTB UL 0 SEC.8-T24S-R33E Lea County Page 3 of 4							Page 3 of 4				
			Asset Area:	Delaware Basin Nort	elaware Basin North East NAPP2129830369							
	Relea	se Disco	overy Date & Time:	10/7/2021 0700								
			Release Type:	Produced Water								
Provide	any kno	wn detail	Is about the event:	Liquid back pressure	valve developed	hole dime size, l	ast visit at this facil	ity was on 10/6/2021 at	11:00 am.			
					Spi	Il Calculation	- On Pad Surface	e Pool Spill				
Convert Irregular shape into a series of rectangles	Length (ft.)	Width (ft.)	Deepest point in each of the areas (in.)	No. of boundaries of "shore" in each area		Contraction and the second	Estimated volume of each pool area (bbl.)	Penetration allowance (ft.)	Total Estimated Volume of Spill (bbl.)	Percentage of Oil if Spilled Fluid is a Mixture	Total Estimated Volume of Spilled Oil (bbl.)	Total Estimated Volume of Spilled Liquid other than Oil (bbl.)
Rectangle A	85.0	23.0	1.00	4	1955.000	0.021	7.250	0.001	7.257			
Rectangle B					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!			
Rectangle C					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!			
Rectangle D					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!			
Rectangle E					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!			
Rectangle F					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!			
Rectangle G					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!			
Rectangle H					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!			
Rectangle I					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!			
Rectangle J Released to Imaging:	10/20/20	121.10.01	1.02 AM		0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!			
Acteused to Imaging.	10/27/20	<u></u>	1.05 /11/1					Total Volume Release:	7.257			

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
COG OPERATING LLC	229137
600 W Illinois Ave	Action Number:
Midland, TX 79701	57590
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	10/29/2021

CONDITIONS

Page 4 of 4

.

Action 57590