

Incident ID	
District RP	
Facility ID	
Application ID	


## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

**Closure Report Attachment Checklist:** *Each of the following items must be included in the closure report.*

- ☒ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☒ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☒ Description of remediation activities


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Jacqui Harris Title: Sr. Environmental Engineer  
Signature:  Date: 1/10/22  
email: Jacqui.Harris@ConocoPhillips.com Telephone: (575) 496-0780

**OCD Only**

Received by: Chad Hensley Date: 02/03/2022

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by:  Date: 02/03/2022  
Printed Name: Chad Hensley Title: Environmental Specialist Advanced



---

*Site Information*

---

**Closure Report**

**Magnum Pronto State Com 005H (08.11.21)**

**Lea County, New Mexico**

**Unit O, S32, T19S, R32E**

**32.61014°, -103.78721°**

**Crude Oil**

**Source: Line on oil dump corroding**

**Release Date: 08/11/2021**

**Volume Released: 6 bbls/Crude Oil**

**Volume Recovered: 3 bbls/Crude Oil**

**Prepared for:**

**Concho Operating, LLC**

**15 West London Rd**

**Loving, NM 88256**

**Prepared by:**

**NTG Environmental**

**701 Tradewinds Blvd**

**Suite C**

**Midland, TX 79706**



## **TABLE OF CONTENTS**

### **FIGURES**

FIGURE 1	OVERVIEW MAP
FIGURE 2	TOPOGRAPHIC MAP
FIGURE 3	SECONDARY CONTAINMENT MAP

### **TABLES/PHOTOLOG**

PHOTOS	PHOTOLOG
--------	----------

### **APPENDICES**

APPENDIX A	C-141 INITIAL AND FINAL
APPENDIX B	GROUNDWATER RESEARCH



701 Tradewinds Boulevard, Suite C  
Midland, Texas 79706  
Tel. 432.685.3898  
www.ntglobal.com

01/12/2022

New Mexico Oil Conservation Division  
1220 South St, Francis Drive  
Sante Fe, NM 87505

**Re: Closure Report**  
**Magnum Pronto State Com 005H (08.11.21)**  
**Concho Operating, LLC**  
**Site Location: Unit O, S32, T19S, R32E**  
**(Lat 32.61014°, Long -103.78721°)**  
**Lea County, New Mexico**

To Whom it may concern:

On behalf of Concho Operating, LLC (COG), New Tech Global Environmental, LLC (NTGE) has prepared this letter to document the liner inspection activities for the Magnum Pronto State Com 005H (08.11.21). The site is located at 32.61014°, -103.78721° within Unit O, S32, T19S, R32E, in Lea County (Figures 1 and 2).

### **Background**

Based on the initial C-141 obtained from the New Mexico Oil Conservation Division (NMOCD), the release was discovered on August 11, 2021, due to a line on the oil dump corroding. It resulted in the release of approximately six (6) barrels of crude oil. Approximately three (3) barrels of crude oil were recovered. The initial C-141 form is attached in Appendix A.

### **Site Characterization**

The site is located within a low karst area. Based on a review of the New Mexico Office of State Engineers database, there is no known water well source within a ½ mile radius of the location. The nearest identified well is located approximately 2.65 miles Northwest of the site in S19, T19S, R32E. The well has a reported depth to groundwater of 345 feet below ground surface (ft bgs). A copy of the associated *Point of Diversion Summary* report is attached in Appendix B.

### **Regulatory Criteria**

In accordance with the NMOCD regulatory criteria established in 19.15.29.12 NMAC, the following criteria were utilized in assessing the site.

- Benzene: 10 milligrams per kilogram (mg/kg).
- Benzene, toluene, ethylbenzene, and total xylenes (BTEX): 50 mg/kg.
- TPH: 100 mg/kg (GRO + DRO + MRO).
- Chloride: 600 mg/kg.



### **Liner Inspection**

On November 9, 2021a, 3<sup>rd</sup> party company conducted liner inspection activities to assess the liner's integrity within the facility. The personnel proceeded to inspect the liner visually. The liner was found to be intact with no integrity issues. Refer to the Photolog.

### **Conclusions**

Based on the liner inspection throughout the facility, no further actions are required at the site. The final C-141 is attached, and COG formally requests closure of the spill. If you have any questions regarding this report or need additional information, please contact us at 432-813-0263.

Sincerely,


**NTG Environmental**

A handwritten signature in black ink, appearing to read "Mike Carmona", is positioned above the printed name and title.

Mike Carmona  
Senior Project Manager



## *Figures*



Document Path: P:\Full Figure Template Revised.aprx

**SITE LOCATION MAP**  
**COG OPERATING, LLC**  
 MAGNUM PRONTO STATE COM 005H (8.11.21)  
 LEA COUNTY, NEW MEXICO  
 32.61014, -103.78721

SCALE: As Shown

Date: 1/12/2022

PROJECT #: 225123



**New Tech Global Environmental, LLC**  
 911 Regional Park Drive  
 Houston, Texas 77060  
 T - 281.872.9300  
 F - 281.872.4521  
 Web: www.ntglobal.com

**NOTES:**


1. Base Image: ESRI Maps & Data 2013
2. Map Projection: NAD 1983 UTM Zone 13N

DRAWING NUMBER:

**FIGURE 1**

SHEET NUMBER:

**1 of 1**





**SECONDARY CONTAINMENT MAP**  
**COG OPERATING, LLC**  
MAGNUM PRONTO STATE COM 005H (8.11.21)  
LEA COUNTY, NEW MEXICO  
32.61014, -103.78721

SCALE: As Shown

Date: 1/12/2022

PROJECT #: 225123



**New Tech Global Environmental, LLC**  
911 Regional Park Drive  
Houston, Texas 77060  
T - 281.872.9300  
F - 281.872.4521  
Web: www.ntglobal.com

**NOTES:**

1. Base Image: ESRI Maps & Data 2013
2. Map Projection: NAD 1983 UTM Zone 13N

DRAWING NUMBER:

**FIGURE 3**

SHEET NUMBER:

**1 of 1**

Document Path: P:\Full Figure Template Revised.aprx





## *Photo Log*

# COG, Magnum Pronto State Com 005H

## Liner Inspection Photos



Liner picture 1



Liner picture 2



Liner picture 3



Liner picture 4



Liner picture 5



Liner picture 6






Liner picture 7



Liner picture 8



Liner picture 9



Liner picture 10



Liner picture 11



Liner picture 12



# COG, Magnum Pronto State Com 005H

## Liner Inspection Photos



**Liner picture 13**



**Liner picture 14**



**Liner picture 15**



**Liner picture 16**



**Liner picture 17**



**Liner picture 18**



## *Appendix A*

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party	OGRID
Contact Name	Contact Telephone
Contact email	Incident # (assigned by OCD)
Contact mailing address	

### Location of Release Source

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Site Type
Date Release Discovered	API# (if applicable)

Unit Letter	Section	Township	Range	County

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
Cause of Release		

State of New Mexico  
Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

**Initial Response**

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input type="checkbox"/> The source of the release has been stopped.	
<input type="checkbox"/> The impacted area has been secured to protect human health and the environment.	
<input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.	
<input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: _____	Title: _____
Signature: <u>Patricia Espinoza</u>	Date: _____
email: _____	Telephone: _____
<b><u>OCD Only</u></b>	
Received by: _____	Date: _____

Received by OCD: 1/14/2022 9:55:43 AM

Released to Imaging: 2/3/2022 8:21:07 AM

L48 Spill Volume Estimate Form

Page 17 of 28

Facility Name & Number:					MAGNUM PRONTO #5								
Asset Area:					NDBW								
Release Discovery Date & Time:					8/11/2021								
Release Type:					Oil								
Provide any known details about the event:													
Spill Calculation - On Pad Surface Pool Spill													
Convert Irregular shape into a series of rectangles	Length (ft.)	Width (ft.)	Deepest point in each of the areas (in.)	No. of boundaries of "shore" in each area	Estimated <u>Pool</u> Area (sq. ft.)	Estimated Average Depth (ft.)	Estimated volume of each pool area (bbl.)	Penetration allowance (ft.)	Total Estimated Volume of Spill (bbl.)	Percentage of Oil if Spilled Fluid is a Mixture	Total Estimated Volume of Spilled Oil (bbl.)	Total Estimated Volume of Spilled Liquid other than Oil (bbl.)	
Rectangle A	30.0	10.0	1.00	1	300.000	0.083	4.450	0.004	4.469				
Rectangle B	15.0	10.0	1.00	2	150.000	0.042	1.113	0.002	1.115				
Rectangle C	5.0	8.0	1.00	2	40.000	0.042	0.297	0.002	0.297				
Rectangle D					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!				
Rectangle E					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!				
Rectangle F					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!				
Rectangle G					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!				
Rectangle H					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!				
Rectangle I					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!				
Rectangle J					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!				
Total Volume Release:									5.881				



Incident ID	
District RP	
Facility ID	
Application ID	

## Site Assessment/Characterization

*This information must be provided to the appropriate district office no later than 90 days after the release discovery date.*

What is the shallowest depth to groundwater beneath the area affected by the release?	_____ (ft bgs)
Did this release impact groundwater or surface water?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a wetland?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release overlying a subsurface mine?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release overlying an unstable area such as karst geology?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within a 100-year floodplain?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.

### **Characterization Report Checklist:** *Each of the following items must be included in the report.*

- ☐ Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.
- ☐ Field data
- ☐ Data table of soil contaminant concentration data
- ☐ Depth to water determination
- ☐ Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release
- ☐ Boring or excavation logs
- ☐ Photographs including date and GIS information
- ☐ Topographic/Aerial maps
- ☐ Laboratory data including chain of custody

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

State of New Mexico  
Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: \_\_\_\_\_ Title: \_\_\_\_\_

Signature: Jacqueline Heredia Date: \_\_\_\_\_

email: \_\_\_\_\_ Telephone: \_\_\_\_\_

**OCD Only**

Received by: \_\_\_\_\_ Date: \_\_\_\_\_

Incident ID	
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

**Closure Report Attachment Checklist:** *Each of the following items must be included in the closure report.*

- ☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☐ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☐ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: \_\_\_\_\_ Title: \_\_\_\_\_

Signature:  Date: \_\_\_\_\_

email: \_\_\_\_\_ Telephone: \_\_\_\_\_

### OCD Only

Received by: \_\_\_\_\_ Date: \_\_\_\_\_

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: \_\_\_\_\_ Date: \_\_\_\_\_

Printed Name: \_\_\_\_\_ Title: \_\_\_\_\_





## *Appendix B*

# Magnum Pronto State Com 005H


Low Karst

**Legend**

-  HIGH
-  LOW
-  MEDIUM

126A

126A

32.61014 -103.78721 

  
N

  
2000 ft



Nearest water well

COG Operating, LLC

Legend

Page 23 of 28


 0.50 Mile Radius

 2.65 Miles

 3.0 Miles

 Drilled 1982

 Magnum Pronto







# New Mexico Office of the State Engineer

## Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.)

(R=POD has been replaced,  
O=orphaned,  
C=the file is closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

(In feet)

POD Number	Code	POD Sub-basin	County	Q 64	Q 16	Q 4	Sec	Tws	Rng	X	Y	DepthWell	DepthWater	Water Column
<a href="#">CP 00075</a>	O	CP	LE	2	4	34	19S	32E		617502	3609301	575		
<a href="#">CP 00563 POD1</a>		CP	LE	1	1	2	19S	32E		612118	3613376*	300		
<a href="#">CP 00639 POD1</a>		CP	LE	3	1	20	19S	32E		613029	3612880*	350	345	5
<a href="#">CP 00640 POD1</a>		CP	LE	2	2	19	19S	32E		612621	3613280*	260	102	158
<a href="#">CP 00812 POD1</a>		CP	LE	4	4	01	19S	32E		620623	3616973*	200		
<a href="#">CP 01656 POD1</a>		CP	LE	3	4	3	17S	32E		613368	3613646	70		
<a href="#">CP 01656 POD2</a>		CP	LE	3	4	3	17S	32E		613364	3613648	70		
<a href="#">CP 01656 POD3</a>		CP	LE	3	4	3	17S	32E		613374	3613633	30		

Average Depth to Water: **223 feet**

Minimum Depth: **102 feet**

Maximum Depth: **345 feet**

**Record Count:** 8

**PLSS Search:**

**Township:** 19S **Range:** 32E

\*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

1/12/22 3:01 PM

WATER COLUMN/ AVERAGE DEPTH TO WATER



# New Mexico Office of the State Engineer

## Point of Diversion Summary

		(quarters are 1=NW 2=NE 3=SW 4=SE)				(NAD83 UTM in meters)	
		(quarters are smallest to largest)				X	Y
<b>Well Tag</b>	<b>POD Number</b>	<b>Q64</b>	<b>Q16</b>	<b>Q4</b>	<b>Sec</b>	<b>Tws</b>	<b>Rng</b>
CP 00640	POD1	2	2	19	19S	32E	612621 3613280*
<b>Driller License:</b> 882		<b>Driller Company:</b> LARRY'S DRILLING & PUMP CO.					
<b>Driller Name:</b> FELKINS, LARRY							
<b>Drill Start Date:</b> 02/08/1982	<b>Drill Finish Date:</b> 02/09/1982		<b>Plug Date:</b>				
<b>Log File Date:</b> 03/04/1982	<b>PCW Rcv Date:</b>		<b>Source:</b> Shallow				
<b>Pump Type:</b>	<b>Pipe Discharge Size:</b>		<b>Estimated Yield:</b>				
<b>Casing Size:</b>	<b>Depth Well:</b> 260 feet		<b>Depth Water:</b> 102 feet				

\*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

1/12/22 3:16 PM

POINT OF DIVERSION SUMMARY



# New Mexico Office of the State Engineer

## Point of Diversion Summary

		(quarters are 1=NW 2=NE 3=SW 4=SE) (quarters are smallest to largest)						(NAD83 UTM in meters)	
Well Tag	POD Number	Q64	Q16	Q4	Sec	Tws	Rng	X	Y
	CP 00639 POD1	3	1	20	19S	32E		613029	3612880*
<hr/>									
<b>Driller License:</b> 882		<b>Driller Company:</b> LARRY'S DRILLING & PUMP CO.							
<b>Driller Name:</b> FELKINS, LARRY									
<b>Drill Start Date:</b> 02/09/1982		<b>Drill Finish Date:</b> 02/10/1982				<b>Plug Date:</b>			
<b>Log File Date:</b> 03/23/1982		<b>PCW Rev Date:</b>				<b>Source:</b> Shallow			
<b>Pump Type:</b>		<b>Pipe Discharge Size:</b>				<b>Estimated Yield:</b>			
<b>Casing Size:</b>		<b>Depth Well:</b> 350 feet				<b>Depth Water:</b> 345 feet			

\*UTM location was derived from PLSS - see Help


The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

1/12/22 3:05 PM


POINT OF DIVERSION SUMMARY



## New Mexico NFHL Data



January 12, 2022



FEMA  
Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS,

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS  
  
Action 72481

CONDITIONS

Operator: COG OPERATING LLC 600 W Illinois Ave Midland, TX 79701	OGRID: 229137
	Action Number: 72481
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
chensley	None	2/3/2022