District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2104354470
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party LOGOS Operating, LLC	OGRID 289408
Contact Name Marie E. Florez	Contact Telephone 505-419-8420
Contact email mflorez@logosresoucesllc.com	Incident # (assigned by OCD) nAPP2104354470
Contact mailing address 2010 Afton Place, Farmington NM 8740	1

Location of Release Source

Latitude

36.5320892

Longitude __107.0992355 (NAD 83 in decimal degrees to 5 decimal places)

Site Name Jicarilla 95 7B	Site Type Well
Date Release Discovered 2/1/2021	API# (<i>if applicable</i>) 30-039-26854

Unit Letter	Section	Township	Range	County
F	36	27N	3W	Rio Arriba

Surface Owner: State Federal Tribal X Private (*Name:* Jicarilla)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Volume Released (bbls)	Volume Recovered (bbls)
Volume Released (bbls)	Volume Recovered (bbls)
Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Volume Released (bbls) 1/4 bbls	Volume Recovered (bbls) 0
Volume Released (Mcf)	Volume Recovered (Mcf)
Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
	Volume Released (bbls) Is the concentration of dissolved chloride in the produced water >10,000 mg/l? Volume Released (bbls) 1/4 bbls Volume Released (Mcf)

Cause of Release

This release was from an oil dump line freeze that sprayed 1/4bbl from the separator. The surface owner (Jicarilla) requested to for LOGOS to remove the separator to clean historic staining under and around the separator. As Kelley Service's scraped and removed the staining, they was hauled off and disposed >20 yards at Envirotech land farm. The release was reported to NMOCD, per the calculations that if 12 yards filled a dump truck this equals 5bbls which than became reportable.

Page 2

		Page 2 of
Incident ID	nAPP2104354470	
District RP		
Facility ID		
Application ID		

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?
Yes X No	
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 $\overline{\mathbf{X}}$ The source of the release has been stopped.

X The impacted area has been secured to protect human health and the environment.

x Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

X All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Marie E. Florez	Title: Regulatory Specialist
Signature: Marie E. Florez	Date: 2/12/2021
email: mflorez@logosresourcesllc.com	Telephone:505-419-8420
OCD Only	
Received by: Jennifer Nobui	Date: 02/08/2022

Initial C141 Approved

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
LOGOS OPERATING, LLC	289408
2010 Afton Place	Action Number:
Farmington, NM 87401	18160
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By		Condition Date
jnobui	Initial Response approved.	2/8/2022

Page 3 of 3

Action 18160