

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2204943884
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party XTO Energy	OGRID 5380
Contact Name Adrian Baker	Contact Telephone 432-236-3808
Contact email adrian.baker@exxonmobil.com	Incident # (assigned by OCD)
Contact mailing address 6401 Holiday Hill Rd Bldg 5, Midland, Texas, 79707	

Location of Release Source

Latitude 32.36851 Longitude -103.86746
(NAD 83 in decimal degrees to 5 decimal places)

Site Name JRU Legg Battery	Site Type Tank Battery
Date Release Discovered 02/04/2022	API# (if applicable)

Unit Letter	Section	Township	Range	County
B	27	22S	30E	Eddy

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input checked="" type="checkbox"/> Condensate	Volume Released (bbls) 580.0	Volume Recovered (bbls) 580.0
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)


Cause of Release Freezing weather caused a Victaulic clamp to fail, releasing fluids into impermeable cotainment. All fluids were recovered. A 48-hour liner inspection notice was sent to NMOCD District 2. Liner was inspected and determined not to be operating as designed. A third-party contractor has been retained for remediation purposes.

Incident ID	NAPP2204943884
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? A release equal to or greater than 25 barrels.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Yes, by Garrett Green to Mike Bratcher' <mike.bratcher@state.nm.us>; 'Victoria Venegas' <Victoria.Venegas@state.nm.us>; 'Rob Hamlet' <robert.hamlet@state.nm.us>; 'emily.hernandez@state.nm.us' on Saturday, February 5, 2022 5:37 PM via email.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped.	
<input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment.	
<input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.	
<input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: NA	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: Adrian Baker	Title: SSHE Coordinator
Signature: 	Date: 2/18/22
email: adrian.baker@exxonmobil.com	Telephone: 432-236-3808
<u>OCD Only</u>	
Received by: Ramona Marcus	Date: 2/21/2022

Location:	JRU Legg Battery	
Spill Date:	2/4/2022	
Area 1		
Approximate Area =	3256.46	cu.ft.
VOLUME OF LEAK		
Total Condensate =	580.00	bbls
Total Produced Water =	0.00	bbls
TOTAL VOLUME OF LEAK		
Total Condensate=	580.00	bbls
Total Produced Water =	0.00	bbls
TOTAL VOLUME RECOVERED		
Total Condensate=	580.00	bbls
Total Produced Water =	0.00	bbls

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 82673

CONDITIONS

Operator: XTO ENERGY, INC 6401 Holiday Hill Road Midland, TX 79707	OGRID: 5380
	Action Number: 82673
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	2/21/2022