

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2205753600
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party TAP ROCK OPERATING, LLC	OGRID 372043
Contact Name CHRISTIAN COMBS	Contact Telephone (720)360-4028
Contact email ccombs@taprk.com	Incident # <i>(assigned by OCD)</i>
Contact mailing address 523 Park Point Dr. #200	Golden CO, 80401

Location of Release Source

Latitude **32.196598** Longitude **-103.597932**
(NAD 83 in decimal degrees to 5 decimal places)

Site Name BETTIS 20 STATE COM #004H	Site Type PRODUCTION
Date Release Discovered 2/26/22	API# <i>(if applicable)</i> 30-025-41438

Unit Letter	Section	Township	Range	County
N	20	24S	33E	LEA COUNTY

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 10.04BBLS	Volume Recovered (bbls) 0BBLS
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

THE FLOAT IN THE FLARE SCRUBBER FAILED, CAUSING FLUID TO BE SPRAYED OUT INTO THE PASTURE AREA.

NAPP2205753600

Soil Type	Porosity	Length	Width	Depth (.083 per inch)	Cubic Feet	Estimated Barrels	Soil Type
Clay	0.15	10	10	0.083	8.3	0.22	Clay
Peat	0.40	10	10	0.083	8.3	0.59	Peat
Glacial Sediments	0.13	10	10	0.083	8.3	0.19	Glacial Sediments
Sandy Clay	0.12	10	10	0.083	8.3	0.18	Sandy Clay
Silt	0.16	10	10	0.083	8.3	0.24	Silt
Loess	0.25	10	10	0.083	8.3	0.37	Loess
Fine Sand	0.16	332.35	127.66	0.0083	352.15075	10.04	Fine Sand
Medium Sand	0.25	10	10	0.083	8.3	0.37	Medium Sand
Coarse Sand	0.26	10	10	0.083	8.3	0.38	Coarse Sand
Gravelly Sand	0.26	10	10	0.083	8.3	0.38	Gravelly Sand
Fine Gravel	0.26	10	10	0.083	8.3	0.38	Fine Gravel
Medium Gravel	0.20	10	10	0.083	8.3	0.30	Medium Gravel
Coarse Gravel	0.18	10	10	0.083	8.3	0.27	Coarse Gravel
Sandstone	0.25	10	10	0.083	8.3	0.37	Sandstone
Siltstone	0.18	10	10	0.083	8.3	0.27	Siltstone
Shale	0.05	10	10	0.083	8.3	0.07	Shale
Limestone	0.13	10	10	0.083	8.3	0.19	Limestone
Basalt	0.19	10	10	0.083	8.3	0.28	Basalt
Volcanic Tuff	0.20	10	10	0.083	8.3	0.30	Volcanic Tuff
Standing Liquids	X	10	10	0.083	8.3	1.48	Standing Liquids

1	2	3	4	5	6
0.083	0.166	0.250	0.332	0.415	0.500
7	8	9	10	11	12
0.581	0.664	0.750	0.830	0.913	1.000

NOTE: This is an **estimate** tool designed for quick field estimates of whether a C-141 should be required (i.e. a release is estimated to be greater than or less than 5 barrel volumes)

Choose the one prevailing ground type for estimating spill volumes at a single location.

Note that the depth should be measured in feet and tenths of feet (1 inch = .083)

Cubic Feet = L x W x D

Estimated Barrels = ((Cubic Feet x Porosity) / 5.61)

NAPP2205753600

Natalie Gladden

To: ocdonline, emnrd, EMNRD; Bratcher, Mike, EMNRD; Hensley, Chad, EMNRD; Hamlet, Robert, EMNRD
Cc: 'Bill Ramsey'; Christian Combs; dakoatah@energystaffingllc.com; Eddie Gaytan
Subject: TAP ROCK - RELEASE NOTIFICATION - BETTIS 20 STATE COM #004H
Importance: High

All,

Please use this email as the release notification for the following site:

Tap Rock Operating

Site: Bettis 20 State Com #004H

DOR: 2/26/22

Cause of Release: The float in the flare scrubber failed, causing the fluid to be sprayed out into the pasture area.

Volume Released: 10.04bbbls of produced water

Volume Recovered: 0bbbls as it was a spray only

A C141 and spill calculator form will be uploaded to the NMOCD portal shortly.

Sincerely,

Natalie Gladden

Director of Environmental and Regulatory Services

Energy Staffing Services, LLC.

2724 NW County Road

Hobbs, NM 88240

Cell: 575-390-6397

Office: 575-393-9048

Email: natalie@energystaffingllc.com



District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 84497

CONDITIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 84497
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	3/1/2022