District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2207748537
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

r EOG Resources, IIIc.		OGRID	7377				
Contact Name Jeremy Haass		Contact Telephone 575-748-1471					
Contact email Jeremy Haass@eogresources.com		Incident #	nAPP2207748537				
Contact mail	ing address	104 S. 4th Stre	et, Artesia, NN	л 8821	.0		
Location of Release Source							
Latitude 32.	505287]	Longitude _	-104.68875	
			(NAD 83 in dec	cimal deg	rees to 5 decim	al places)	
Site Name L	uke BAV F	ederal Com #1			Site Type V	Nellhead	
Date Release	Discovered	3/17/2022			API# 30-015	i-31947	
	Γ ~ .						
Unit Letter	Section	Township	Range		Coun	ty	
J	3	21S	22E		Eddy		
Surface Owner	r: State	✓ Federal ☐ Tr	ibal Private (/	Name: _			
Nature and Volume of Release							
					ons or specific	justification for the	volumes provided below)
Crude Oil				Volume Recov	vered (bbls)0		
✓ Produced	d Water Volume Released (bbls) Unknown			Volume Recov	vered (bbls) 0		
Is the concentration of dissolved chloride produced water >10,000 mg/l?		in the	Yes No				
Condensa				Volume Recovered (bbls)			
Natural Gas Volume Released (Mcf)			Volume Recovered (Mcf)				
Other (describe) Volume/Weight Released (provide units)			Volume/Weigh	nt Recovered (provide units)			
Cause of Release Historical impacts discovered beside the wellhead, no release volume is known or can be calculated. The environmental consultant investigating the impacted area determined on 03/17/2022 that due							
	to the size of the impacted area footprint, that it most likely crossed the threshold for being a reportable quantity.						

- 73				0
···	age	, 7	0	t i
-	$u \simeq c$	- 4	v	•

Incident ID	NAPP2207748537
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☐ Yes ☑ No	If YES, for what reason(s) does the respon	sible party consider this a major release?
If YES, was immediate no	otice given to the OCD? By whom? To wh	om? When and by what means (phone, email, etc)?
	Initial Re	esponse
The responsible	party must undertake the following actions immediatel	vunless they could create a safety hazard that would result in injury
✓ The impacted area ha✓ Released materials ha	ease has been stopped. s been secured to protect human health and ave been contained via the use of berms or decoverable materials have been removed and	ikes, absorbent pads, or other containment devices.
	d above have <u>not</u> been undertaken, explain v	
has begun, please attach	a narrative of actions to date. If remedial	emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred lease attach all information needed for closure evaluation.
regulations all operators are public health or the environr failed to adequately investig	required to report and/or file certain release notified ment. The acceptance of a C-141 report by the Oate and remediate contamination that pose a threatening the contamination of the contamination	pest of my knowledge and understand that pursuant to OCD rules and frications and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws
Printed Name: Jeremy	Haass	Title: Sr. Safety & Environmental Specialist
Signature: Ty Hus	25	Date: 3/18/2022
email: jeremy_haass@		Telephone: 575-748-1471
OCD Only Received by: Jocelyn H	darimon	Date: 03/21/2022

Received by OCD: 3/19/2022 4:51:51 PM Form C-141 State of New Mexico Page 3 Oil Conservation Division

	1 48000
Incident ID	
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)	
Did this release impact groundwater or surface water?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No	
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No	
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No	
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No	
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No	
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No	
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No	
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ☐ No	
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.		
Characterization Report Checklist: Each of the following items must be included in the report.		
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody		

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 3/19/2022 4:51:51 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name:	_ Title:	
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	

Received by OCD: 3/19/2022 4:51:51 PM Form C-141 State of New Mexico Page 5 Oil Conservation Division

	I uge 5 of
Incident ID	
District RP	
Facility ID	
Application ID	

Remediation Plan

Remediation Plan Checklist: Each of the following items must b	e included in the plan.	
 □ Detailed description of proposed remediation technique □ Scaled sitemap with GPS coordinates showing delineation poin □ Estimated volume of material to be remediated □ Closure criteria is to Table 1 specifications subject to 19.15.29. □ Proposed schedule for remediation (note if remediation plan tin 	12(C)(4) NMAC	
Deferral Requests Only: Each of the following items must be con-	nfirmed as part of any request for deferral of remediation.	
Contamination must be in areas immediately under or around p deconstruction.	roduction equipment where remediation could cause a major facility	
Extents of contamination must be fully delineated.		
Contamination does not cause an imminent risk to human healt	n, the environment, or groundwater.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name:	Title:	
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	
☐ Approved	Approval	
Signature:	Date:	

Received by OCD: 3/19/2022 4:51:51 PM Form C-141 State of New Mexico Page 6 Oil Conservation Division

	Page 6 of
Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

A scaled site and sampling diagram as described in 19.15.29.11 NMAC			
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)			
☐ Laboratory analyses of final sampling (Note: appropriate ODG	C District office must be notified 2 days prior to final sampling)		
☐ Description of remediation activities			
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name: Title: Title:			
Signature:	Date:		
email:	Telephone:		
OCD Only			
Received by:	Date:		
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.			
remediate contamination that poses a threat to groundwater, surface	water, human health, or the environment nor does not relieve the responsible		
remediate contamination that poses a threat to groundwater, surface	water, human health, or the environment nor does not relieve the responsible or regulations.		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 91386

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267 Midland, TX 79702	Action Number: 91386
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jharimon	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141	3/21/2022