<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural** Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2209041864
District RP	
Facility ID	
Application ID	94798

Release Notification

			Resp	onsible .	Party
Responsible	Party: Nov	o Oil & Gas Nort	hern Delaware, I	LLC OG	RID 372920
Contact Nam	e: Kurt A.	Shipley		Cor	tact Telephone: 405-286-3916
Contact emai	il: kshipley	@novoog.com		Inci	dent # (assigned by OCD): nAPP2209041864
Contact mail Oklahoma (1001 West Wils 116	shire Blvd., Suite	206	
			Location	of Relea	se Source
Latitude 32.3	<u>3405953</u>		Longitude (NAD 83 in de		0455863 5 decimal places)
Site Name: H	lades Nortl	h Loop		Site	Type: Produced Water Line (production)
Date Release	Discovered	: 03/28/2022 at (6:30 am	API	‡ (if applicable)
Unit Letter	Section	Township	Range		County
D	1	T23S	R28E	Eddy	
Surface Owner		Federal Ti	Nature and	d Volum	e of Release specific justification for the volumes provided below)
Crude Oil		Volume Release			Volume Recovered (bbls)
Produced	Water	Volume Release	ed (bbls): 730		Volume Recovered (bbls): 300
		Is the concentration produced water	tion of dissolved c >10,000 mg/l?	chloride in th	e Xes No
Condensa	ite	Volume Release	ed (bbls)		Volume Recovered (bbls)
☐ Natural G	as	Volume Release	ed (Mcf)		Volume Recovered (Mcf)
Other (de	scribe)	Volume/Weight	Released (provide	e units)	Volume/Weight Recovered (provide units)
Cause of Rel	ease				-
					y of the poly pipe (not at a fused connection). The cause of find the root cause with our field inspections. We sent

the section of pipe with the rupture to be inspected by the distributor and the manufacturer of the pipe.

Volume Calculation is included on ATTACHMENT on page 3.

P	aa	0	7	a	F
1	uz	C	4	\boldsymbol{v}_{l}	

Incident ID	nAPP2209041864
District RP	
Facility ID	
Application ID	94798

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?
release as defined by 19.15.29.7(A) NMAC?	Calculated volume of the release was 730 bbls of produced water, which is greater than the 25 bbl
N. V. O. N.	threshold defining a major release.
⊠ Yes □ No	
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
NMOCD – Artesia Offic Haney with Altamira-US	was provided by Kurt Shipley on March 28, 2022 at 4:47pm by phone. Notification was made to the ce (575.703.3842). A recorded message was provided on the hotline voicemail (Laura Polk). Bryan S (on behalf of Novo Oil & Gas Northern Delaware, LLC.) submitted notification of a release (NOR) tem on March 31, 2022.
	Initial Response
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The responsible p	
The source of the rele	ease has been stopped.
☐ The impacted area ha	is been secured to protect human health and the environment.
Released materials ha	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and managed appropriately.
If all the actions described	d above have <u>not</u> been undertaken, explain why:
All actions above have	been completed.
Per 19.15.29.8 B. (4) NM	IAC the responsible party may commence remediation immediately after discovery of a release. If remediation
has begun, please attach	a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and
public health or the environr	required to report and/or file certain release notifications and perform corrective actions for releases which may endanger ment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have
	ate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
and/or regulations.	
Printed Name: Kurt A	A. Shipley Title: Chief Operating Officer
Signature:	Date: March 31, 2022
email: <u>kshipley@novoo</u>	og.com Telephone: <u>405-286-3916</u>
OCD O-1-	
OCD Only	Having an
Received by:	Harimon Date: <u>04/05/2022</u>

Received by OCD: 4/5/2022 11:44:13 AM
Form C-141 State of New Mexico
Page 3 Oil Conservation Division

	Page 3 of	f 4
Incident ID	nAPP2209041864	
District RP		
Facility ID		
Application ID	94798	

ATTACHMENT

Release Volume Calculation:

Water rate on the receiving end of the Hades North Loop was 18,000 bbls of produced water per day. This was recorded on the San Mateo SCADA water meter. During the time that the pipe was leaking, the receiving end SCADA meter was receiving a rate 11,000 bbls of produced water per day. The difference was 18,000 bbls minus 11,000 bbls, equal to 7,000 bbls of produced water per day.

This is our estimated rate for the amount of water lost from the pipeline during the failure while the pipeline was in operation. The SCADA data shows the meter receiving the reduced rate from 4:00am to 6:30am (2.5 hours).

This calculates to 7,000 bbls per day / 24 hours = 292 bbls x 2.5 hours = 730 bbls.

Released to Imaging: 4/5/2022 11:53:55 AM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 96057

CONDITIONS

Operator:	OGRID:
NOVO OIL & GAS NORTHERN DELAWARE, LLC	372920
1001 West Wilshire Blvd	Action Number:
Oklahoma City, OK 73116	96057
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created	By Condition	Condition Date
jharim	on None	4/5/2022