District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

\_)

Incident ID	nAPP2212446966
District RP	
Facility ID	
Application ID	

# **Release Notification**

#### **Responsible Party**

Responsible Party: ETC Texas Pipeline, Ltd.	OGRID: 371183	
Contact Name: Carolyn Blackaller	Contact Telephone: (432) 203-8920	
Contact email: Carolyn.blackaller@energytransfer.com	Incident # (assigned by OCD)	
Contact mailing address: 600 N. Marienfeld St., Suite 700, Midland, TX 79701		

## **Location of Release Source**

Latitude 32.4283568

*NAD 83 in decimal degrees to 5 decimal places)* 

Site Name: Cotton Draw Pipeline	Site Type: Pipeline
Date Release Discovered: 4/23/2022	API# (if applicable)

Unit Letter	Section	Township	Range	County
0	S35	T21S	R37E	Lea

Surface Owner: State Federal Tribal X Private (Name:\_\_\_\_\_

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Volume Released (bbls)	Volume Recovered (bbls)
Volume Released (bbls)	Volume Recovered (bbls)
Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Volume Released (bbls)	Volume Recovered (bbls)
Volume Released (Mcf): 203.9 mcf	Volume Recovered (Mcf): 0 mcf
Volume/Weight Released (provide units) 51.2 bbl	Volume/Weight Recovered (provide units) 0 bbl
	Volume Released (bbls)         Is the concentration of dissolved chloride in the produced water >10,000 mg/l?         Volume Released (bbls)         Volume Released (Mcf): 203.9 mcf

Cause of Release: The release was attributed to an unknown cause.

eceived by OCD: 5/4/2022 orm C-141	1:09:15 PM State of New Mexico	Incident ID	nAPP2212446966	Page 2 o
age 2	Oil Conservation Division	District RP	IIAI 1 22 12440900	
		Facility ID		
		Application ID		
Was this a major release as defined by 19.15.29.7(A) NMAC? XYes No	If YES, for what reason(s) does the responsible par An unauthorized release of a volume, excluding ga		?	
	otice given to the OCD? By whom? To whom? Whe MOCD District I & Jim Griswold via email on 4/25/2		nail, etc)?	

8

#### **Initial Response**

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 $\overline{\mathbf{X}}$  The source of the release has been stopped.

 $\overline{\mathbf{X}}$  The impacted area has been secured to protect human health and the environment.

X Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

X All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Carolyn Blackaller	Title: Sr. Environmental Specialist
Signature:	Date: <u>5/4/2022</u>
email: Carolyn.blackaller@energytransfer.com	Telephone: (432) 203-8920
OCD Only	
Received by: Jocelyn Harimon	Date: 05/04/2022

Received by OCD: 5/4/2022 1:09:15 PM Form C-141 State of New Mexico

Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

## Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)
Did this release impact groundwater or surface water?	🗌 Yes 🗌 No
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	🗌 Yes 🗌 No
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	🗌 Yes 🗌 No
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	🗌 Yes 🗌 No
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	🗌 Yes 🗌 No
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	🗌 Yes 🗌 No
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	🗌 Yes 🗌 No
Are the lateral extents of the release within 300 feet of a wetland?	🗌 Yes 🗌 No
Are the lateral extents of the release overlying a subsurface mine?	🗌 Yes 🗌 No
Are the lateral extents of the release overlying an unstable area such as karst geology?	🗌 Yes 🗌 No
Are the lateral extents of the release within a 100-year floodplain?	🗌 Yes 🗌 No
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?	🗌 Yes 🗌 No

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.

Characterization Rep	port Checklist: Ea	ch of the following	g items must be inclu	ded in the report.

Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.
Field data
Data table of soil contaminant concentration data
Depth to water determination
Determination of water sources and significant watercourses within 1/2-mile of the lateral extents of the release
Boring or excavation logs
Photographs including date and GIS information
Topographic/Aerial maps

Laboratory data including chain of custody

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Page 3

Received by OCD: 5/4/202 Form C-141	2 1:09:15 PM State of New Mexico	Incident ID	Page 4 of 8
Page 4	Oil Conservation Division	District RP	
5		Facility ID	
		Application ID	
regulations all operators are public health or the environ failed to adequately investig	prmation given above is true and complete to the best of my kn required to report and/or file certain release notifications and ment. The acceptance of a C-141 report by the OCD does not gate and remediate contamination that pose a threat to groundw of a C-141 report does not relieve the operator of responsibility	perform corrective actions for releases while relieve the operator of liability should their water, surface water, human health or the en	ch may endanger operations have wironment. In
Printed Name:			
Signature:	Date:		
email:	Telephone:	:	
OCD Only			
Received by:	Dat	te:	

**Received by OCD: 5/4/2022 1:09:15 PM** Form C-141 State of New Mexico

Oil Conservation Division

	Page 5 of	۶ <b>8</b>
Incident ID		
District RP		
Facility ID		
Application ID		

# **Remediation Plan**

Remediation Plan Checklist: Each of the following items must be in	ncluded in the plan.		
<ul> <li>Detailed description of proposed remediation technique</li> <li>Scaled sitemap with GPS coordinates showing delineation points</li> <li>Estimated volume of material to be remediated</li> <li>Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC</li> <li>Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required)</li> </ul>			
Deferral Requests Only: Each of the following items must be confin	med as part of any request for deferral of remediation.		
Contamination must be in areas immediately under or around produce deconstruction.			
Extents of contamination must be fully delineated.			
Contamination does not cause an imminent risk to human health,	the environment, or groundwater.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			
Printed Name:T	`itle:		
Signature:	Date:		
email:	Telephone:		
OCD Only			
Received by:Da	ite:		
Approved Approved with Attached Conditions of Approved	pproval Denied Deferral Approved		
Signature: D	ate:		

Page 5

Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Page 6 of 8

# Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

<u>Closure Report Attachment Checklist</u>: Each of the following items must be included in the closure report.

A scaled site and sampling diagram as described in 19.15.29.11 NMAC

Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)

Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)

Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Carolyn Blackaller Title: Sr. Environmental Specialist

Signature: \_\_\_\_\_ Date: 1/25/2021

Page 6

email: Carolyn.blackaller@energytransfer.com

Telephone: (432) 203-8920

**OCD Only** 

Received by:\_\_\_\_\_

Date:

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by:	Date:
Printed Name:	Title:

#### Received by OCD: 5/4/2022 1:09:15 PM

NAPP2212446966
----------------

Page 7 of 8	Page	7	of	° <b>8</b>
-------------	------	---	----	------------

Liquid Spill				
	Enter Numbers Only		,	
Length of Spill Area (ft):	230.0	Est. Liquid Vol. (bbls):	15.3764	19
Width of Spill Area (ft):	65.0	Porosity Factor (soil type):	Clay	
Depth of Spill Area (ft):	0.4	Vol. of Oil Released (bbls):	15.3764	19
% Oil in Liquid:	30.0	Vol. of Water Released (bbls):	35.8784	47
Amount Recovd. (bbls):	0.0	Impacted Soil Vol (ft3):	19.380	)
Gas Release Calc. (Leak, Relief VIv, etc.)				
Hole or Rip/Gouge?:	Hole	Spe	cific Gravity:	0.750
Length (in inches):		Pipel	line Diameter:	16.000
Width (in inches):		Equival	ent Diameter:	0.250
Diameter (in inches):	0.250	Release Rate	(MCF/Hour):	2.8
Pressure (psig):	40.0			
Temperature (Deg F):	67.0	Gas Rele	ease (Mcf):	203.9

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

	OGRID:
ETC Texas Pipeline, Ltd.	371183
8111 Westchester Drive Dallas, TX 75225	Action Number:
	104077
	Action Type:
	[C-141] Release Corrective Action (C-141)
CONDITIONS	

#### Created By Condition Condition Date 5/4/2022 jharimon None

CONDITIONS

Page 8 of 8

.

Action 104077