

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Conoco Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786
Facility Name: Middle Mesa 1 SWD	Facility Type: SWD

Surface Owner BLM	Mineral Owner BLM	API No. 3004527004
--------------------------	--------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter L	Section 25	Township 32N	Range 07W	Feet from the 1555'	North/South Line South	Feet from the 1210'	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	-------------------------------	-------------------------------	---------------------------

Latitude **36.94806** Longitude **-107.52242**

NATURE OF RELEASE

Type of Release Lube Oil	Volume of Release 6.41 BBL	Volume Recovered 6.41 BBL
Source of Release Day Oil Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 12/10/13 @ 10:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. RCVD DEC 27 '13	

If a Watercourse was Impacted, Describe Fully.*
N/A

**OIL CONS. DIV.
DIST. 3**



Describe Cause of Problem and Remedial Action Taken.*

Ball valve at end of hose was cracked open and resting on day tank stand, causing a release of approximately 6.41 BBL of lube oil into the secondary containment (metal trough). Approximately .25 gals spilled over onto the snow covered ground. Contaminated snow was scooped up - no soil was contaminated. Oil in secondary containment was pulled.

Describe Area Affected and Cleanup Action Taken.*

No further remediation required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 6/18/2014	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/20/13 Phone: (505) 326-9786			

* Attach Additional Sheets If Necessary

njk 14169 34944