District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Responsible Party EOG Resources

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2213134092
District RP	
Facility ID	
Application ID	

## **Release Notification**

## **Responsible Party**

**OGRID 7377** 

Contact Name James Kennedy		Contact Telephone 432-258-4346					
Contact email james_kennedy@eogresources.com		Incident # (assigned by OCD) nAPP2213134092					
Contact mailing address 5509 Champions Drive Midland, TX 79706							
			T 4	c D	) -1 C		
			Locatio	n oi k	Release So	ource	
Latitude 32.0	9507					-104.08231	
			(NAD 83 in c	decimal de	egrees to 5 decin	nal places)	
Site Name B	onbon BNN	State Com #1H			Site Type Well site/tank battery		
Date Release	Discovered	05/03/2022			API# (if app	olicable) 30-015-3	6913
Unit Letter	Section	Township	Range		Cour	ats :	
M	27	25S	28E	Edd		ity	
111	2,	200	202	Date	<i>,</i>		
Surface Owner	r: X State	☐ Federal ☐ Ti	ribal 🗌 Private	(Name:			)
			<b>N</b> T 4	1 8 7		D 1	
			Nature an	ia vo	lume of 1	Release	
				ch calcula	tions or specific		e volumes provided below)
Crude Oil	[	Volume Release	ed (bbls)			Volume Rec	overed (bbls)
☐ Produced Water Volume Released (bbls) 5			Volume Rec	overed (bbls) 2			
Is the concentration of dissolved chloride produced water >10,000 mg/l?		e in the	☐ Yes 🖾 ì	No			
Condensa	Condensate   Volume Released (bbls)			Volume Rec	overed (bbls)		
☐ Natural Gas Volume Released (Mcf)			Volume Rec	overed (Mcf)			
Other (describe) Volume/Weight Released (provide units		)	Volume/Wei	ght Recovered (provide units)			
Leak on water transfer line, found after transfer pump was brought back online.							

- 73				0
v	age	, 7	0	t i
-	u z c	- 4	v	•

Incident ID	NAPP2213134092
District RP	10.0122101002
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?
release as defined by 19.15.29.7(A) NMAC?	
` /	
☐ Yes ⊠ No	
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
,	
	Initial Response
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.
	s been secured to protect human health and the environment.
	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and managed appropriately.
If all the actions described	d above have not been undertaken, explain why:
D 1015200 D (4) 111	
has begun, please attach	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and
	required to report and/or file certain release notifications and perform corrective actions for releases which may endanger nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have
failed to adequately investigated	ate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
and/or regulations.	a C-141 report does not reneve the operator of responsionity for comphance with any other federal, state, or local laws
Printed Name: _James F.	Kennedy Title:Env Specialist
Signature:	Date: _05/11/2022
email:james_kennedy	v@eogresources.com         Telephone:        432-258-4346
OCD Only	
Received by: <u>Jocelyn I</u>	Harimon Date: <u>05/11/2022</u>

Received by OCD: 5/11/2022 10:25:59 AM
Form C-141 State of New Mexico
Page 3 Oil Conservation Division

	I uge 5 of
Incident ID	
District RP	
Facility ID	
Application ID	

## **Site Assessment/Characterization**

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)			
Did this release impact groundwater or surface water?	☐ Yes ☐ No			
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No			
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No			
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No			
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No			
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No			
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No			
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No			
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No			
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No			
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No			
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?	☐ Yes ☐ No			
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.				
Characterization Report Checklist: Each of the following items must be included in the report.				
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.  Field data  Data table of soil contaminant concentration data  Depth to water determination  Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release  Boring or excavation logs  Photographs including date and GIS information  Topographic/Aerial maps  Laboratory data including chain of custody				

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 5/11/2022 10:25:59 AM
Form C-141 State of New Mexico
Page 4 Oil Conservation Division

	Page 4 of
Incident ID	
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			
Printed Name:	Title:		
Signature:	Date:		
email:	Telephone:		
OCD Only			
Received by:	Date:		

Received by OCD: 5/11/2022 10:25:59 AM
Form C-141 State of New Mexico
Page 5 Oil Conservation Division

	Page 5 of	f 7
Incident ID		
District RP		
Facility ID		
Application ID		

# **Remediation Plan**

Remediation Plan Checklist: Each of the following items must b	e included in the plan.	
<ul> <li>□ Detailed description of proposed remediation technique</li> <li>□ Scaled sitemap with GPS coordinates showing delineation points</li> <li>□ Estimated volume of material to be remediated</li> <li>□ Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC</li> <li>□ Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required)</li> </ul>		
<u>Deferral Requests Only</u> : Each of the following items must be con	nfirmed as part of any request for deferral of remediation.	
Contamination must be in areas immediately under or around predeconstruction.	roduction equipment where remediation could cause a major facility	
Extents of contamination must be fully delineated.		
Contamination does not cause an imminent risk to human health	n, the environment, or groundwater.	
	e and remediate contamination that pose a threat to groundwater, acceptance of a C-141 report does not relieve the operator of	
Printed Name:	Title:	
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	
☐ Approved ☐ Approved with Attached Conditions of	Approval	
Signature:	Date:	

Received by OCD: 5/11/2022 10:25:59 AM Form C-141 State of New Mexico
Page 6 Oil Conservation Division

	Page 6 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

A scaled site and sampling diagram as described in 19.15.29.11 NMAC			
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)			
☐ Laboratory analyses of final sampling (Note: appropriate ODC	C District office must be notified 2 days prior to final sampling)		
Description of remediation activities			
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.  Printed Name:  Title:  Title:			
Signature:	Date:		
email:	Telephone:		
OCD Only			
Received by:	Date:		
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.			
Closure Approved by:	Date:		
Printed Name:	Title:		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 105961

### **CONDITIONS**

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	105961
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By	Condition	Condition Date
jharimon	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141	5/11/2022