District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2216142798
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible	Party COC	· Danas II			OGRID 73	77	
		Resources, I	nc				710 1171
Contact Name Amber Griffin Contact email amber_griffin@eogresources.com					elephone 575-7	748-1471	
Contact ema	iil amber_	griffin@eogre	sources.com			nAPP2216142798	
Contact mailing address 104 S. 4th Street, Artesia, NM 8			8210				
			Location	of R	telease So	ource	
Latitude 36	.0294685				Longitude :	-107.343879	7
(NAD 83 in decimal degrees to 5 decimal places)							
Site Name Bois D Arc Divide 22 #002				Site Type V	Vellhead		
Date Release Discovered 6/9/2022				licable) 30-043	3-20082		
0/9/2022				30-0-0	F-20002		
Unit Letter	Section	Township	Range	County]	
Р	22	21N	05W	San	doval		
Surface Owne	er: State	Federal T	ribal Private (I	Name:)
			Nature and	d Vo	lume of I	Release	
	Materia	l(s) Released (Select a	l that apply and attach	calculat	ions or specific		e volumes provided below)
Crude Oi	1		d (bbls) Unknov			Volume Reco	vered (bbls)
☑ Produced			vn		Volume Reco	vered (bbls)	
	Is the concentration of dissolved chlorid produced water >10,000 mg/l?		hloride	e in the	☑ Yes ☐ N	Го	
Condens	ate	Volume Release	d (bbls)			Volume Reco	vered (bbls)
Natural C	Gas	Volume Release	d (Mcf)			Volume Reco	vered (Mcf)
Other (de	escribe)	Volume/Weight	Released (provide	e units)	Volume/Weig	ght Recovered (provide units)
Cause of Release Historical impacts were discovered during annual bradenhead testing. The environmental consultant contracted to investigate the area determined on 6/9/2022, based on the impacted area footprint, that the release more than likely breached the reportable volume threshold.							

Page 2 of 7

Incident ID	NAPP2216142798
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the respo	nsible party consider this a major release?	
☐ Yes ☑ No			
If YES, was immediate n	otice given to the OCD? By whom? To w	nom? When and by what means (phone, email, etc)?	
	Initial R	esponse	
The responsible	party must undertake the following actions immediate	ly unless they could create a safety hazard that would result in injury	
☐ The source of the rela	ease has been stopped.		
☐ The impacted area ha	as been secured to protect human health and	the environment.	
Released materials ha	Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.		
	ecoverable materials have been removed an		
If all the actions describe	d above have <u>not</u> been undertaken, explain	why:	
has begun, please attach	a narrative of actions to date. If remedial	emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred blease attach all information needed for closure evaluation.	
regulations all operators are public health or the environi failed to adequately investig	required to report and/or file certain release not ment. The acceptance of a C-141 report by the G gate and remediate contamination that pose a through	best of my knowledge and understand that pursuant to OCD rules and fications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws	
Printed Name: Amber	Griffin	Title: Rep Safety & Environmental Sr	
Signature: Amber	Griffin	Date: 6/10/2022	
email: amber_griffine	@eogresources.com	Telephone: 575-748-1471	
OCD Only			
Received by: Jocely	n Harimon	Date: 06/13/2022	

Received by OCD: 6/12/2022 3:26:49 PM Form C-141 State of New Mexico Page 3 Oil Conservation Division

	Page 3 of	7
Incident ID		
District RP		
Facility ID		
Application ID		

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)	
Did this release impact groundwater or surface water?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No	
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No	
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No	
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No	
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No	
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No	
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No	
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ☐ No	
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.		
Characterization Report Checklist: Each of the following items must be included in the report.		
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody		

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 6/12/2022 3:26:49 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 of	f 7
Incident ID		
District RP		
Facility ID		
Application ID		

I hereby certify that the information given above is true and complete to the regulations all operators are required to report and/or file certain release not public health or the environment. The acceptance of a C-141 report by the failed to adequately investigate and remediate contamination that pose a thruaddition, OCD acceptance of a C-141 report does not relieve the operator of and/or regulations.	ifications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have eat to groundwater, surface water, human health or the environment. In
Printed Name:	
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:

Received by OCD: 6/12/2022 3:26:49 PM Form C-141 State of New Mexico Page 5 Oil Conservation Division

	I uge 5 of
Incident ID	
District RP	
Facility ID	
Application ID	

Remediation Plan

Remediation Plan Checklist: Each of the following items must b	e included in the plan
Detailed description of proposed remediation technique Scaled sitemap with GPS coordinates showing delineation poin Estimated volume of material to be remediated Closure criteria is to Table 1 specifications subject to 19.15.29. Proposed schedule for remediation (note if remediation plan tin	ts 12(C)(4) NMAC
<u>Deferral Requests Only</u> : Each of the following items must be con	ifirmed as part of any request for deferral of remediation.
Contamination must be in areas immediately under or around p deconstruction.	roduction equipment where remediation could cause a major facility
Extents of contamination must be fully delineated.	
Contamination does not cause an imminent risk to human healt	n, the environment, or groundwater.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name:	Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:
Approved	Approval
Signature:	Date:

Received by OCD: 6/12/2022 3:26:49 PM Form C-141 State of New Mexico Page 6 Oil Conservation Division

	Page 6 of 7
Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

☐ A scaled site and sampling diagram as described in 19.15.29.1	11 NMAC	
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)		
☐ Description of remediation activities		
and regulations all operators are required to report and/or file certai may endanger public health or the environment. The acceptance of	nations. The responsible party acknowledges they must substantially anditions that existed prior to the release or their final land use in OCD when reclamation and re-vegetation are complete.	
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.		
remediate contamination that poses a threat to groundwater, surface	water, human health, or the environment nor does not relieve the responsible	
remediate contamination that poses a threat to groundwater, surface	water, human health, or the environment nor does not relieve the responsible or regulations.	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 116025

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	116025
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Create	ed By	Condition	Condition Date
jharii	mon	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-	6/13/2022