

Devon Energy Production Company, LP

Request for Incident Closure

August 24th, 2020

Uncle Sam 13 C Federal #1 API – 30-025-30997 <u>nDEV1242 NO-RP</u>

Description of Original Incident:

On January 8th of 1991, there was an overflow of the production tank. The release was approximately 70 bbls in volume and consisted of crude oil. Approximately 30 bbls of fluid were recovered from the unlined, earthen secondary containment. The location of this site is, A-13-18S-32E; <u>32.752800, -103.713400</u>.

Immediate Actions Taken:

My apologies but no other information about this specific incident could be found. The well was plugged and abandoned on 8/6/2009. Reclamation activities took place between August and October of 2012. All activities were completed by 10/24/2012.

Our current assessment of this incident was performed on August 24th, 2020. With the information and pictures provided, we would like to respectfully request that the incident be closed out.

Thank you so much for your time. If there is anything more that you would like us to do with this incident in order to close it out, please let us know and we'll be happy to make the necessary arrangements.

Have a wonderful day,


Tom Bynum

Гот Вулит

EHS Consultant/Contractor

tom.bynum@dvn.com


580-748-1613



.



Devon Energy Production Company, LP



Page 6

Oil Conservation Division

Incident ID	NDEV1242	
District RP		
Facility ID		
Application ID		

Page 4 of 13

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

<u>Closure Report Attachment Checklist</u>: Each of the following items must be included in the closure report.

X A scaled site and sampling diagram as described in 19.15.29.11 NMAC

X Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)

X Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)

X Description of remediation activities


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Tom Bynum	Title: EHS Consultant
Signature: Tom Bynum	Date: <u>8/24/2020</u>
Signature: <u>Tom Bynum</u> email: tom.bynum@dvn.com	Telephone: 575-748-3371
OCD Only	
Received by:	Date:
	y of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible /or regulations.
Closure Approved by: Bradford Billings	Date:
Printed Name:	Title:

Daga	5	-	12
Page	3	IJ	13

•

			ochiques o	CD					
Form 3160-5	UNITED STATE	ES		FORM APPROVED OMB No 1004-0137					
	PARTMENT OF THE		OCT 232	Exr	Expires' July 31, 2010				
BUI	REAU OF LAND MAN	AGEMENT		MM-81958					
	NOTICES AND REPO form for proposals t				6 If Indian, Allottee or Tribe Name				
abandoned well.	Use Form 3160-3 (A	PD) for such pr	oposals.						
	IT IN TRIPLICATE – Other	instructions on page	2.	7. If Unit of CA/Agreer	nent, Name and/or No.				
1. Type of Well				8. Well Name and No.	/				
✓ Oil Well Gas	Well Other	······		Uncle Sam 13C Fede	eral #1				
2 Name of Operator Devon Energy Production Co LP	······································			9. API Well No 30-025-30997					
3a. Address PO BOX 250, Artesia, NM 88211		3b. Phone No. (includ	le area code)	10. Field and Pool or E					
4. Location of Well (Footage, Sec., T	P. M. or Super Description	575-748-0184		West Corbin Delawar					
4. Elocation of wen (<i>Poblage</i> , <i>Sec</i> , <i>1</i> 660' FNL & 660" FEL, Sec 13, T18S, R32E, U				LEA					
12. CHE	CK THE APPROPRIATE BO	DX(ES) TO INDICATE	E NATURE OF NO	TICE, REPORT OR OTHE	R DATA				
TYPE OF SUBMISSION			TYPE OF A	CTION					
✓ Notice of Intent	Acidize	Deepen	P	roduction (Start/Resume)	Water Shut-Off				
V Nouce of Intent	Alter Casing	Fracture Tre	at 🗹 R	eclamation	Well Integrity				
Subsequent Report	Casing Repair	New Constru	action R	ecomplete	Other				
	Change Plans	Plug and Ab	andon 🔲 T	emporarily Abandon	Location				
Final Abandonment Notice	Convert to Injection	Plug Back	V	/ater Disposal	Reclamation				
testing has been completed. Fina determined that the site is ready f 1. Devon Energy has contracted T 2. On 8/6/2012 Talon/LPE mobilize collected from the surface of the lo The results for the soil samples and 3. The chloride impacted soil at th and tested on the location using th 4. The caliche will be removed fro onto the drillig pit area. 5. New soil will be transported in f pit area. 6 The drilling pit area and location 7. The location and lease road will the location and lease road will be 2. On 8/6/2012 Talon/LPE mobilize 14. I hereby certify that the foregoing is	or final inspection.) alon/LPE to do reclamation ad personnel to the site to of cation.The soil samples we a attached. A site plan is a e sample located S-7 will be e field tiration method for c m the lease road and well l rom a local borrow pit or a will be contoured to match then be cut, ripped, cross- seeded using the recomm	n services at the Unc earry out soil sampling re sent to Cardinal L lso attached. e excavated and tran hlorides. ocation. The remove downsized location. the surrounding terri- ripped and windrows lended BLM seed mit S 7 S - 2 3	le Sam 13C Fede g activities for the aboratories for an asported to CRI fo ad caliche will be to A minimum of 2-fo fine d acai ain. s will be installed of kture for the area.	rai No. 1, a plug and aba construction of a work pl alysis of total Chlorides of r disposal. Comfirmation used to repair lease road tot of new soil will be place y_{c} f f f f f f f f on the location to help pre- stant T_{c} f f f f f f f f	ndoned location. an, Grab soil samples were via Method SM4500CI-B, a samples will be collected is in the area or placed cod over the top of the drilling				
Merle Lewis		Title	Production For	eman					
Signature Muled)- 7	Date	9/14/2012						
	THIS SPACE	FOR FEDERAL	OR STATE C	OFFICE USE					
	title to those rights in the cubic site con	a crime for any person k	Title SE Office LF nowingly and willfu	D	Date JO·21-12 t or agency of the United States any false,				
(Instructions on page 2)					ULI 2 4. 2012				





PHONE (575) 393-2326 ° 101 E. MARLAND ° HOBBS, NM 88240

August 11, 2012

MIKE STUBBLEFIELD TALON LPE 408 W. TEXAS AVE. ARTESIA, NM 88210

RE: UNCLE SAM 13C FED. NO. 1

Enclosed are the results of analyses for samples received by the laboratory on 08/08/12 14:47.

Cardinal Laboratories is accredited through Texas NELAP under certificate number T104704398-11-3. Accreditation applies to drinking water, non-potable water and solid and chemical materials. All accredited analytes are denoted by an asterisk (*). For a complete list of accredited analytes and matrices visit the TCEQ website at www.tceg.texas.gov/field/ga/lab_accred_certif.html.

Cardinal Laboratories is accreditated through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2	Haloacetic Acids (HAA-5)
Method EPA 524.2	Total Trihalomethanes (TTHM)
Method EPA 524.4	Regulated VOCs (V1, V2, V3)

Accreditation applies to public drinking water matrices.

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Celeg D Keine

Celey D. Keene Lab Director/Quality Manager

Page 1 of 5



Analytical Results For:

TALON LPE MIKE STUBBLEFIELD 408 W. TEXAS AVE. ARTESIA NM, 88210 Fax To: (575) 745-8905

Received:	08/08/2012	Sampling Date:	08/06/2012
Reported:	08/11/2012	Sampling Type:	Soil
Project Name:	UNCLE SAM 13C FED. NO. 1	Sampling Condition:	** (See Notes)
Project Number:	700794.043.01	Sample Received By:	Jodi Henson
Project Location:	SEC.13 - T18S - R32E		

Sample ID: S - 1 0' (H201839-01)

Chloride, SM4500Cl-B	mg,	/kg	Analyze	d By: HM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	16.0	16.0	08/09/2012	ND	384	96.0	400	0.00	

Sample ID: S - 2 0' (H201839-02)

Chloride, SM4500Cl-B	SM4500CI-B mg/kg			Analyzed By: HM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	<16.0	16.0	08/09/2012	ND	416	104	400	0.00	

Sample ID: S - 3 0' (H201839-03)

Chloride, SM4500Cl-B	mg	ng/kg Analyzed By: HM							
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	<16.0	16.0	08/09/2012	ND	416	104	400	0.00	

Sample ID: S - 4 0' (H201839-04)

Chloride, SM4500Cl-B	mg	/kg	Analyze	d By: HM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	16.0	16.0	08/09/2012	ND	416	104	400	0.00	

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE Liability and Damages Cardnal's liability and dient's exclusive remedy for any daim ansing, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed valued unless made in writing and received by Cardinal's bubidity and dient's exclusive remedy for any daim ansing, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed valued unless, made in writing and received by Cardinal's within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, which with subsidianes, affiliates or successors ansing out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claims based upon any of the above stated reasons or otherways. Results related not the samples dentified dower. This report shall not be reported except in full with written approval of Cardinal based upon any of the above stated reasons or otherways.

Celey D. Kune

Celey D. Keene, Lab Director/Quality Manager

Page 2 of 5



Analytical Results For:

TALON LPE MIKE STUBBLEFIELD 408 W. TEXAS AVE. ARTESIA NM, 88210 Fax To: (575) 745-8905

Received:	08/08/2012	Sampling Date:	08/06/2012
Reported:	08/11/2012	Sampling Type:	Soil
Project Name:	UNCLE SAM 13C FED. NO. 1	Sampling Condition:	** (See Notes)
Project Number:	700794.043.01	Sample Received By:	Jodi Henson
Project Location:	SEC.13 - T18S - R32E		

Sample ID: S - 5 0' (H201839-05)

Chloride, SM4500Cl-B	mg	/kg	Analyze	d By: HM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	368	16.0	08/09/2012	ND	416	104	400	0.00	

Sample ID: S - 6 0' (H201839-06)

Chloride, SM4500Cl-B	mg/kg Analyzed		Ву: НМ						
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	128	16.0	08/09/2012	ND	416	104	400	0.00	

Sample ID: S - 7 0' (H201839-07)

Chloride, SM4500Cl-B mg/kg		/kg	Analyzed By: HM						·	
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier	
Chloride	5440	16.0	08/09/2012	ND	416	104	400	0.00		

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE Lobility and Damages Cardinal's lability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waved unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be lable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidianes, affiliates or successors ansing out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratones.

Celey D. Kune

Celey D. Keene, Lab Director/Quality Manager



PHONE (575) 393-2326 ° 101 E. MARLAND ° HOBBS, NM 88240

Notes and Definitions

ND	Analyte NOT DETECTED at or above the reporting limit
RPD	Relative Percent Difference
**	Samples not received at proper temperature of 6°C or below.
***	Insufficient time to reach temperature.
-	Chloride by SM4500Cl-B does not require samples be received at or below $6^{\circ}C$
	Samples reported on an as received basis (wet) unless otherwise noted on report

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE Liability and Damages Cardinal's liability and client's exclusive remedy for any claim ansung, whether based in contract or tort, shall be limited to the amount paul by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waved unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be lable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidianes, affiliates or successors arising out of or related to the performance of the services hareunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise, Results relate only to the semples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratones

Celey D. Kune

Celey D. Keene, Lab Director/Quality Manager

Page 4 of 5

Page 11 of 13

CARDINAL

101 East Marland, Hobbs, NM 88240

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

(575) 393-2326 FAX (575) 393-2476 Company Name: BILL TO Tabon/LPE ANALYSIS REQUEST ŢĘ, Project Manager: mike Stublefield P.O. #: 408 Weit Terai Aue. Company: Talon /LPE Address: Arteria City: State: NM Zip: 82210 Attn: Phone #: 575.441.2254 Fax #: Address: 100 794.043.01 Project Owner: Down Energy Corp. Project #: City: Project Name: Uncle Sam 13 C Federal No. 1 State: Zip: Project Location: sec. 13 - TIBS - R 32 E Phone #: maer Shelly il Sampler Name: Fax #: Total chlorides FOR LAB USE ONLY MATRIX PRESERV SAMPLING (G)RAB OR (C)OMP GROUNDWATER WASTEWATER SOIL CONTAINERS OTHER : ACID/BASE ICE / COOL Lab I.D. Sample I.D. OIL SLUDGE OTHER H20183] DATE TIME 8/6/012 4:359 G 5.10 2 5.2 0 4:408 5 3 5.30 ራ 4:458 4 5.4 0 G 4-50P 5 5.5 0 4:55 P G 6 5.60 5:00 P 6 5.2 0 <u>c</u> 5:05P

PLEASE NOTE: Lobality and Damages Cardinals hability and clients exclusive temical for any dama biary dama biary attention based on contract or tort, shall be landed to the anount paid by the client for the analyses. All claims including those for negligence and any other cause whatsoever shall be demed wawed unless made in whiting and received by Cardinal within 30 days after completion of the applicable service. In on event shall Cardinal be hable for incidential or consequential diamages, including without limitation, business interruptions, loss of use of profils incurred by client, its subsidialities,

	e of services hereinder by Cardinal, regardless of whether such claim is based upon any of the above stated	
Relinguished By:	Date: Received By:	Phone Result: Yes No Add' Phone #:
-	8/8/zoiz	Fax Result: Ves No Add'I Fax #:
miselshillfield	Time: 47 LOCU MUNDON	REMARKS:
Relinquished By:	Date: Received By:	
	Time:	
Delivered By: (Circle One)	Sample Condition CHECKED BY:	-
Sampler - UPS - Bus - Other:	$\begin{array}{c c} & \text{Cool} & \text{Intact} & \text{(InitIals)} \\ & & & \text{Yes} & \text{Yes} \\ & & & \text{Vol} & \text{No} \end{array}$	

† Cardinal cannot accept verbal changes. Please fax written changes to 505,393-2476'

Page 5 of 5

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

COMMENTS

Operator:	OGRID:
Pima Environmental Services, LLC	329999
5614 N Lovington Hwy	Action Number:
Hobbs, NM 88240	9869
	Action Type:
	[C-141] Release Corrective Action (C-141)
	-

COMMENTS

Created By	Comment	Comment Date			
jharimon	Closure approved on 10/01/2020 by Bradford Billings	7/28/2022			

COMMENTS

Page 12 of 13

Action 9869

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
Pima Environmental Services, LLC	329999
5614 N Lovington Hwy	Action Number:
Hobbs, NM 88240	9869
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By		Condition Date
jharimon	None	7/28/2022

Page 13 of 13

Action 9869